

Douglas County Surveyor's Record of  
Government Corners Renewed

28 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97301

79

$\frac{1}{4}$  Corner to Sec. 31, T28-5W. & Sec. 36, T28-6W.  
Found - Orig. 8", now 20" W.Oak S.54°W. 19.8 ft. Weopened & find  
good scribe marks.

Old Stump Hole & Rotted Stump Section for N.E. BT.

Note - N. S. Fence 15 ft. West of Corner.

Set Brass Cap Mkd: County Surveyor's Office, 1961  $\frac{1}{4}$  S36/S31 T28S  
R6W R5W

New BT's: 13" B.Oak bears S.42°E. 11.0 ft. scribed  $\frac{1}{4}$  S31 CS BT.  
9" B.Oak bears S.34°W. 11.2 ft. scribed  $\frac{1}{4}$  S36 CS BT.

80

$\frac{1}{4}$  Cor. to Sec. 34, T28-5W. & Sec. 3, T29-5W.  
Found -  $\frac{3}{4}$ " I. P. at Corner - 18", now 36" W.Oak S.36°W. 146.4 ft.,  
not 446.4., we open & find good scribing.

Orig. S.W. BT., center rotted.

Note - Corner is in field. I set Wit. Cor. 10' South & under E.W. Fence.

Set Brass Cap at Wit. Cor. Mkd: County Surveyor's Office, 1961 W.C. 10' N.  
to  $\frac{1}{4}$  S34 T28S R5W  
S 3 T29S

New BT's: 7" R.Fir bears S.48°W. 137.0 ft. scribed  $\frac{1}{4}$  S 3 CS BT W.C.  
14" W.Oak bears N.88°W. 236.3 ft. scribed W.C.  $\frac{1}{4}$  S34 CS BT.

81

Sec. Cor. Secs. 32-33, T28-5W. & Secs. 5-4, T29-5W.  
Found - All 4 BT's as recorded by Epp. 1926. See Book 1, Page 104, REN #8  
Distance to N.E. BT. should be 120.0 ft. and dist. to S.E.  
BT. should be 148.8 ft. All BT's show good scars. Do not open.

Note - Corner is under East West Fence.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961  $\frac{1}{4}$  S32/S33 T28S R5W  
S 5 S 4 T29S

No new Bearing Trees scribed.

$\frac{1}{4}$  Corner to Sections 32 and 33.  
Found - Mound of Rocks & burned stake REN #38 Also a 6"x2"xl8" Stone 4"  
above gr. - Also Both BT's as recorded. Weopen N.W. BT. &  
find good scribing.

Set Brass Cap Mkd: County Surveyor's Office, 1961  $\frac{1}{4}$  S32/S33 T28S R5W.

New BT's: 16" W.Oak bears S.44°E. 44.5 ft. scribed  $\frac{1}{4}$  S33 CS BT.  
14" W.Oak bears N.40°W. 46.0 ft. scribed  $\frac{1}{4}$  S32 CS BT.

Note - This side of Mt. in 1961 Fire area. All trees may die near  $\frac{1}{4}$  Corner.

82

Sec. Cor. Secs. 33-34, T28-5W. & Secs. 4-3, T29-5W.  
Found -  $\frac{3}{4}$ " I. P. at Corner. - 16", now 24" Fir Snag N.38°E. 6.7 ft.,  
shows good scars. - 16", now 28" Fir N.40°W. 41.1 ft., shows  
good scars. - 18", now 24" Fir Snag S.28 $\frac{1}{2}$ °E. 20.0 ft., shows  
scars. - S.W. BT. now fence corner & may die. (in 1961 fire area)

Set Brass Cap Mkd: County Surveyor's Office, 1961  $\frac{1}{4}$  S33/S34 T28S R5W  
S 4 S 3 T29S

New BT's: 12" R.Fir bears S.78°W. 39.2 ft. scribed S 4 T29S R5W CS BT.  
16" R.Fir bears N. 8°E. 57.3 ft. scribed S34 T28S R5W CS BT.  
No live trees near to S.E.

83

Renewed Corner  $\frac{1}{4}$  S36/S37 T28 Found - Orig. 22", now 28" W.Oak N.84°E.  
R6W R5W 84.0 ft., not 90.4 ft. We open &  
find good scribing. - Orig. 24", now 30" B.Oak Snag, center rotted, no  
scribing, S.45°W. 85.8 ft. - Orig. N.W. BT. standing, shows good scars.  
Orig. S.E. BT. not found. - Note - We find 1" I.P. bears N.80°E. 18.8 ft.

Set Brass Cap Mkd: County Surveyor's Office, 1961 R6W  $\frac{1}{4}$  S36/S31 T28S  
S 1 S 6 R5W T29S

New BT's: 10" W.Oak bears N.83°W. 12.5' scribed S36 T28S R6W CS BT.  
12" W.Oak bears S.36°W. 15.7' scribed S 1 T29SR6W CS BT.  
8" W.Oak bears S.64°E. 21.0' scribed S 6 T29S R5W CS BT.  
11" W.Oak bears N.30°E. 6.0 ft. scribed S31 T28S R5W CS BT.

Fd. Brass Cap and all bearing trees o.k. 10/11/73

Sec. Cor. Secs. 31-32, T28-5W. & Secs. 5-6, T29-5W.  
Found -  $\frac{1}{4}$ " I. P. at Corner & N.E. & N.W. BT's, as recorded. S.W. BT. gone. REN #35  
New BT's: 10" Laurel bears S.44°E. 6.5 ft. scribed S 5 CS BT.  
No trees near to South West.

84

85

RE-RENEWED, SEE CORNER NO. #145

RE-RENEWED, SEE CORNER NO. #140

FD. 11/87  
M. 105-139-0-2  
D. 20/72

James W. Byron, Deputy County Surveyor  
Dale McFarland  
Jim Powell  
September - October 1961  
C. S. File No. 49/64