

Douglas County Surveyor's Record of
Government Corners Renewed

28

T. S.

6

R. W. W. M.

✓ 1/4 CORNER BETWEEN SECTIONS 23 and 26. 11
Renewed the corner from original B.T.'s. Oak dead. Set
4" x 4" x 40" Oak post. Marked new trees. **96**
A Fir 15" dia. bears S. 28° E., 3.7 ft.
A Fir 30" dia. bears N. 41° 45' E., 11.8 ft.

✓ 1/4 CORNER BETWEEN SECTION 27 and 28. 12
Original B.T. N. 7° E., standing and alive. Stub of Original
B.T. N. 80° W. standing but dead scribe marks visible distance
and direction check by using slope measure to tree N. 7° E.
Set 4" x 4" x 40" Oak Stake and erected mound of rock.

✓ 1/4 CORNER BETWEEN 28 and 33. 13
Renew corner from remains of old bearing trees which
are down but check for direction and distance. Set 30"
Iron Pipe also post from which **106**
A Laurel 40" dia. bears S. 89° W., 37.5 ft.
An Oak 10" dia. bears S. 38° E., 44.0 ft.

✓ 1/4 CORNER BETWEEN 33 and 34. 14
Renew Corner from original B.T.'s. Tree north alive,
other one dead. Both bearing scribe marks. Set an Iron
Pipe 2" x 24" and marked new tree.
A White Oak 24" dia. bears S. 65° 30' E., 91.0 ft.

✓ 1/4 CORNER SOUTH SIDE OF SECTION 34. 15
Renewed corner from original B.T. S. 47° E., which is alive
and standing. Scar had been chopped out but old blaze had
rotted no scribe marks visible. Found hole where tree had
stood N. 26° E., Remains of fire place of Robert Phipps
Cabin bears S. 59° W., Mark new tree N. 56° E., 1 ft. **104**
Set an Oak Post also an Iron Bolt 5/8" x 24".

✓ N.E. CORNER OF ROBT. PHIPPS CL. # 37 - 42 on TWP. LINE 16
Located corner 3.00 chains west of 1/4 corner on South Side
34. Set Oak post 4 x 4 x 40" also mound of rock and an Iron
Pipe. Marked new trees
A White Oak 12" dia. bears N. 18° E., 124.3 ft.
A White Oak 10" dia. bears S. 81° W., 64.2 ft.

~~✓ S.E. CORNER OF PHIPPS CL. 37 T. 28-29 S. R. 6 W. 17
Found a large Oak standing. Old scar had been chopped
out but no scribe marks were visible. Victor Phipps testifies
that his father pointed this tree out to him as the Original
B.T. Direction given in field notes was given as N. 30° W
but tree was blazed on East side. After running East and
South side of claim I established the corner by courses and
proportionate measurement from the other corners and the old
B.T. then bears N. 52° W., 94.5 ft. Marked a new tree
An Oak N. 7° 59' W., 75.6 ft.
Set an Oak post and 1" x 40" Iron rod.~~

WRONG TWP. & RANGE

SHOULD BE T 29-7 W.

SEE M 1-7918

✓ S.W. CORNER OF ROBT. PHIPPS CL. 37
Reestablished from stamps of two Laurels which correspond
to field notes but no scribe marks were visible as trees
were badly decayed. Found a fir stake marked S.S. badly
rotted. Set a 4" x 4" x 40" Oak Post and marked new trees
as follows
A Fir 36" dia. S. 69° 20' W., 39.8 ft.
A Fir 36" dia. S. 22° 30' E., 31.2 ft.

✓ 1/4 CORNER BETWEEN 31, T 28, R. 6 and 36 T. 28-7 19
Set Iron Bar for corner.
Fir 10" dia. bears N. 61° E., 45 ft.
Laurel 8" dia. bears S. 71° W., 17.5 ft.
Corner reset from 1 original B.T. **87**

Jesse W. Cole Deputy
January 1921
Witnesses
L. H. Smick
Glen Taylor

Vol. 1 Pg. 109

O. G. Stewart
Witnesses
J. Lewis
J. M. Lemb
Jan. 12, 1922