

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 6 R. W. W. M.

G. G. Stewart
wit.
C. C. Laurance
R. A. Hercher
Laurance
Dec. 19, 1922

Ben B. Irving
Deputy
Witness - Chas. Buxton
Sept. 11, 1922

W. H. Woods Dep.
wit.
W. S. Crear
Nov. 12, 1925
Sec. Surv. 3-21

Floyd Cole Deputy
wit.
C. F. Andrew
O. A. Parker
April 5, 1915

W. H. Woods
wit.
W. S. Crear
Nov. 8, 1925
Sec. Surv. 3-1

Vol. 3 Pg. 140A
C.S. 5/14

SEE Vol. 2 PAGE 202

- ✓ 1/4 CORNER BETWEEN 20 and 29. 20
 Reestablished from mound of rocks set by former surveyor and commonly accepted as correct. No B.T.s in evidence. Drove 1 1/2" Iron Pipe and marked
 14" Balm N.38°E., 210.5 ft.
 16" Balm N.62°E., 261.5 ft.
RENEWED, SEE CORNER NO. 43
- ✓ CORNER COMMON TO SECTIONS 17, 18, 19 and 20. 21
 No evidence of original corner. Ran line from 1/4 Corner common to sections 17 and 18 to corner common to Sections 19, 20, 29, and 30. Set 1" Iron Pipe on line at distance proportional to that shown in original notes. No trees available.
 Point on south edge of large rock outcrop N.44°37'W., 191.5 ft. High point on Rock outcrop S.84°30'E., 790ft. North end of gable on Wm. Buxtons Barn S.66°40'E., no other points available.
- ✓ CORNER COMMON TO SECTIONS 19, 20, 29 and 30. 22
 Renewed corner by placing 3/4" Iron Pipe from two original bearing trees standing and stump of another and rotten stump of fourth. Replaced two missing B.T.s as follows
 White Oak 10" dia. bears S.40°45'W. 134.6 ft.
 White Oak 10" dia. bears N.41°E., 29.1 ft.
 Original Standing B.T.s as follows
 White Oak 27" dia. bears S.27°E., 15.8 ft.
 White Oak 24" dia. bears N.33 1/2°W., 77.2 ft.
- ✓ 1/4 CORNER BETWEEN SECTION 34 and 35. 23
 Set stake from one original B.T.
 Old E. N. Y Oak 10" dia. S. 18° W. 75 lks.
 Marked Black Oak 10" dia. S. 10 lks. scribbled 1/4 Cor. C.S.
RENEWED, SEE CORNER NO. 105
- ~~CORNERS OF SECTIONS 33 and 34 and 3-4. 24
 Renew corner. Tree in section 34 standing, others down. Remark a Cedar 16 in. dia. N.51°15'W., 19 lks.
 Fir 18 in. dia. N.25°50'W., 55 lks.
 Maple 14 in. dia. S.75°45'E., 55 lks.~~
- ✓ 1/4 CORNER BETWEEN SECTIONS 34 and 35. 25
 No evidence of old witness trees. Marked
 A Maple 24" dia. bears S.74 1/2°W. 63 lks.
 A Maple 8" dia. bears S.49°E., 62 lks.
- ✓ CORNER BETWEEN 28 and 33. 26
 Marked new trees
 An Oak 12" dia. bears S.39°W. 35 lks.
 An Oak 18" dia. bears N.45°E. 122 lks.
S.B. T 22-4W
- ✓ CORNER SOUTH SIDE OF 33. 27
 Renew corner with Vine Maple stake from original trees, still standing. **SEE #51**
- ✓ CORNER BETWEEN SECTIONS 35 and 36. 28
 Set from old B.T. One tree rotting but identified, other B.T. down. Set Oak Stake from which
 Black Oak 12" dia. bears N.40°15'W. / Scribbled B.T. 99
 Black Oak 12" dia. bears N.45°45'E., 82 lks.
 Scribbled B.T. S. 36-C.S.
- ✓ INTERIOR L. CORNER OF D.L.C. No. 54. 29
 Corner set on 1/4 section line 42.80 chs. from 1/4 Corner between 34 and 35. Set 1" x 2" Iron Pipe from which
 N.W. Corner of house bears S.43°W., 55 lks.
 Apple tree 6" dia. bears N.15°W.,

W.P.O. N.G. TWP. RANGE?

APPARENTLY NOT AUSTRIAN SEE CORNER No. 13 + 1/2