

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

*File
M 112-12*

North Line of T28S R6W.
Renew South $\frac{1}{4}$ Corner Section 31, T27S R6W.
Found - Orig. 24", now 48" B.Oak N.71 $\frac{1}{2}$ °W. 137.9 ft. We open
& find good scribe marks "S".
Orig. 16", now down 40" Oak, N.43°E. 510.2 ft.
Also find 1" Iron Pipe at Corner. E.W. Fence 15' South
Brass Cap Not Set.
New BT's: 6" B.O. bears N.29°W. 15.0 ft. scribed $\frac{1}{4}$ S31 CS BT.
8" W.O. bears N.26°E. 10.7 ft. scribed $\frac{1}{4}$ S31 CS BT.

84

James W.
Byron
January
1961
C.S. File
No. 49/50

North $\frac{1}{4}$ Corner Section 1.
Found - $\frac{3}{4}$ " Iron Pipe at Corner & now 12" W.Oak S.67°W. 20.0 ft. ^{Ren #38}
shows good scribing "P S.1 S C".
We scribe New BT: 20" W.Oak bears N.45°E. 65.2 ft. scribed 137
N $\frac{1}{4}$ S1 CS BT.

85

James W.
Byron
Jan. 1961
C.S. File
#49/79

$\frac{1}{4}$ Corner Sec. 6, T28-6W. & Sec. 1, T28-7W.
Found - Both Orig. BT's. Each checks record for bearing
& distance. We open N.E. BT. & find good scribing "S".
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S1/S6 T28 S County Surveyor's
R7W R6W Office, 1961
NEW BT: 8" B.Oak bears S.59°E. 3.8 ft. scribed $\frac{1}{4}$ S 6 CS BT.

86

J. Byron
March, 1961
C.S. 49/50

$\frac{1}{4}$ Section Corner to Sec. 31, T28-6W. & Sec. 36, T28-7W.
Found - 5/8" Bolt at Corner. 10", now 16" Fir Snag N.6 $\frac{1}{2}$ °E. 45.0 ft.
We open & find good scribing "S". ^{REN #19}
8", now 12" Down Laurel S.71°W. 17.5 ft.
No trace of Orig. BT's. found.
Set - Brass Cap at Corner and alongside 5/8" Bolt and Mkd:
County Surveyor's Office, 1961 $\frac{1}{4}$ S36/S31 T28S
R7W R6W
New BT's: 9" W.Oak bears N.60°W. 12.4 ft. scribed $\frac{1}{4}$ S36 CS BT.
10" Laurel bears S.60°E. 29.8 ft. scribed $\frac{1}{4}$ S31 CS BT.
N. S. Fence is 32 ft. West of Corner.

87

James W.
Byron
May 24,
1961
C.S. File
No. 49/50

$\frac{1}{4}$ Corner to Sec. 25, T28-6W. & Sec. 30, T28-5W.
Found - Orig. 17", now 24" W.O. N.62°W. 23.8 ft. We open near base &
find good scribing "T". - Orig. 14", now 24" W. O. N.64°E.
17.2 ft. We do not open.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961
 $\frac{1}{4}$ R6W S25/S30 R5W T28S
New BT's: 15" W.O. bears S.63°W. 50.2 ft. scribed $\frac{1}{4}$ S25 CS BT.
Orig. 24" W.O. N.64°E. 17.7 ft. scribed $\frac{1}{4}$ S30 CS BT.

88

James W. Byron, Deputy County Surveyor
Dale McFarland
Jim Powell
September - October 1961
C. S. File No. 49/64

*FO. 6K
5/91
D. BAKER
M 113-32*

Sec. Cor. to Secs. 25 & 36, T28-6W & Secs. 30 & 31, T28-5W.
Found - Orig. 20", now 28" W.Oak, shows good scribing on old face, "BT",
S.65°W. 27.1 ft. - Orig. 28", now 32" W.Oak N.25°W. 66.7 ft.,
shows good scar. We do not open. Orig. SE.BT. not found.
Note - At 4 way Fence Intersection.
Set Brass Cap at Corner Mkd: County Surveyor's R6W S25 | S30
Office, 1961 S36 | S31 T28S R5W
Note - Cap set 2.0 ft. above ground. Solid Rock at Bottom.
New BT's: O.B.T. 28" W.Oak S.65°W. 27.5 ft. "S36 T28S R6W CS BT.
22" W.Oak bears S.41 $\frac{1}{2}$ °E. 43.0 ft. scribed S31 T28S R5W CS BT.
13" W.Oak bears N.43°E. 45.7 ft. scribed S30 T28S R5W CS BT.
8" W.Oak bears N.31°W. 37.0 ft. scribed S25 T28S R6W CS BT.

89

$\frac{1}{4}$ Corner to Sec. 36, T28-6W. & Sec. 31, T28-5W.
Found - Orig. 8", now 20" W.Oak S.54°W. 19.8 ft. We open & find good scribe.
Old Stump Hole & rotted Stump Section for N. E. BT.
Note - N. S. Fence 15 feet West of Corner.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961
 $\frac{1}{4}$ R6W S36/S31 R5W T28S
New BT's: 13" B.Oak bears S.42°E. 11.0 ft. scribed $\frac{1}{4}$ S31 CS BT.
9" B.Oak bears S.34°W. 11.2 ft. scribed $\frac{1}{4}$ S36 CS BT.

90