

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 28 S. T. S. R. 6 W. R. W. W. M.

NOKE-CHAPMAN CO., EUGENE, ORE. 21881

112

$\frac{1}{4}$  Corner to Sections 15 and 14.  
Found - Both Orig. BT's.: Orig. 18", now 44" B.Oak S.78 $\frac{1}{2}$ °W.  
131.3 ft., shows good scars.  
Orig. 14", now 40" B.Oak Stump N.55 $\frac{1}{2}$ °W. 198.0 ft. We  
open & find good scribing "B".  
Fence Corner Thus:




FND OK  
2/92 J. ARTMAN  
M.L.P. 1992-0020

Set - Brass Cap at South Side of Anchor Post Mkd: County Surveyor's  
Office, 1962  $\frac{1}{4}$  S15/S14 T28S R6W.  
New BT's: Rescribed O.B.T., now 44" B.O., S.78 $\frac{1}{2}$ °W. 131.3 ft.  
"  $\frac{1}{4}$  S15 CS BT"  
11" Laurel N.47 $\frac{1}{2}$ °W. 159.8 ft. scribed  $\frac{1}{4}$  S15 CS BT.  
No trees near East of Section Line.

113

Section Corner to Sections 10 - 11 - 14 - 15.  
Found - Large Sandstone 12" x 2", 3" above ground & at Fence Cor. Thus:

Set - Brass Cap 0.7 ft. East of Center of Rock and Mkd:  
County Surveyor's Office, 1962 T28S R6W  
No trees near for Bearing Trees:



Fd OK  
2/80 By M. M. W. K. E.  
F. A. A. G.  
CS 62/82

S. E. Corner D. L. C. No. 43.  
Found = Orig. 8", now 22" B.Oak S.75°E. 31.8 ft. We open & find  
good scribing "6".  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962  
S. E. Corner D.L.C. 43 T28S R6W  
New BT: Rescribed Orig. BT., now 22", B. Oak S.75°E. 21.8 ft.,  
S.E. Cl. 43, CS BT.  
10" B.Oak bears N.61°W. 13.0 ft. scribed SE Cl. 43 CS BT.  
Note - E. W. Fence is North 24.0 ft.

114

$\frac{1}{4}$  Corner to Sections 23 and 24.  
Found - Short  $\frac{3}{4}$ " I. P. at fence Corner & Both BT's. as recorded  
by Kerr. Bearing Trees are O. K. REN #50  
Set - Brass Cap alongside I. P. and at Fence Corner Mkd: County  
Surveyor's Office, 1962  $\frac{1}{4}$  S23/S24 T28S R6W.

115

$\frac{1}{4}$  Corner to Sections 14 and 23.  
Found - 8", now 24" B.Oak Stump N. ~~49~~ 49 $\frac{1}{2}$ °W. 244.9 ft., shows good  
reverse scribing "S 1". S.E. BT. not found. Ren #59  
No Original Bearing Trees found.  
Set - Brass Cap at Corner Mkd: County Surveyor's  $\frac{1}{4}$  S14 T28S R6W  
Office, 1962 S23  
New BT's: 12" W.Oak bears N.39 $\frac{1}{2}$ °W. 54.0 ft. scribed  $\frac{1}{4}$  S14 CS BT.  
17" Double W.Oak S.82°W. 27.9 ft. scribed  $\frac{1}{4}$  S23 CS BT.

116



Section Corner to Sections 8 - 9 - 16 - 17.  
Found - Orig. 8", now 12" W.Oak S.39°W. 27.7 ft., previously opened,  
shows good scribing "BT". Orig. 10", now 20" W.Oak N.87°W. 36.3",  
shows scars. Found Stump Hole for S.E. BT. NE BT. not found.  
Note - Corner is at 4 way Fence Corner.  
Set - Brass Cap at Cor. Mkd: County Surveyor's  $\frac{1}{4}$  S17/S16 T28S R6W  
Office, 1962  
New BT's: 5" W.Oak bears S.45°E. scribed S16 T28S R6W CS BT.  
Rescribe O.B.T., now 20", W.Oak N.87°W. 36.3 ft. S8T28S R6W CS BT.  
No trees near to N.E. (upper scribing on NE face)

117

**RE-RECORDED CORNER NO. #180**

James W. Byron, Deputy County Surveyor  
Dale McFarland  
John Powell  
January 15, 1962  
C. S. File No. 49/139

FD OK  
7/91 1991-0049

FD

OSHD 1969-  
L3