

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T.S. R. 6 W. R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey
& Crew
May 14, 1964
C.S. File No.
49/139

North $\frac{1}{4}$ Corner to Section 1 only, T28-6W.
Found - $\frac{3}{4}$ " Iron Pipe at Corner - See Ren. No. ³⁸85. **137**
12" W.Oak S. 67° W. 20.0 ft., scribing visible.
20" W.Oak N. 45° E. 65.2 ft. This Tree marked in 1961 REN. #85
Set - Brass Cap alongside I. Pipe & Mkd: County Surveyor's Office, 1964
T28S R6W $\frac{1}{4}$ S1
Note - Did not mark any new trees.

James W. Byron, Deputy
M. Godfrey, C. Putnam
Jan. 24, 1961.
C. S. File # 49/64.

N. E. Corner (Township Corner) to T. 28S. R. 6 W. **138**
Found - Orig. 14" W.Oak, now 18", nearly dead, S. 57 $\frac{1}{2}$ ° E. 414.5 ft.
Prev. opened, scribe marks "BE" plainly visible.
Orig. 12" B.Oak, now 21" Snag, 275.9 ft. Prev. opened & face
rotted, opened tree above old chopping. Foud frag. but
unmistakable reverse scribing.
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1961 **#183**

T28S R6W S 1/S 6 R5W
New BT's: 18" W.Oak S. 58° E. 209.3 ft. Mkd: T28S R5W S6 CS BT.
Crocker's S.W. BT., actually N.W. of Crocker's corner,
bears S. 87 $\frac{1}{4}$ ° W. 151.8 ft., shows good scars. Not rescribed
Crocker's Iron Bolt bears S. 67 $\frac{1}{2}$ ° E. 76 ft. from true corner.

John M.
Powell &
Crew
Dec. 21,
1965
C.S. File
No. 49/139

Sec. Corner to Sections 15 - 16 - 21 - 22. **139**
Found - County Surveyor's Brass Cap, 1962 - See Ren. #121
Also $\frac{1}{2}$ " Iron Pipe.
9", now 10" B.Oak S. 34° E. 56.4 ft., good scars.
10", now 12" B.Oak N. 73° W. 37.8 ft., good scars
New BT's: 6" B.Oak N. 10 $\frac{1}{2}$ ° W. 4.6 ft. scribed S 16 CS BT.
Note - One old BT. will be cut, which one questionable, Will most
likely be the S. 34° E. BT.

FD. B. C. BLOOM
5/8" E. 81.0
M 96.76
M 105.55 2/88
G. BAUGHMAN

John M. Powell
& Crew.
3/30/66
C.S. File
No. 49/139

$\frac{1}{4}$ Corner to Sections 29 and 28. **140**
Found - $\frac{3}{4}$ " Iron Pipe at $\frac{1}{4}$ Corner, See Ren. #114.
48" W. Oak, now 40", N. 67 $\frac{1}{2}$ ° E. 196.0 ft. shows axe work.
(I find this bearing to be N. 65° E.)
New BT: 48" W. Oak S. 67 $\frac{1}{2}$ ° E. 86.0 ft., scribed $\frac{1}{4}$ S28 CS BT.
Note - This corner is in corral. Tied to Corners of Barn.

RE-RENEWED, SEE CORNER NO. #160

James W.
Byron, Co. Surv.
For: Park Dept.
C.S. 54/24
M 31 - 39.

N. E. Corner of D. L. C. No. 45. **141**
Found - 2" Iron Pipe used for the corner, established by
Surveyor, Boyer, shown on L. G. Hicks Maps, 4/26/1916,
See recorded on M 13 - 73.
From Which: 2" Iron Pipe, Initial Point of "Watts Acres", bears
S. 0° 07' 40" W. 79.49 feet.

FD. I. P. BLOOM
4/18/64
M. HANIG
C.S. 50/164

April 12, 1966

Vernon "Ray"
Tracy &
Crew
12/22/66
C. S. File
No. 49/139

N. W. Corner to D. L. C. No. 43. **142**
Found - County Surveyor's Brass Cap, properly mkd., 4" above ground
on S. side of driveway. Recorded in "Meadowbrook", Plat 9/24.
No BT's. available.
Power Pole bears N. 26° W. 20.8 ft., aluminum tag 2"x6" mkd. "CopCo B9277".
Power Pole bears N. 66° W. 113.8 ft., aluminum tag 2"x7" mkd. "CopCo B12467"
This corner lies S. 75° E. 25110 ft. from business Rt. #99 (old highway),
east edge of road surface, parallel to south edge of driveway.

12/22/66
FD. Brass Cap
10/85
E.A. Bloom
M 99-57