

Douglas County Surveyor's Record of  
Government Corners Renewed

T 28

T. S.

R 6

R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97101

CONT. - - - - -

(Sec. cor. 18 & 19; 13 & 24 of T.28-7)

158

Set - A 1" x 36" I.P. with brass cap stamped "Douglas County Surveyor T28S S13 S18 S24 S19 R7W R6W 1982", firmly in the ground protruding 0.2 ft. (new position bears S.2°W., 29.8 ft. from 1973 pipe.)

New bearing and distances:

A 12" maple bears N.9°W., 46.1 ft.

A 19" maple bears N.62°E., 158.9 ft.

A 48" cottonwood bears N.22 1/2°W., 21.7 ft. rescribe "T28S R7W 13 CS BT" in double blaze. Deface other blaze.

New BT - A 47" cottonwood bears S.44°E., 3.1 ft. to boat spike set above fencing. (impractical to scribe)

No suitable trees in SW quadrant.

Corner located Sly side of dim road, 2 ft. north of E-W fence.

5/11/82

Karen Reed, Douglas  
County Surveyors  
Office  
Terrie Plouff  
May 11, 1982  
L.S. 61/36

RE-RENEWED SEE CORNER NO. #168

1/4 Corner for Sections 35 and 36

159

Found - 1961 County brass cap with 1" I.P. alongside protruding 14" out of ground. Cap properly marked. Ren. #99

Search for BTs revealed no evidence left from either renewal #28 or #99. New Accessories:

\* 8" W. oak scribed "1/4 S36 CS BT" in double blaze bears N.50 1/2°E., 82.4 ft.

\* 8" W. oak scribed "1/4 S36 CS BT" in double blaze bears N.69°E., 75.0 ft.

\* 18" B. oak scribed "1/4 S36 CS BT" in double blaze bears S.2°E., 36.8 ft.

SE corner new metal barn bears N.73 1/2°W., 67.5 ft.

Fence corner with fences running North, South and West bears S.57°E., 121.7 ft.

Sketch in C.S. file.

8/4/82

Gregory Quibell  
Deputy, Doug. Co.  
Surveyors Office  
John Powell  
August 4, 1982  
C.S. 62/1

\* THESE 2 TREES FOUND OK 9/92 BY BRANCH M112-56

RE-RENEWED SEE CORNER NO. #170

Herbert Northcraft  
L.S.# 750  
For: Rosa Owens  
July, 1982  
M 92 - 67

1/4 Corner for Secs. 29, & 28.

Ren. # 140

RE-SET - Reset corner with a 5/8" x 30" I.R., 6" under surface, 1.25-ft. north of the barn door hinge, Wf L.S. 750 on side, from:

48" W. Oak N.67-17°E., 36.0 ft.

48" W. Oak S.67-17°E., 36.0 ft.

B.O. - S corner of barn S.61°E., 19-ft.

7/82

Section corner for Sections 33 and 34 only of T.27-6

161

Found - Original monument not found.

Post set by Briggs not found. Ren. #38 in T.27-6

Iron pipe set by Byron has been removed and is lying with old fence debris. Ren. #86 in T.27-6

We find, at N.76 1/2°E., 198.0 ft. the center of a root hole with the decaying remains of the northerly portion of the trunk of an Ash. The size of this trunk is indeterminable, it is large enough to be that tree referred to in Renewals #38 & #86. Down portion is tagged with BLM BT tag, and has evidence of a possible old blaze. We found no scribing in the tree. The southerly portion of this tree is standing & alive. Briggs Ren. calls a 20" Ash, N.76 1/2°E., 300 lks. (198.0 ft.) matching orig. record to a 14" Ash. Byron fd. scribing in this tree during his renewal.

A 54" now 58" diam., W.Oak with well healed single blaze 5 1/2 ft. above ground on a westerly trunk bears S.63°E., 307.5 ft.

Byrons sketch shows an anchor post N.54°E., at 31 ft. We find a gate post bearing N.54°E., 33.0 ft. This is probably not the same post tied by Byron, portions of this fence have been rebuilt.

Set - A 1" x 30" I.P. with attached brass cap 42" deep (cap is 14" below surface) at the corner position. Cap Mkd. "Douglas County Surveyor T 27 S R 6 W CC S33 S34 1984".

New Accessories:

A 6" W. Oak double blazed & scribed "CC T27S R6W S33 CS BT" bears N.72°W., 360.9 ft.

5/8" x 30" I.R. with "Douglas Co. Surveyor" alum. cap attached and stamped "BO 1", set in fence line (running S.56°E.) 4" above ground bears N.86 1/4°E., 52.0 ft.

5/8" x 30" I.R. with "Douglas Co. Surveyor" alum. cap attached and stamped "BO 2" set in fence line (running S.56°E.) 4" above ground bears N.4 1/4°W., 38.1 ft.

Note: Sketch in C.S. file. Corner falls in dim track road. 6/5/84

Larry E. Monrean, Deputy  
Douglas County Surveyors Office  
R. W. Smith & S. J. Flause  
June 5, 1984  
C.S. 62/18