

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 7 R. W. W. M.

G. G. Stewart Deputy
Witnesses
C. Crocker
J. H. Porter
September 1922.

Set by Ben B. Irving Mar. 3-8 and 10, 1926.

✓ 1/4 CORNER BETWEEN 20 and 29. **SEE CORNER NO. 86A** 22
Reset from two O.B.T.s agree with distance but bearing
of one is 90° off. Marked
Fir 6" dia. for corner.
Laurel 12" dia. bears N. 76°W., 37.6 ft.
Black Oak 8" dia. bears S. 20 1/2°E., 23.6 ft.

✓ 1/4 CORNER BETWEEN 29 and 30. 23
Found one stump and burned B.T. Set Iron Pipe for
corner and marked
White Oak 10" dia. bears N. 19 1/2°E., 56.2 ft.
Black Oak 8" dia. bears S. 89 1/2°W., 48.4 ft.
Note: Black Oak B.T. cut. No tree West. Marked
White Oak 10" dia. bears S. 27°30'E., 25.0 ft.
Note by H.L. Eppstein, C. Crocker Witness
February 1934.

✓ S.W. CORNER OF CLAIM 54 24
Found O.B.T. standing. Set Iron pipe for corner and
marked
Black Oak 18" dia. bears N. 54 1/2°E., 136.9 ft.
White Oak 20" dia. bears N. 20°W., 107.5 ft.

✓ SECTION CORNER 15, 16, 21 and 22. **SEE CORNER NO. 75** 25
Found conglomerate rock set by Frear. One original B.T.
intact. All others had been chopped into and were rotting
quite rapidly. B.T. set by Frear down and rotting.
Drove Iron Pipe by rock and marked new trees as follows.
Douglas Fir 12" dia. bears N. 36°10'W., 44.0 ft. distant
Douglas Fir 16" dia. bears N. 47°53'E., 43.3 ft.
Douglas Fir 22" dia. bears S. 34°00'E., 48.0 ft.
Black Oak 20" dia. bears S. 7°00'W., 56.0 ft.
This last is one of the original B.T.s which has never been
chopped into. Frear's conglomerate rock is disintegrating
badly.

✓ 1/4 SECTION CORNER 21 and 22. 26
No evidence of this corner could be found on the ground.
Set a new corner by proportionate distances between section
corner 15, 16, 21 and 22 and section corner 21, 22, 27, and
28. This section line was found to bear N. 28°37'W., 4632 ft.
For quarter section corner set a Ford axle from which a
White Oak 5" dia. bears S. 8°E., 20.7 ft. 152
Fir 20" dia. bears S. 8°06'W., 38.0 ft.

✓ SECTION CORNER 21, 22, 27 and 28. **SEE CORNER NO. 74** 27
Two of the Original B.T.s standing but badly rotted.
Scribe marks not legible. The third was down and rotting.
Found enough of the marks to identify the corner. Set for
corner a very hard rock 6" x 10" x 24" flush with the ground
and marked with a cross from which a
White Oak 26" dia. bears N. 27°51'W., 170.7 ft.
White Oak 16" dia. bears N. 88°41'E., 184.1 ft.
White Oak 34" dia. bears S. 15°00'E., 191.9 ft.
There was no tree available for witness in the S.W.
quadrant but the gable peak of a red barn bears
S. 67°07'W., approximately 1/2 of a mile. This is
the highest point visible.

✓ 1/4 CORNER SECTION 22 and 23. 28
Found Original B.T.s which were badly rotted. Set an Oak
post for corner from which
Black Oak 6" dia. bears S. 62°39'W., 19.4 ft.
Black Oak 8" dia. bears S. 55°55'E., 40.6 ft. 153

Witnesses to all these corners are,
R. L. Irving and R. E. Jennie.