

Douglas County Surveyor's Record of
Government Corners Renewed

28

T. S.

7

R. W. W. M.

Section corner to secs. 28, 29, 32 and 33.

60

Found - R. Fir 16 inch Stump only, N.54°E., 47.0 feet. 12 inch R. Fir, N.10°E., recorded N.10°W., 13.3 ft. Also found 24 inch R. Fir stump, S.10½°E., 31.0 feet. The N. E. and N. W. have scribing visible.

Set brass cap at corner mkd. ~~29/28~~ T 28 S, R 7 W., County Surveyor's Office, 1955.

Blazed and scribed:

12 inch R. Fir, N.25°W., 4.6 feet, mkd S 29 C. S. BT.

16 inch Fir, S.46½°W., 53.3 ft., S 32 C. S. BT.

20 inch Fir, N.86°E., 14.1 feet, mkd. S 28, CS. BT.

James W. Byron, Deputy County Surveyor
Ray Irving
John Fee
May 5, 1955.
C. S. File No. 46/130.

Section corner to secs. 31 & 32 (T 28 S, R 7 W) and secs. 5 & 6 (T 29 S, R 7 W).

61

Found:

30 inch Fir stump S.83°E., 78.2 feet, bark scribed BT. *Ren #54*

8 inch Fir, S.20°W., 38.9 feet, some scribing visible. Tree pushed over.

24 inch Fir, Stump, N.32°E., 54.4 feet. Log against scribing.

Set 1 inch X 30 inch Iron Pipe with Brass Cap mkd. ~~31/32~~ 28 S R 8 W, County Surveyor's Office, 1954.

Chisled 3 inch cross on high point of rock 12 feet x 10 feet, 8 feet high, N.78½°W., 90.7 feet.

No trees near.

Var. 20¼°E.

James W. Byron
Ray Irving
John Fee
Nov. 16, 1955.
C. S. File No. 47/25.

Northeast corner of the Orley Hull Donation Land Claim No. 54.

62

Found ½ inch iron pipe, 6" under on N. - S. fence and found 96 inch B. O.

recorded 72 inches which shows blaze - We do not cut out. The Southwest

B. T. is gone - would be in plowed field. *Ren #30*

Blazed and scribed:

30 inch Pine, N.36°W., 53.2 feet dist., mkd. NE Cl 54 CS BT.

8 inch W. Oak, South 30.8 feet dist., mkd. NE Cl 54 CS BT.

*FD. 2/10/54
O.S.N.D. N.
NAVIC.
C.S. 5/1/54
R.A. I.P. Lease.*

Section corner to secs. 20, 21, 29 and 28.

63

Found ½ inch iron pipe at corner of fence and 2 B. T.s in Good Condition. *Ren #21*

O. B. T. at N.35½°E., 31.5 feet gone. Stump tipped over but position good. Also found old stump of tree at S.79°W., 28 feet which had been cut out.

Set iron pipe with brass cap stamped County Surveyor's Office 1956 ~~20/21~~ 29/28.

Marked 2 new trees:

10 inch R. Fir, N.38°15'E., 26.3 feet.

14 inch R. Fir, S.38½°W., 65.2 feet.

O. B. T. - 30 inch B. O. bears S.39°E., 38.2 feet.

O. B. T. - 50 inch B. O. bears N.12°W., 214.5 feet. *7/5/52*

*FD. SK 7/81
G.G. RUBB
M88-34
7/14 G. Bannum
E.M.S. 7/2
2/21 O.S.N.D. 5/1/54*

County Surveyor's Office
James W. Byron, Dep.
County Surveyor
October 16, 1956
C. S. File No. 47/176.

¼ corner to secs. 7 & 18.

64

This corner was lost or obliterated. Re-establish corner by proportional measurement.

Set an ¾ inch iron post for corner point.

From which:

18 inch Fir tree bears N.35°W., 17.5 feet mkd. ¼ S 7, 1581 B.T.

20 inch Fir stump bears S.6°W., 30 feet mkd. ¼ S 18 BT.

168

Sec. corner to secs. 7, 8, 17 & 18.

65

This corner has been lost or obliterated. Point for corner located by double proportional measurement.

¾ inch iron pipe at point for corner.

From which:

24 inch Fir, N.77°E., 6 feet dist., mkd. S 8, T 28 S, R 7 W., 1581 B.T. on bark.

8 inch Laurel, S.15°E., 9.0 feet, mkd. S 17, B.T.

18 inch Fir, N.83°W., 11 feet bark blazed S 7 B.T.

10 inch Fir, S.60°W., 6.3 feet bark blazed S 18 B.T.

Arthur Boyer
March 8, 1957.
C. S. File M 4 + 74.