

Douglas County Surveyor's Record of  
Government Corners Renewed

28

T. S.

7

R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

County Surveyor's Office  
James W. Byron, Deputy County Surveyor

April, 1957

C. S. File No. 47/176.

RM 1-15

$\frac{1}{4}$  corner to secs. 20 and 29.

Found an 18 inch (now) fir at corner showing old blazes and 8 inch B. O. now 12 inches, with face rotted and no scribing visible - checks for bearing and distance to corner, S.20 $\frac{1}{2}$ °E., 23.0 feet. The 12 inch Laurel, N.76°W., 37.6 feet not found. I also find 18 inch B. O. with open face that shows faint scribe marks - may be orig. and bears N.68°E., 118.8 feet.

Set an iron pipe with brass cap at west face of 18 inch Fir corner tree, mkd.  $\frac{1}{4}$  S 29, T28S, R7W., County Surveyor's Office, 1956.

From which:

10 inch R. Fir bears S.9 $\frac{1}{2}$ °W., 9.4 feet, scribed  $\frac{1}{4}$  S29 CS BT.

10 inch R. Fir, bears N.25°W., 38.4 feet, scribed  $\frac{1}{4}$  S 20 CS BT.

86-A

Section corner to Secs. 29, 30, 31 and 32.

Found  $\frac{3}{4}$  inch iron pipe at corner. REN. #18

Found 44 inch B. Oak, N.76°W., 18.8 feet - (to center of tree).

Found 42 inch B. Oak, stump, N.19°W., 11.0 feet to center of stump.

Found 36 inch W. Oak, N.6°E., 27.6 feet to center of tree.

We: Rescribe Oak, N.76°W., 18.8 feet (S 30 C. S. BT.)

Rescribe W. Oak, N.6°E., 27.6 feet (S 29 C. S. BT.)

Rock claimed by some to be orig. sec. corner bears S.58 $\frac{1}{2}$ °E., 9.85 feet.

$\frac{1}{2}$  inch iron pipe in fence line (about 6 inches extending above ground) bears S.85°E., 19.8 feet.

Northwest corner of concrete bottom step of C. M. Siegel house bears S.3 $\frac{1}{2}$ °E., 25.05 feet.

No trees near in SE or SW quadrants.

87

$\frac{1}{4}$  corner to secs. 28 and 29.

Point for corner located by proportional measurement. SEE ALSO #123

Set a  $\frac{3}{4}$  inch iron rod 16 inches below ground surface in field for corner.

Blaze and scribe:

28 inch Fir, S.81 $\frac{1}{2}$ °W., 317.8 feet. ( $\frac{1}{4}$  S 29 CS BT). DUPLICATED RENEWED

30 inch Black Oak, S.86 $\frac{1}{2}$ °E., 151.5 feet. ( $\frac{1}{4}$  S 28 CS BT). SEE #20

88

Southeast corner of the Orley Hull DLC No. 54.

Found  $\frac{3}{4}$  inch iron pipe at corner and 6 inch Maple (now 18 inches) S.46°E., 12.4 feet - reverse scribing visible. REN. #29

Blazed and scribed:

24 inch W. Fir, N.76°W., 9.3 feet, SE Cl 54 CS BT.

Note: Corner 30 feet South of logging road.

89

Southwest corner of the Orley Hull DLC No. 54.

Found  $\frac{1}{2}$  inch pipe at corner. REN. #24

Found 24 inch B. Oak, N.51 $\frac{1}{2}$ °E., 136.9 feet - has been chopped open and old face rotted.

No trace of tree to Northwest.

A 36 inch W. Oak, N.30°E., 54.0 feet shows definite axe scar facing corner pipe. - Reblaze and scribe this tree (SW Cl 54 CS BT).

Blaze and Scribe:

6 inch W. Oak, S.82°E., 37.9 feet, scribed (SW Cl. 54 CS BT).

90

Corner of 26, 27, 34 and 35.

I renewed this corner from the original bearing trees both of which had been chopped open. Tree S.E. bore scribe marks.

I set a 4 x 4 x 40 Cedar Post 5 ft. East of small creek and marked: An Ash 8" diam. bears N.10°30'W., 5.9 feet.

A B.Oak 8" diam. bears S.63°30'W., 18.0 feet.

82

91

$\frac{1}{4}$  Corner North Line of Section 6.

Set 3" x 3" x 30 stake from old bearing tree which bears S. 22°E., 48 lks. remarked.

Also Marked: White Oak 15" diam. bears N.72°E., 20 ft. new B.T.

SEE COR. #131

92

J.W.Cole-Surv.

Wit.:

R.K. Paris

L. Stevens

4/9/24

Eppstein

Wit.:

Chambers

Lige Mathews

Feb. 9, 1922