

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 7 R. W. W. M.

MOSE-CHAPMAN CO., EUGENE, ORE. 97190

A. Boyer
Nov. 1958
M.13-19

Center Section 7 - Iron Pipe
25" W. Fir N.80°W. 39.9 ft. scribed Cen S7 1581 B.T.
15" Cedar S.87°E. 23.5 ft. " Cen S7 1581 B.T.
180 ft. N. of top of ridge on N. slope & 117 ft. E. & 38 ft. S. of
36" Fir blazed about 1930.

108

1/4 Section Corner to Sections 23 & 24.
Found - Orig. 10", now 34" Oak N.38°W. 146.5 ft., now down. I open
& find good scribing 1/4 S B".
Find 3' x 6' x 4' high isolated Rock N.80°E., record
distance 264.0 ft. I find should be 262.0 ft. to center.
Set Brass Cap at Corner Mkd: 1/4 S23/S24 T28S R7W County Surveyor's
Office, 1958
New BT's: 26" W.Oak bears N.47°W. 102.9 ft. scribed 1/4 S23 CS BT.
Chisled + 2" on West Face of isolated Rock 3' x 6' x 4' high, N.80°E.,
262.0 ft.

109

S. W. Corner D. L. C. No. 37.
Found - No Orig. BT's. I find Eppstein's 12", now 18" W. Oak N.32°E.
39.5 ft., I open & find good scribing. - Ren. #72 & 101
Find 4" x 16" x 9" Rock at Corner & Fence Corner.
New BT's:
7" W. Oak bears N.58°W. 6.0 ft. scribed CL 37 SW CS BT.
14" W. Oak bears N.20°E. 20.3 ft. scribed CL 37 SW CS BT.

110

Section Corner to Sections 13, 14, 23, & 24.
Found - All four of Eppstein's BT's. as recorded except 20" W. Oak,
record N.5°E. 40.0 ft., should be N.55°E. 40.0 ft., I open
& find good scribing. Ren. #93
Also open record 8" B.O., should be 8" R.Fir, now Stump,
shows good scribing N.75°W. 49.4 ft.
Also record 10" B. Oak should be 10" Fir S.24 1/2°W. 24.3 ft.,
shows good scars, I do not open.
I open 12", now 16" B. Oak S.89°E. 35.7 ft. & find goodscribing.
Set Brass Cap at Corner Mkd: S14/S13 T28S R7W County Surveyor's
S23/S24 Office, 1958.
New BT's: 14" Cedar bears N.60°W. 82.0 ft. scribed S14 T28S R7W CS BT.
15" Fir bears S.64°E. 40.7 ft. scribed S24 T28S R7W CS BT.
9" W.Oak bears N.17 1/2°E. 53.1 ft. scribed S13 T28S R7W CS BT.
Note: I find 1 1/2" Iron Pipe said by Cleal Davis to have been set for
this section corner about 3 years ago, bears N.16 1/2°E. 61.7 ft.

111

N. W. Corner D.L.C. No. 58.
Found - Remains of old Oak Stump with good reverse scribing on chip
at base "S 7", bears S.82°W. 54 ft.
Oak Stump Hole that checks bearing & distance for Orig.
West BT.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1958
N.W. Cor. DLC 58 T28S R7W
Note: Corner under E.W. Fence.
New BT's: 7" B.Oak bears S.23°W. 16.4 ft. scribed N.W. CL 58 CS BT.
10" B.Oak bears N.64°E. 13.4 ft. scribed N W CL 58 CS BT.

112

1/4 Section Corner to Sec. 12, T28S R7W, & Sec. 7, T28S R6W. #255
Found - Both BT's. as recorded by Frear & both are now partly dead.
Each checks for bearing & distance. The B.Oak to N.W. shows
good scar, I do not open. Also find gun barrel at Corner. Ren. #99
Do Not Set Brass Cap at Corner.
New BT's: 8" W.Oak bears S.54 1/2°W. 34.0 ft. scribed 1/4 S12 CS BT.
8" B.Oak bears S.46°E. 11.9 ft. scribed 1/4 S 7 CS BT.

113

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
November - December 1958
C. S. File No. 49/50

RE-RENEWED SECTION CORNER #255