

Douglas County Surveyor's Record of  
Government Corners Renewed

28

T. S.

7

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

S. E. Corner Claim No. 54.

Found -  $\frac{3}{4}$ " Iron Pipe at Corner (6" Male, now 18") S.46°E. 12.4',  
Reverse scribing visible. REN. #29 #89

Renew Corner, blazed & scribed 24" W. Fir N.76°W. 9.3 ft. SE Cl. 54  
CS BT.

Note: Corner 30' South of Logging Road.

S. W. Corner D. L. C. No. 54.

Found -  $\frac{1}{2}$ " Iron Pipe S.W. Cor. DLC 54. REN. #24 #90 126

Orig. & Renewed BT's. NE BT. centers rotted, NW BT gone.  
A 36" W. Oak N.30°E. 54.0 ft., shows definite Axe Scar,  
facing corner, Pipe, reblazed & Scribed this Tree.  
(S.W. Cl. 54 CS ET.)

Blaze & Scribe 6" W. Oak S.82°E. 37.9 ft. (SW Cl. 54 CS BT).

$\frac{1}{4}$  Section Corner to Section 20 & 29. 127

Found - 18" Fir at corner, shows old blazes. REN. #22 #86A

8" B. Oak, now 12", face rotted, no scribing visible,  
checks for bearing & distance to corner, S.20'30"E. 23.0'.

18" B. Oak with open face, shows faint scribe marks, N.68°E. 118.8',  
fence corner.

At  $\frac{1}{4}$  corner Set Brass Cap at West Face of 18" Fir Corner Tree,

$\frac{1}{4}$  S29 T28S R7W County Surveyor's Office, 1956 from which:

10" Fir bears S. 9°30'W. 9.4 ft. scribed  $\frac{1}{4}$  S29 CS BT.

10" Fir bears N.25°W. 38.4 ft. scribed  $\frac{1}{4}$  S20 CS BT.

James W. Byron, Deputy County Surveyor  
Surveyed For Douglas County  
C. S. File No. 47/176  
R.M. 1 - 15  
April 24, 1956

SEE NEXT PAGE