

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 7.8.13 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

March 1961
C.S. File 49/50

$\frac{1}{4}$ Section Corner to Sections 9 and 10. 146
Found - Both BT's. & $\frac{1}{2}$ " I. Pipe at Corner. All as recorded REN #6
by Stewart, 1922. The B.Oak to N.W., now snag, shows
good scribing "BT". Fir to N. E., now Stump.
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1961
 $\frac{1}{4}$ S9/S10 T28S R7W
New BT's: 8" R.Fir bears S.68°E. 31.9 ft. scribed $\frac{1}{2}$ S10 CS BT.
15" R.Fir bears N.19°W. 5.7 ft. scribed $\frac{1}{2}$ S 9 CS BT.

$\frac{1}{4}$ Section Corner to Sections 1 and 12. 147
Found - Orig. 12", now 44" B.Oak S.13°E. 240.9 ft., REN #2 shows good
scribing "BT". Orig. N.E. BT. not found.
Note - Corner in field - Set Wit. Cor. 140 ft. South.
Set Brass Cap at Wit. Cor. Mkd: Wit. C. 140 North to $\frac{1}{4}$ S 1 T28S R7W
County Surveyor's Office S 12 1961
Note - Iron Bar set 1917 not found.
New BT's: 18" B.Oak bears S.56°E. 86.4 ft. scribed $\frac{1}{2}$ S12 CS BT W.C.
9" B.Oak bears N.74°W. 47.1 ft. scribed $\frac{1}{2}$ S 1 CS BT. W.C.

$\frac{1}{4}$ Section Corner To Sec. 1, T28-7W. & Sec. 6, T28-6W. 148
Found - Both Orig. BT's. Each checks record for bearing & distance.
We open N.E. BT. & find good scribing "S".
Set - Brass Cap at Corner Mkd: $\frac{1}{4}$ S1/S6 T28S County Surveyor's
R7W R6W Office, 1961
New BT: 8" B.Oak bears S.59°E. 3.8 ft. scribed $\frac{1}{4}$ S 6 CS BT.

Section Corner to Sections 5 - 6 - 7 - 8. 149
Found - Brass Cap at Corner and Stumps of two 1921 BT's. show scribng.
New BT's: 14" Yewwood bears N.12 $\frac{1}{2}$ °E. 29.5 ft. scribed S 5 T28S R7W CS BT.
Unfilled 3" (cross) & drove PK nail at center bears N.50°E.
28.3 ft. in Sandstone Outcrop on Steep West Slope exposed
Rock about 7' high & 10' across.
No other Trees near.

$\frac{1}{4}$ Section Corner to Sections 5 and 8. 150
Found - Brass Cap at Corner & Shell of Stump of S.W. BT. & Stub of
N.W. BT., check record O.K.
New BT's: 10" W.Fir bears S.51°W. 48.0 ft. scribed $\frac{1}{4}$ S 8 CS BT.
15" Cedar bears N.24 $\frac{1}{2}$ °E. 71.2 ft. scribed $\frac{1}{4}$ S 5 CS BT.
F.O. OK 5/26/76 - Co. Surveyor C.S. 59/8

$\frac{1}{4}$ Section Corner to Sections 30 and 31. 151
Found - Mensch's BT's. N.E. BT. now Stump, We open S.W. BT. &
find good scribing "B". We do not find Brass Cap Set
by Mensch. Corner under N. S. Fence. REN #42
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961
 $\frac{1}{4}$ S30 T28S R7W
S31
New BT: 8" Laurel bears N.67°E. 22.4 ft. scribed $\frac{1}{4}$ S30 CS BT.
FD. 2/84 B. ROGERS M 96-49

$\frac{1}{4}$ Section Corner to Sections 21 and 22. 152
Found - Axle Set By B. B. Irving. REN #26 $\frac{1}{4}$ S21 CS BT.
5" W.Oak S. 8°E. 30.7 ft. (instead of 20.7') showing
good scribing " $\frac{1}{4}$ ". Tree nearly dead.
Fir S.8°W. 38.0 ft., down & badly rotted. Shows scar. h/20/92
Do Not Set Brass Cap. *NOTE: PER BLM - This COE. MAY NOT BE THE 1/4 COR. Watch for Resurvey Notes & PLAT YH*
Blaze & Scribe 2 New BT's: 24" D. Fir S. 3 °W. 33.0 ft. " $\frac{1}{4}$ S21 CS BT".
12" D. Fir N. 7°E. 25.7 ft. " $\frac{1}{4}$ S22 CS BT".
Corner lies on Steep West Slope - Rock outcrops to South, SE. & East.

$\frac{1}{4}$ Section Corner to Sections 22 and 23. 153
Found - B.Oak(now 8 $\frac{1}{2}$ ") showing good scras S.62 $\frac{1}{2}$ °W. 19.4 ft. Did not open. REN #28
8" B.Oak Snag S.56°E. 26.6 ft. (instead of 40.6 ft.) with nearly
rotted old face showing good scribing "S23 CS".
Orig. B.Oak, now 40") S.77°E. 52.8 ft., showing scar. This tree
nearly dead. Has never been opened to face.
(cont'd. over)

James W. Byron, Deputy County Surveyor
Milo Godfrey
Clete Putnam
March 1961
C. S. File No. 49/50

RE-RENEWED SEE CORNER NO. #229