

Douglas County Surveyor's Record of  
Government Corners Renewed

T 28 S. T. S. R 7 W. R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

Set Iron Pipe with Brass Cap at Corner Mkd:  
County Surveyor's Office, 1961 T28S R7W  $\frac{1}{4}$  S22/S23  
New BT: 18" Madrone S.84°E. 23.2 ft. Mkd.  $\frac{1}{4}$  S23 CS BT".

FD. 12/18/87  
D. D. Bente  
1105-35

West  $\frac{1}{4}$  Corner Section 31. 154

Found - Brass Cap at Corner 2' West of N.S. Fence. BT. not found.  
We also find Brass Cap at AP bears N.89°W. 30.1 ft.  
New BT: 10" W.Oak bears N.52°E. 9.0 ft. scribed  $\frac{1}{4}$  S31 CS BT.

SEE #35 + 1924 Resurvey

Corner 

S31	T28S R7W
S 6	T29S R7W

155

Found - Both Fir BT's. recorded by Mensch. Each is now down,  
We open & find good scree on each B.T.  
Brass Cap (1924) Not found. Ren #36

Set - Brass Cap Mkd: 

S31	T28S R7W
S 6	T29S R7W

 County Surveyor's Office, 1961

New BT's: 6" Cedar bears N.31 $\frac{1}{2}$ °E. 82.7 ft. scribed S31 T28S R7W CS BT.  
12" R.Fir bears S.28 $\frac{1}{2}$ °E. 99.7 ft. scribed S 6 T29S R7W CS BT.

$\frac{1}{4}$  Section Corner to Section 14 and 13. 156

Found - B.Oak, now 30", N.64°E. 101.0 ft. This tree previously  
opened & center rotted. Fragments of scribe Mkd. in  
rotten wood found inside.

B.Oak, Now 40", N.82°W. 148.5 ft. This tree previously  
opened & center Rotted. No scribing found.

Set Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1961  
T28S R7W  $\frac{1}{4}$  S14/S13

New BT's: 14" B.Oak S.57°E. 27.0 ft. Mkd:  $\frac{1}{4}$  S14 CS BT.  
12" W.Oak N.88 $\frac{1}{2}$ °W. 79.1 ft. Mkd:  $\frac{1}{4}$  S13 CS BT.

Corner lies in N. & S. Fence Line. Fence Corner(N. S. & W.)  
bears North approximately 40 feet.

$\frac{1}{4}$  Section Corner to Sec. 31, T28S R7W. & Sec. 6, T29S R7W. 157

Found - Brass Cap at Corner & Stump of S.E. BT. Rotted 

S 31	T28-7W
S. 6	T29-7W

  
Remains of N. W. BT. found.

New BT's: 5" W.Oak bears S.70°W. scribed  $\frac{1}{4}$  S 6 CS BT.  
12" Ash bears N. 9°W. 11.6 ft. scribed  $\frac{1}{4}$  S31 CS BT.

Also see Ren. #1 T29-7

$\frac{1}{4}$  Section Corner to Sec. 32, T28-7W. & Sec. 5, T29-7W. 158

Found - 2" x 2" Stake at Corner & 27" B.Oak N.44°W. 36.0 ft.,  
shows good scribing  $\frac{1}{4}$  S32 BT.

26" Fir Stump bears S.79°W. 52.0 ft. We open near base  
& find good scribing "T". 222

Stump Section of 30" B.Oak, shows old scar N.39°W. 28.0 ft.

Set - Brass Cap alongside Corner Stake & Mk: 

S32	T28S R7W
S 5	T29S R7W

 County Surveyor's Office, 1961

New BT: 6" R.Fir bears S.51°W. 25.4 ft. scribed  $\frac{1}{4}$  S 5 CS BT.

(see also Ren #55)

"DESTROYED BY Logging Report By DCSO 4/24/82 CS. 6211"

$\frac{1}{4}$  Section Corner to Sections 17 and 18. 159

Found - 40" Fir S.50°E. 29.7 ft. (measured on slope) with characteristic  
Ford scribing " $\frac{1}{4}$  2 Bl-" (bark scribe).

32" Fir S.32°W. 3.0 ft. with old scribing "BT" (bark scribe)

40" Fir Stump, cut low, bears N.85°W. 8 ft.

Old scribing on 2 trees found, both face corner as set.

Both trees have been rescribed since orig. scribing.

Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1961  
S 18/S17  $\frac{1}{4}$  T28 S R7W

S. E. BT. is S.50°E. 28.0 ft. (horizontal measure)

A scribed Stake, approx. 10 to 15 yrs. old) 4" sq. & 18" above ground  
bears N.32°E. 7 feet.

May 9 1961

James W. Byron, Deputy County Surveyor  
Milo Godfrey  
Clete Putnam  
April 1961  
C. S. File No. 49/50