

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 7 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

199

James W. Byron, Co. Surv.
"Ray" Tracy & Crew
January, 1969
C. S. File No. 54/78

Witness Corner to Section Corner Sections 25 & 36 only, T28-8W.
Found - 1" I.P. for Wit. Cor. which is 25 ft. W. of true corner point.
No trace 1924 GLO Brass Cap.
16", now 24" maple, alive, N.22°E. 11.9 ft., blaze healed over.
12", now 22" Alder, alive, S.35°W. 24.4 ft., scribe marks visible on nearly healed blaze.
24", now 30" Ash, alive, N.27°W. 29.0 ft., scribe marks visible on unhealed blaze.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969

R	T 28 S	R
8	S 25	7
W	S 36	W

W. C. 25 ft. E. to corner.
Set - Old 1" I.P. at true corner point which is 25 ft. E. of witness corner in old creek bed. This corner approx. 140 ft. west of Tenmile Creek.

RE-RENEWED, SEE CORNER NO. #267

200

Vernon R. Tracy & Crew
Feb. 3, 1969
C. S. File No. 52/79

Section Corner to Sections 22 - 23 - 26 - 27.
Found - 1" x 1" Iron Bar, 14" long, 8" above surface of ground, Ren. #80.
9", now 10" W.Oak, S. 23° W. 33.4 ft., healed blaze. Ren. #80
15", now 16" Laurel, N. 31° W. 19.4 ft., scribe marks visible on nearly healed blaze.
6", now 8" D.Fir, S.73°E. 22.7 ft., healed blaze.
N. E. BT., now sawed stump, scribe visible.

Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1969

T 28 S	R 7 W
S 22	S 23
S 27	S 28

alongside
New BT: 6" D.Fir N. 64° E. 19.8 ft. scribed "T28S R7W S23 CS BT".
This corner lies on moderate north slope approx. 100 ft. S. of draw, course NW.
C.S. 52/79

201

James W. Byron, Co. Surveyor
Vernon "Ray" Tracy
Jack Heritage & Vince Perron
March, 1969
C.S. File No. 54/83 Map M-37-44

S.W. Corner D. L. C. No. 51.
Found - Bearing Trees as recorded in Ren. #103 by Wenderoth:
12", now 16" W.Fir, now broken stump, S.65°47'E. 17.2 ft., scribe marks visible.
12", now 17" W.Fir, alive, N.67¼°E. 31.2 ft., shows good scar, we do not open.

No trace of I.P. called for, falls in old cat. road.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969

T 28 S	R 7 W
S.W. DLC	51

New BT: 5" D.Fir N. 12° W. 28.3 ft. mkd: S.W. Cl 51 CS BT.
This corner lies on moderate northerly slope at end of old Cat Road.

202

¼ Corner to Section 35 and Section 36.
Found - No trace of Orig. Bearing Trees around this area.
At Prorated Point on Section Line Set for ¼ Corner.
Set - Brass Cap at Cor.Mkd: County Surveyor's Office, 1969

T 28 S	R 7 W
¼ S 35	S 36

New BT's: 22" D.Fir S. 84° W. 22.4 ft. mkd: "¼ S35 CS BT".
13" Myrtle N. 38½° E. 17.5 ft. mkd: "¼ S36 CS BT".
This corner lies 1.3 ft. east of old fence, course N-S & 22.0 ft. south of creek 2.0 ft. wide, course N.60°E.

203

Section Corner to Sections 35 & 36, T28-7 and Secs. 1 & 2, T29-7W.
Found - BT's. as recorded by Cole In C.S. File 6/33; as follows:
14", now 16" Fir, N.72½°E. 17.0 ft. (face) bark scribed "S36 CS BT".
We rescribe: "T28S R7W S36 CS BT".
10", now 13" Fir Stump, S.3½°W. 12.0 ft. (face) bark scribed "S1 CSBT".
10", now 13" Fir Stump, S.65°W. 18.0 ft. (Face) No scribe found, cut off low.
12", now 16" Fir, N.25°W. 16.2 ft. (face) bark scribed "S35 CS BT".
We rescribe "T28S R7W S35 CS BT".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969

T 28 S	R 7 W	S 35	S 36
T 29 S	S 2	S 1	

New BT's: 12" D.Fir S.55°E. 21.9 ft. (center) Mkd: T29S R7W S1 CS BT.
13" D.Fir S.71°W. 77.1 ft. (center) Mkd: T29S R7W S2 CS BT.
The only remains of orig. bearing trees were down & out of place, no scribe.
Fence corner bears N. 15° E. 5.5 ft., fence E & N.