

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

204

$\frac{1}{4}$ Corner to Section 26 and Section 35.
At proportional point on Section Line btwn. sections 26 and 35,
Set - Brass Cap at Cor. Mkd: County Surveyor's T 28 S R 7 W
Office 1969 $\frac{1}{4}$ S 26
S 35

New BT's: 10" D. Fir S. 9° W. 47.3 ft. mkd: " $\frac{1}{4}$ S35 CS BT".
10" Laurel N. 23° E. 6.5 ft. mkd: " $\frac{1}{4}$ S26 CS BT".
There is no evidence of original BT's. Fence Corner bears
N. 50° E. 12.0 ft., fences N.-S.-E. & W.

205

$\frac{1}{4}$ Corner to Section 27 and Section 34.
Found - Orig. 12", now 28" B. Oak, N. 35° W. 13.2 ft., opened and found
good scribing of "BT".
Orig. 20", now 30" B. Oak Windfall & out of place, but has a
good stump hole, S. 41° W. 44.2 ft., shows very little in
way of a face.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 28 S R 7 W
Office 1969 $\frac{1}{4}$ S 27
S 34

New BT's: 11" Madrone N. 88° E. 15.4 ft. mkd: " $\frac{1}{4}$ S27 CS BT".
8" W. Oak S. 55° W. 22.1 ft. mkd: " $\frac{1}{4}$ S34 CS BT".
Note - This $\frac{1}{4}$ corner lies on a steep, west slope.

206

$\frac{1}{4}$ Corner to Section 21 and Section 28.
This corner set from survey at prorated distance.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 28 S R 7 W
Office 1969 $\frac{1}{4}$ S 21
S 28

New BT's: 10" D. Fir N. 78° E. 25.0 ft. mkd: " $\frac{1}{4}$ S21 CS BT".
12" D. Fir S. 63° E. 21.5 ft. mkd: " $\frac{1}{4}$ S28 CS BT".

207

$\frac{1}{4}$ Corner to Section 28 and Section 33.
This corner set from survey at prorated distance.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 28 S R 7 W
Office 1969 $\frac{1}{4}$ S 28
S 33

New BT's: 14" Hemlock S. 52° E. 24.0 ft. mkd: " $\frac{1}{4}$ S33 CS BT".
13" S. Pine N. 72° W. 51.1 ft. mkd: " $\frac{1}{4}$ S28 CS BT".

208

$\frac{1}{4}$ Corner to Section 28 and Section 27.
This corner set from survey at prorated distance.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 28 S R 7 W
Office, 1969 $\frac{1}{4}$ S 28 | S 27 217

New BT's: 17" DbL. Ash(?) N. 9° W. 93.6 ft. mkd: " $\frac{1}{4}$ S28 CS BT".
9" W. Oak (Triple) S. 10° E. 252.0 ft. mkd: " $\frac{1}{4}$ S27 CS BT".

Set Steel Fence Post alongside Brass Cap at Corner.

209

$\frac{1}{4}$ Corner to Section 22 and Section 27.
Set at proportional point on Section Line.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 28 S R 7 W
Office 1969 $\frac{1}{4}$ S 22
S 27

New BT's: 6" W. Oak S. 49° E. 36.7 ft. mkd: " $\frac{1}{4}$ S27 CS BT".
12" Pine N. 42° W. 66.3 ft. mkd: " $\frac{1}{4}$ S22 CS BT".

No trace found of Original BT's. This corner lies North of
Lookingglass Road. By VRT.

210

$\frac{1}{4}$ Corner to Section 10 and 15.
Prorated $\frac{1}{4}$ Corner and Set Brass Cap btwn. section corners.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 28 S R 7 W
Office, 1969 $\frac{1}{4}$ S 10
S 15

New BT's:
9" B. Oak N. 4° W. 8.4 ft. mkd: " $\frac{1}{4}$ S10 CS BT".
11" W. Oak S. 44° E. 5.8 ft. mkd: " $\frac{1}{4}$ S15 CS BT".

Find no trace of Orig. BT's. Corner lies on steep easterly slope of ridge.

James W. Byron, County Surveyor
John M. Powell & Crew
March, 1969
C. S. File No. 54/83

Map M-37-44
A 33-57

RECEIVED AND CORNER NO. #226

J.W. Byron
V. Tracy & Crew
4/8/69
C.S. 54/85