

Douglas County Surveyor's Record of
Government Corners Renewed

T 28 T. S. R 7 1/2 R.W.W.M.

KOIKE-CHAPMAN CO., EUGENE, ORE. 21881

Ronald Geisler
L.S. 1988
For: Champion
International
Nov. 1985-Jan.
1986
M 90 - 79

Section corner for Sec. 6; and Sec. 1 of T.28-8 17
Found - 1924 GLO 3 1/4" brass cap on a 3" I.P. Ren. No. 2
23" rotted fir stump, 3 ft. tall, bears S.12°W., 30.3 ft.
(Rec. 31.0 ft.) No scribing. (1924)
25" rotted fir stump bears S.29°E., 34.3 ft. No scribing. (1924)
New BTs - 8" fir bears S.6 1/2°E., 136.0 ft. scribed T28S R7 1/2 W., S6 BT.
8" fir bears S.31°W., 198.3 ft. scribed T28S R8W S1 BT.

Section corner for Secs. 6 and 7; and Secs. 1 and 12 of T.28-8 18
Found - 1924 GLO 2 1/2" brass cap on a 2" I.P. Ren. No. 3
14" fir, uprooted and down, bears S.19°W., 12.5 ft. No scribing.
(original)
18" fir, now badly splintered stump and downed tree, bears
N.37°E., 23.8 ft. Scribed T28S R7 1/2 W. (1924)
13" incense cedar bears S.49°E., 28.5 ft. Closed face. (1957)
New BTs - 10" cedar bears N.42°W., 16.4 ft. scribed T28S R8W S1 BT.
4" fir bears N.17°E., 10.3 ft. scribed X BT.
8" fir bears S.26°W., 27.4 ft. scribed T28S R8W S12 BT.

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
August 7, 1989
C.S. 64/1

Intersecting Range Lines, Section 30, T.28-7 1/2 19
Found - A 1924 3 3/8" dia. GLO brass cap on a 3" O.D. iron pipe, protruding
8" above bottom of a 10 ft. dia. x 26" deep hole. BC/IP is 18"
below ground level. (From 1924 GLO resurvey)
A GLO 2 1/2" dia. brass cap on a 1" O.D. iron pipe, Brass cap
stamped "AP2 TR 61 1924" (leaning 0.5 ft. south from plumb) Set
flush with bottom of a 5 ft. dia. x 18" deep hole, bears
N.3°E., 31.98 ft. (Rec. N.1 1/2°E., 31.7 ft. from 1924 M & B
survey of Tract No. 61 T28S R7W) Hole is to be filled up in
near future by property owner.
New Accessories:
A DCSO 5/8" x 30" long I. Rod protruding 7" above ground with an
alum. cap stamped "B01 1989" set in North-South fence line bears
N.37 1/4°E., 101.37 ft.
A DCSO 5/8" x 30" long I. Rod protruding 7" above ground with an
alum. cap stamped "B0 2 1989" set in North-South fence line
bears S.53°E., 96.77 ft.
A DCSO 2 3/8" dia. brass cap on a 1 3/8" iron pipe stamped "NE
DLC 37 1989" bears S.88 1/2°W., 494.74 ft.
Corner lies approx. 80 ft. west of a north-south fence line in a hay field.
Corner is in a hole that is to be filled up in the near future by property
owner.

(See CS file for traverse notes and field notes) 8/7/89