

Douglas County Surveyor's Record of  
Government Corners Renewed

28

T. S.

8

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

(CONTINUED)

Note: All BTs are down, have been uprooted within the last few years. (52 Cont.)  
Scribing found only on the N.W. BT. All check for bearing & distance.  
Set Brass Cap at Corner marked County Surveyor's Office, 1957,  
 $\frac{1}{4}$  S 7 $\frac{1}{8}$  T 28S, R 8W.  
New Bearing Trees: 9 inch Hemlock N 79°W 72.4 feet scribed  $\frac{1}{4}$  S 7 CS BT.  
52 inch Fir S 52°E 71.5 feet, bark scribed  $\frac{1}{4}$  S 8 CS BT.

-----  
 $\frac{1}{4}$  Section Corner to Sections 18 & 17. 53  
Found - Both Original BTs. I open each face. The S.E. BT shows old rotted blaze. The S.W. BT shows good scribing "BT".  
Set Brass Cap at corner marked  $\frac{1}{4}$  S 18|17 T 28S, R 8W, County Surveyor's Office, 1957

-----  
Section Corner to Section 27, 26, 34, & 35. 54  
Found - Original S.E. BT 24 inch Cedar, now 36 inch S14°E 15.2 feet.  
I open & find good scribing "W" evidence of other BTs found but no scribing.  
Set Brass Cap at corner marked  $\frac{27}{34}$ | $\frac{26}{35}$  T 28S, R 8 W, County Surveyor's Office, 1957.  
New Bearing Trees: 12 inch Chinquapin bears N 38°E 20.6 feet scribed S 26 T28S, R8W, CS BT.  
8 inch Laurel bears N 87°E 23.0 feet scribed S 26 T28S R8W CS BT.  
36 inch Cedar (rescribe Original) bears S 14°E 15.2 feet scribed S 35 T 28S, R 8W, CS BT.  
50 inch Fir bears N 74°W 25.2 feet bark scribed S 27 CS T28S, R8W BT.

-----  
 $\frac{1}{4}$  Section Corner to Sections 27 & 34. 55  
Found - Original N.E. BT now 50 inch Fir, bark scribed  $\frac{1}{4}$  S.  
Also found stump hole and parts of old Laurel at record bearing & distance of original S.W. BT.  
Set Brass Cap at corner marked  $\frac{1}{4}$  S 27 T 28S, R8W, County Surveyor's Office, 1957  
 $\frac{34}{34}$   
New Bearing Trees: Rescribed original N.E. BT (Bark scribed) S 27  $\frac{1}{4}$  CS BT  
bears N 30°E 6.0 feet (dist. to center of BT)  
22 inch Cedar S 59°W 60.2 feet  $\frac{1}{4}$  S 34 CS BT.

-----  
 $\frac{1}{4}$  Section Corner to Sections 26 & 27. 56  
Found - Original 12 inch now 20 inch Oak BT S 66°E 85.1 feet. This BT has been opened several years ago. I find good scribing " $\frac{1}{4}$ S". I find base of rotted stump (Oak) at record distance & bearing for N.W. BT.  
Set Brass Cap at corner marked County Surveyor's Office, 1957  $\frac{1}{4}$ S 27|26  
New Bearing Trees: 12 inch Laurel bears N 72°W T 28S, R8W  
12.9 feet scribed  $\frac{1}{4}$  S27 CS BT.  
14 inch R. Fir bears N51°E 9.8 feet scribed  $\frac{1}{4}$ S 26 CS BT.

-----  
Section Corner 34, 35, 3, & 2. 57  
Found - Boyers BT, 1935, 12 inch now 14 inch Fir in good condition, S72°W 50.5 FT.  
None of the original BTs found. ~~See Rev. #25, T. 29-8~~ #198  
Set Brass Cap at corner marked County Surveyor's Office  $\frac{34}{31}$ | $\frac{35}{2}$  T 28S R8W  
1957. T 29S  
New Bearing Trees: 14 inch Fir N 2°W 24.0 ft scribed S34 T 28S R8W CS BT.  
19 inch Fir N17°E 17.2 ft. scribed S35 T28S, R8W, CS BT.  
12 inch Fir S10°E 30.5 ft. scribed S2 T29S, R8W, CS BT.

-----  
 $\frac{1}{4}$  Section Corner to Section 29 & 32. 58  
Found - Both BTs & 1 $\frac{1}{4}$  ft. Iron Rod. See County Road Survey Notes renewed by Frear, 1936. The 10 inch now 18 inch W. Fir checks for bearing & distance S 60°E 2.0ft. shows good face. I do not open. - Rev. No. 36  
The 50 inch R. Fir East 13.0 feet, bark scribed  $\frac{1}{4}$  S BT. I Re-bark-scribe this BT.  $\frac{1}{4}$ S 29S 32 CS BT.

James W. Byron, Deputy County Surveyor  
M. Godfrey  
J. Fee  
July & August, 1957  
C. S. File No. 49/5

Fd. Recd  
12/1/59  
L. ROBERTS  
M 109-38  
2563/102

RE-RENEWED, SEE CORNER NO #198