

Douglas County Surveyor's Record of  
Government Corners Renewed

28 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21851

$\frac{1}{4}$  Corner to Section 23 & 24. *See Reel # 5* 65  
Found - 1 inch iron rod in N. S. fence line. Both BTs as recorded by Boyer, 1936, alive & in good condition. The S. E. BT. not grown over, scribing visible. The S.W. BT. has burned face, not scribing visible. I rescribe this BT.  $\frac{1}{4}$  S. 23, CS. BT. 118  
Both BTs. check for bearing & distance.

----- Aug. 30, 1957 -----

$\frac{1}{4}$  Corner to Sections 19 & 30. 66  
Found - Two snags which I believe were the original BTs. for  $\frac{1}{4}$  Corner. The South 24.4 ft. now 72 inch Fir snag shows real old face & what I believe to be scribe marks, "4. B" BT bark scribed. The N. 35°W., 6.6 ft. Laurel snag shows real old face, center rotted, No scribe marks found. Now 24 inch.  
Bearing Trees check for bearings and distances.

Set Brass cap at corner marked County Surveyor's Office, 1957;  $\frac{1}{4}$  S. 19  
New Bearing Trees: # 209  
12 inch Fir N. 61° E., 13.7 feet scribed  $\frac{1}{4}$  S. 19, CS. BT.  
14 inch Fir S. 62° E., 20.0 feet scribed  $\frac{1}{4}$  S. 30, CS. BT.

----- Aug. 30, 1957 -----

Renew Section Corner To Sections 31, 32, 6, & 5. 67  
Found - Original BT. 15 inch, now 32 inch Fir Stump, N. 32° E., 14.0 feet. I open & find good scribing "B". Also I find parts of face with good scribing of the original 12 inch, now 15 inch Fir, S. 42° E. 8.0 feet. Both BTs. check for record distance & bearing. I can not find the original N. W. BT. and the original S.W. BT is face down uprooted.

Set Brass Cap at Corner: County Surveyor's Office, 1957, Mkd.  $\frac{31}{65}$  T.28S.  
From Which: 24 inch Fir bears S. 56° E., 15.3 feet scribed T. 29S, R. 6W, S. 5, CS. BT.  
7 " Laurel bears S. 34 $\frac{1}{2}$ ° W. 28.8 ft. scribed T. 29S, R. 8W, S. 6, CS. BT.  
6" Chinquapin bears N. 51° W, 37.5 ft. scribed S. 31, CS. BT.  
6" R. Fir bears N. 37 $\frac{1}{2}$ ° E., 54.7 ft. scribed S. 32, CS. BT.

----- Sept. 6, 1957 -----

$\frac{1}{4}$  Corner to Sections 32 & 5. 68  
Found - Both original BTs. 40 inch, now 50 inch Fir S. 40° W. 26 feet shows old scribing " $\frac{1}{4}$ S. BT." (Bark scribed). Also newer scribing " $\frac{1}{4}$ S". I open 5 inch, now 14 inch, W. Fir N. 35° E., 12.5 feet. Good scribing marks "BT". BTs check record bearings & distances.

Set Brass Cap at corner marked:  $\frac{1}{4}$  S.  $\frac{32}{5}$  T. 28S County Surveyor's Office, 1957.  
I rescribe 14 inch W. Fir, which bears N. 35° E., 12.5 feet,  $\frac{1}{4}$  S. 32, CS. BT.

----- Sept 6, 1957 -----

Renew Section Corner 32, 33, 5, & 4. 69  
Found - Original 24 inch, now 32 inch Fir, S. 40° W., 16,5 feet. I open & find good scribing, "S. 5". I also find 15 inch, now 24 inch Fir, N. 15° W., 24.4 feet. Shows old face. I do not open. Checks bearings & distances using old faces for distances.

Set Brass Cap at corner marked: County Surveyor's Office, 1957,  $\frac{32}{54}$  T. 29S  
New Bearing Trees: Rescribe (Bark). The original N. 15° W., BT. new distance, 29.4 feet, T. 28S., R. 8W., S. 32, CS. BT.

Bark Scribe 48 inch R. Fir, N. 7° E., 14.0 feet T. 28S, R. 8W, S. 33, CS. BT.

Blaze & Scribe 9 inch Cedar S. 9° E., 17.6 ft., T. 29S, R. 8W., S. 4, CS. BT.

The original S.W. BT. is in good condition.

----- Sept. 9, 1957 -----

Renew Section Corner to Section 29, 28, 32, & 33. 70  
Found - All four original BTs. All BTs. except N. E. BT. show good bark scribing. All check for bearing & distance.  
The N.W. BT. now 36 inch Fir stump.  
The S.W. BT. now 24 inch snag.  
The N.E. BT. now 40 inch stump, shows old face I do not open.  
The S.E. BT. now 30 inch Fir, dead.

Set Brass Cap at corner marked County Surveyor's Office, 1957;

S.  $\frac{29}{32}$  T. 28S., R. 8W.  
S.  $\frac{32}{33}$

New Bearing Trees: (continued over)

James W. Byron, Deputy Co. Surveyor  
M. Godfrey  
Sept. 1957  
C. S. File No. 49/12

*File Used 12/1/69  
L. Roberts  
M 109-28  
CS 63/102*