

Douglas County Surveyor's Record of
Government Corners Renewed

28

T. S.

8

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(cont'd) 14 inch W. Fir N. 78°E., 4.6 feet scribed, T.28S, R.8W., S.28, CS. BT.
12 inch Cedar East 39.0 feet scribed T.28S., R.8W., S.33, CS. BT.
18 inch W. Fir, S. 21½°W., 19.9 Feet scribed T.28S., R.8W., S.32, CS. BT.
10 inch W. Fir, N. 36½°W., 44.0 feet scribed T.28S., R.8W., S.29, CS. BT.
Sept 9, 1957

R.9W R.8W.

Renew Township Corner Sections $\frac{36}{1} | \frac{31}{26}$ T.28S.
T.29S.

71

Found - ¾ inch iron pipe at corner & one original BT., 15 inch now 24 inch rotted stump N. 86½°W., 23.8 feet. Good scribing on chip of old face. This corner renewed by C.A.S. (Coos Head Tbr. Co.), Aug. 1956, per notes on yellow tag.

Original BT checks bearing & distance to ¾ inch iron pipe. I find these BTs. (Scribed, 1956)

7 inch R. Fir S. 8°W., 22.8 feet scribed BT., S.31, T.29S., R.9W.

6 inch R. Fir N. 76½°E., 21.0 feet scribed BT. S.31, R.8W., T.28S.

24 inch Cedar N. 3°E., 86.9 Feet scribed BT., S.31, T.28S., R.8W.

Sept 10, 1957

R.9W R.8W.

¼ Corner of Section 36/31

72

Found - 1 inch axle with hus at corner & both original BTs.

The 40 inch now 50 inch Fir N. 20°W., 11.9 feet uprooted. I open old scar at base & find good scribing "B".

The original N.E. BT. has just a part of shell of old stump left. Shows Burl facing Corner. Both BTs. check for bearing & distance.

Find - 26 inch Cedar S. 42½° E., 43.6 feet scribed ¼ S. CS. BT. REN. #7

14 inch W. Fir, S. 38° W., 33.4 feet shows face, may be BT.

New BT.: 5 inch W. Fir S. 61½° W., 24.3 feet. I scribe ¼ S. 36, DCS. BT.

Note: This corner renewed about 10 or 15 years ago. Probably renewed by Coos Co. Surveyor.

Sept. 10, 1957

Section Corner to Sections 33, 34, 4, & 3.

73

Found - Original 20 inch now 36 inch R. Fir N. 78°E., 37.6 feet BT. - Good bark scribing "T.28S., R.8W., S.34", shows good scar near base, I do not open.

Find 20 inch Laurel S. 4°W., 113.5 feet, now down, may be original BT., scribing not found.

Find 18 inch Laurel S. 80°E., 37.0 feet, shows old & rotted face. I believe this to be original. #155

Set Brass Cap at corner marked: County Surveyor's Office, 1957,

S. $\frac{33}{43} | \frac{34}{3}$ T. 28 S. R. 8 W.
T. 29 S.

New Bearing Trees: 15 inch W. Fir S. 59°E. 18.6 feet scribed T29S, R8W. S3 CS BT.

15 inch R. Fir S. 16°W. 18.8 ft. scribed T29S, R8W. S.4 CS BT.

22 inch R. Fir N. 73°W. 47.6 ft. scribed T29S, R8W. S.33 CS BT.

Note - BT. bark scribed.

Sept. 19, 1957

Section Corner to Section 3, 2, 10, & 11.

74

Found - Original N. E. & S. E. BTs.

The original 20 inch now 28 inch Fir N. 81°E., 25.7 feet, BT is now uprooted, shows good bark scribing "T28S., R8W., S.2 BT".

The original 6 inch now 12 inch short snag show "S B" scribe marks negative. BTs. check for bearing & distance.

Set Brass Cap at corner marked: S $\frac{3}{10} | \frac{2}{11}$ T.28S, R.8W., County Surveyor's Office, 1957.

New BTs.: 12 inch Cedar bears S. 46°E., 21.5 feet scribed T.28S, R.8W. S.11 CS BT.

6 inch Cedar bears N. 43°E., 51.5 ft. scribed T.28S, R.8W. S.2 CS BT.

Found: 38 inch R. Fir N. 5°E., 54.0 feet bark scribed T.28, R.8 S.3 CS BT. I change S. 3 to S.2.

12 inch Cedar bears S. 78°W., shows good scribing partly grown over. I add blaze & scribe CS.

30 inch R. Fir bears S. 21°E., 47.0 feet scribed T.28S., R.8W., S.11 CS BT (Bark Scribed).
Sept. 24, 1957

¼ Section Corner to Sections 26 & 35.

75

Found - Original 40 inch now 20 inch R. Fir N. 79°W., 11.2 feet BT. Bark scribed "½ S" above. I open old face at base & find good scribing "BT". I can find no trace of the original S. E. BT.

James W. Byron, Dep. Co. Surveyor
M. Godfrey
Sept. 10, 1957
C. S. File No. 49/12

James W. Byron, Dep. Co. Surveyor
M. Godfrey
S. Blouw
Sept. 1957
C. S. File No. 49/5