

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO. EUGENE, ORE. 21881

(CONTINUED)

Set Brass Cap at Corner marked $\frac{1}{4}$ S 26 T.28S., R.8W., County Surveyor's Office, 1957. (75 Cont.)

New BTs: Rescribe (Bark) original N.79°W. 11.2 feet, scribed BT only.
Blaze & scribe 7 inch Cedar S.4°W., 19.7 ft. Scribed $\frac{1}{4}$ S.35 CS BT.

$\frac{1}{4}$ Section Corner to Sections 10 & 11. 76

Found - Eppsteins renewed BT., now 34 inch B. Oak, N.26°W., 73.0 feet.

I open & find good scribing "BT". Original BTs now gone. - *REN. #40*

Set Brass Cap at corner marked: $\frac{1}{4}$ S 10/S11 T.28S., R.8W. County Surveyor's Office, 1957.

New BTs.: I rescribe 34 inch B. Oak N.26°W., 73.0"BT" only.

Blaze & scribe 7 inch R.Fir N.27°E., 107.6 ft. $\frac{1}{4}$ S. 11 CS BT.

Brass Cap in Fence Corner as shown in sketch in file. Sept. 24, 1957

$\frac{1}{4}$ Section Corner to Sections 33 & 4. 77

Found - Fir tree, now 48 inch diam. N.40°E., 2.6 ft. showing bark scribe, " $\frac{1}{4}$ S". Very plain & scar of bwer blaze.

Fir stump, now 48 inch diam. S.65°W., 19.8 feet. Chop out blaze & find scribe mark "B". Did not chop out low enough to find more.

Distances are from face of old blazes.

Set Brass Cap at corner marked: $\frac{1}{4}$ S. 33 T.28S. County Surveyor's Office, 1957.
S. 4 T.29S.

Northeast Tree in very good condition.

Mark one new tree:

10 inch R.Cedar bears S.38°E., 37.1 ft. (scribed "T29S.R8W. $\frac{1}{4}$ S.4 CS BT.

Corner lies in bottom of gulch approximately 40 ft. West of small creek. 141

Sept. 17, 1957

Section Corner common to Sections 14, 15, 22, & 23. 78

Found - What I believe to be the original N.W. BT. Shows old faces. I open and find center completely rotted, no scribing found. I retrace by compass & pacing line to North checks calls. All other original BTs. gone. Corner in Field.

Set Brass Cap 14 inch above ground marked: S 15/S14 T.28S, R.8W. County Surveyor's Office 1957
S 22/S23

New Bearing Trees:

40 inch W. Oak bears N.53°W., 129.5 feet scribed S 15, T.28S, R.8W. CS BT

32 inch B. Walnut N.78°E., 474.8 ft. scribed S.14, T.28S, R.8W, CS BT.

32 inch B. Oak bears S.37 $\frac{1}{2}$ °E., 272.0 ft. scribed S23, T28S, R8W, CS BT.

30 inch R. Fir bears S.23°W., 352.8 ft. scribed S.22, T.28S, R.8W, CS BT.

(See signed statement in file by Charles Wilson) Sept. 30, 1957

S. E. Corner to D.L.C. 40. 79

Found - $\frac{3}{4}$ inch Iron Pipe at corner and original 30 inch now 40 inch W. Oak, N.60°W., 40.9 feet BT. Upper old face open and rotted. Not scribing found, I open lower face & find definite scribe marks.

Set Brass Cap at corner and alongside $\frac{3}{4}$ inch Iron Pipe, Mark cap: County Surveyor's Office, 1957, S.E. Corner D.L.C. 40, T.28S., R.8W.

New Bearing Trees:

18 inch R. Fir bears S.41°E., 11.0 feet scribed S.E. CL 40, CS BT.

14 inch W. Fir bears N.81°W., 25.0 feet scribed S.E. CL 40, CS BT.

Sept. 30, 1957

Section Corner Common to 8, 9, 16, & 17. 80

Found - All four original BTs.

50 inch now 60 inch R.Fir S.62°E., 10.6 ft. bark scribed, fair condtn.

16 in. now 32 in. Hemlock N.45 $\frac{1}{2}$ °W., 20.5 ft. is now open, scribing visible "BT".

S.69°W (recorded S.69°E.) BT shows good face. I do not open.

N.16 $\frac{1}{2}$ °E. BT shows good face. I do not open. All BTs. check for bearing & distance except S.E. BT should be S.69°W.

Set Brass Cap at corner marked: S8/S9 T.28S., R. 8 W., County Surveyor's Office, 1957
S17/S16

I reblaze & rescribe all original Bearing Tree.

60 inch R.Fir S.62°E., 12.3 ft. (measured to center of tree). Bark Scribe low near ground, S.16, T.28S., R.8W., CS BT.

18 inch Hemlock S.69°W., 16.5 feet scribed S.17, T.28S., R.8W., CS BT.

(continued over)

James W. Byron
M. Godfrey
S. Bilow
Sept. 1957
C. S. File No. 49/5

James W. Byron, Deputy County Surveyor
M. Godfrey
S. Bilow
Sept. 30, 1957
C. S. File No. 49/5

FD OK
3/9/57 M 111-70

RE-RENEWED SEE CORNER NO #205

FD OK
12/92
By Bentz
M 116-57