

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91801

85

James W. Byron, Dep. C. Surveyor
M. Godfrey
J. Fee
Aug. 16, 1957
C. S. File No. 49/120

1962
BLM
NOTES IN FILE

Section Corner to Sections 24, 19, 25, & 30.

Found - Original 8" now 10" Dead Ewewood scribe marks visible N.32°W. 26.4 ft. Also rotted stumps for S.W. & S.E. BTS. check for bearing & distance. I find 40" Fir N.78°E. 20.4 ft. record N.78°W. 20.4 ft. Shows old face near base, I do not open.

Set Brass Cap at corner marked $\frac{S24}{R9W} \frac{S29}{R8W}$ County Surveyor's Office, 1957

New BTs.: 48" Hemlock N.85°W. 21.0 ft. scribed T28S R9W S24 DCS BT.

12" Hemlock N.45½°E. 39.1 ft. scribed T28S R8W S19 DCS BT.

7" Hemlock S59°W. 9.8 ft. scribed T28S R9W S25 DCS BT.

10" Hemlock S.79°E. 17.1 ft. scribed T28S R8W S30 DCS BT.

2 NEW BTs: 10" HEMLOCK S.12½°W. 30½ Lks. MKD. T28S R9W S25 BT = 13" HEMLOCK N.32°W. 138 Lks. MKD. T28S R9W S24 BT.

(ADD
BLM
1962
TO
B.C.)

86

Section Corner to Sections 16, 17, 20, & 21.

Found - Original 24" Fir now 40" N.40°W. 27.1 ft. Bark scribed S17 R8W.

Original 20" now 36" Fir 30.4 ft. Bark Scribed.

The S.E. & N.E. Original BTs. not found.

Set Brass Cap at corner marked $\frac{17}{20} \frac{16}{21}$ T28S R8W County Surveyor's Office, 1957.

New BTs: 14" W. Fir bears S.45°E. 11.0 ft. scribed S21 T28S R8W CS BT.

16" Cedar bears N35½°E. 39.0 ft. scribed S16 T28S R8W CS BT.

¼ Section Corner to Sections 1 and 2.

Unable to find any evidence of the Original corner.

Set an iron pipe 3 ft. long 1½" diam. 28" in the ground,

mkd. RS404, from which:

8" W. Oak bears S.19½°E. 145 lks. dist. mkd. ¼ S1 RS404 BT

8" W. Oak bears S. 2½°W. 245 lks. dist. mkd. ¼ S2 RS404 BT.

- Ed. OK 3/25 - V. M. LINDA M55-57

Section Corner to Sections 1 and 2 only.

Determined from the only extant orig. B.T.

16" Maple bears S.75°W. 65 lks. dist., down with partial scribe marks.

Set Iron Pipe 3 ft. long 1½" diam., 18" in the ground, mkd: 95

RS404, with mound of stone to top from which:

38" D. Fir bears S.40½°E. 87 lks. dist., mkd. T28S R8W S1 RS404 BT.

14" D. Fir bears S.51°W. 154 lks. " , mkd. T28S R8W S2 RS404 BT.

88

¼ Section Corner to Sections 1 and 12.

Determined from the Orig. BT's:

D. Fir Stump, 44", bears N.49°E. 38 lks. mkd. B with other mkds. burned out.

36" Chincupin bears S.27°W. 23 lks. dist. with axe face, mkd. decayed.

Set Iron Pipe 3' long 1½" diam. 28" in the ground mkd. RS404 from which:

New Bearing Trees: 8" W. Fir bears N.55°E. 15 lks. dist.,

mkd. ¼ S1 RS404 BT.

10" D. Fir bears S.57°E. 18 lks. dist.,

mkd. ¼ S12 RS404 BT.

89

Center ¼ Section Corner. - SECTION 1

At intersection with the East & West center line.

Set an Iron Pipe 3 ft. long 1½" diam., 28" in the ground, mkd. RS404, from which: #159

14" W. Fir bears N.16°E. 300 lks. dist. mkd. C¼ S1 RS404 BT.

8" D. Fir bears S.83°E. 239 lks. dist. mkd. C¼ S1 RS404 BT.

6" W. Fir bears S.77½°W. 182 lks. dist. mkd. C¼ S1 RS404 BT.

10" W. Fir bears N.42½°W. 277 lks. dist. mkd. C¼ S1 RS404 BT.

90

¼ Section Corner on North Boundary of Section 1.

Orig. BT's: A White Oak 30" diam., bears N.87°E. 391 lks. dist.,

with BT scar decayed. I open top bear & find axe face, mks. decayed.

A Black Oak, 44" diam., bears S.26°E. 339 lks. dist., down & charred

by slash fire.

Set Iron Pipe 3' long 1½" diam., 28" in the Gr. mkd. RS404, from which:

18" Cedar bears S.78°E. 70 lks. dist. mkd. ¼ S1 RS404 BT.

38" Cedar bears S.36°W. 87 lks. dist. mkd. ¼ S1 RS404 BT.

91

- Ed. OK 3/25 - V. M. LINDA M55-57

Marvin C. Ramsey
For: J. H. Baxter & Co.
Filed: January 26, 1960
C. S. File No. 51/65

RE-RENEWED, SEE CORNER NO. #188 87

RE-RENEWED, SEE CORNER NO. 127

RE-RENEWED, SEE CORNER NO. #159

RE-RENEWED, SEE CORNER NO. #185