

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 28 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

121

S. W. Corner D. L. C. #41.  
Found -  $\frac{1}{2}$ " Iron Pipe at Corner, See Ren. #18.  
12" D. Fir, now 14", S.  $54^{\circ}$  W. 8.0 ft. scribe visible "W".  
30" Fir Stump N.  $68^{\circ}$  E. 17.0 ft. scribe visible "W" "41".  
New BT: 8" W. Fir N.  $15^{\circ}$  E. 13.3 ft. scribed S W DLC #41 CS BT.  
Note - This corner lies about 60.0 ft. south of creek.

122

N. W. Corner D. L. C. No. 40. FD. OK 12/92 By Benz M116-57  
Found - 24" Locust, now 30", S.  $19^{\circ}$  E. 95.0 ft. faint scribe visible "NW 40"  
No trace of Iron Rod at corner, See Ren. #16.  
Set - at DLC Corner, Iron Bolt with 1" Square Head 20" long.  
Reblazed & Rescribed: 30" Locust S.  $19^{\circ}$  E. 95.0 scribed NW DLC #40 CS BT.  
Note - The Northeast corner of Rodger Iverson's porch bears S.  $68^{\circ}$  W. 189.3 ft.  
This corner is about 6" under ground & 3.6 ft. East of N-S Fence.

123

S. W. Corner D. L. C. No. 40.  
Found -  $\frac{3}{4}$ " Iron Pipe, See Ren. #20.  
8" Cedar, now down, N.  $29^{\circ}$  E. 38.0 ft.  
18" Fir Stump N.  $38^{\circ}$  E. 89.0 ft., part of tree with scribing left,  
New BT's: 10" D. Fir N.  $39^{\circ}$  W. 41.8 ("SW" "C1" visible.)  
ft. scribed SW. DLC #40 CS BT.  
10" D. Fir N.  $4\frac{1}{2}^{\circ}$  E. 51.0 ft. scribed S. W. DLC #40 CS BT.

124

$\frac{1}{4}$  Corner to Sections 15 and 22.  
Found - 22" Chinq., now 22", S.  $38^{\circ}$  W. 8.5 ft. scribing visible.  
6" W. Fir, now 7", N.  $32^{\circ}$  E. 25.3 ft., shows good scar.  
36" Fir Stump S.  $66^{\circ}$  E. 13.6 ft., bark scribed " $\frac{1}{4}$ " BT".  
No trace of Iron Pipe, See Ren. #43.  
Set - Brass Cap at  $\frac{1}{4}$  Corner Mkd: County Surveyor's T28S R8W  
Office, 1966  $\frac{1}{4}$  S 15  
S 22

All Bearing Trees in good condition.

FD. OK 7/93 M117-37 Heimbürger

125

$\frac{1}{4}$  Corner to Sections 28 and 27.  
Found - 18" Cedar, now 39", S.  $1^{\circ}$  E. 15.8 ft., scribe visible "4S".  
4" D. Fir, now 6", S.  $48^{\circ}$  W. 10.0 ft. (See Ren. #114)  
24" Fir Stump, now gone  
Set - Brass Cap at Cor. Mkd: County Surveyor's T28S R8W  
Office, 1966  $\frac{1}{4}$  S28/S27

All BT's. in good condition. Do not mark new trees.

July 6, 1966

126

$\frac{1}{4}$  Corner to Sections 3 and 2.  
Found - Orig. 36" D. Fir Stump N.  $39\frac{1}{2}^{\circ}$  E. 11.9 ft.  
Orig. 30" D. Fir Snag, S.  $37^{\circ}$  W. 13.9 ft., bark scribed,  
faint " $\frac{1}{4}$ " S BT".  
BT's. as recorded in Ren. #114A.  
12" Yew, now 13", N.  $45^{\circ}$  W. 26.0 ft., scribe visible " $\frac{1}{4}$ " S3 BT".  
8" Yew, now 9", N.  $25^{\circ}$  E. 64.7 ft., scribe visible " $\frac{1}{4}$ " S2 BT".  
Set - Brass Cap at Cor. Mkd: County Surveyor's T28S R8W  
Office, 1966  $\frac{1}{4}$  S 3/S 2

All BT's. in good condition.

July 6, 1966

127

$\frac{1}{4}$  Corner to Sections 1 and 12.  
Found -  $1\frac{1}{2}$ " I. Pipe at Corner, See Ren. #89.  
Orig. 36" Chinq., now broken off snag, S.  $27^{\circ}$  W. 15.2 ft.,  
no scribe visible.  
No trace of 44" Fir Stump N.  $49^{\circ}$  E. 25.1 ft.  
10" D. Fir S.  $57^{\circ}$  E. 11.9 ft., healed over face, scribe mks. visible.  
8" W. Fir N.  $55^{\circ}$  E. 9.9 ft. Tree down, scribe visible.  
New BT's: 11" W. Fir N.  $69^{\circ}$  W. 9.8 ft. scribed  $\frac{1}{4}$  S 1 CS BT.  
Note - This corner lies on top of ridge, running east & west. Yellow  
Tag on road 500 ft. west of  $\frac{1}{4}$  corner.

July 1966

FD. OK  
R. Gensler  
11/85 - 11/86  
M 90-79

John M. Powell  
Frank Jones & Joe Brady  
March 1966  
C. S. File No. 52/79