

Douglas County Surveyor's Record of

Government Corners Renewed

T. 28 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21681

133

S. E. Corner D. L. C. No. 37.  
 Found - 1" I.P. & Orig. BT's., see Ren. #33.  
 Orig. 6", now 40" W.Oak, N.10°W. 218.5 ft., chopped open  
 several years ago, now nearly healed over. Do not open.  
 No trace of renewal bearing trees.  
 Set - Brass Cap in place of old pipe Mkd: County Surveyor's T 28 S R 8 W  
 Office, 1969 S.E. Cor. DLC 37  
 New BT's: Orig. 40" W.Oak N.10°W. 218.5 ft. Rescribed "SE DLC 37 CS BT".  
 22" W.Oak S.2°E. 15.5 ft. mkd: "SE DLC 37 CS BT".  
 This corner lies 12.0 ft. south 5° W. of 4 way fence corner and  
 on west line of D.L.C. No. 38.

134

S. W. Corner A.P.2, D.L.C. No. 38.  
 Found - 1924 GLO Brass Cap mkd: /AP2 DLC 38 1924"  
 8", now 10" W.Oak, alive, N.26 3/4° E. 47.5 ft.,  
 Rescribe " S. W. DLC 38 CS BT".  
 30", now 36" Fir, sawed stump, N.53°E. 46.2 ft., shows lower portion  
 of bar blaze, no scribe mark.  
 New BT: 14" D.Fir S. 7° E. 28.0 ft. mkd: "SW DLC 38 CS BT".  
 This corner lies on steep east slope approx. 100 ft. east of top  
 of hill & S.0°53'45"W. 727.99 ft. from the S.E. corner D.L.C. #37.

135

N. W. Corner D. L. C. No. 37, AP2.  
 Found - Unrecorded 1924 GLO Brass Cap mkd: /AP2 DLC37 1924"  
 Orig. 18", now 20" W.Oak stump, S.20°E. 117.5 ft., find axe mark  
 only, no scribe.  
 Unrecorded 14" W.Oak S.38°E. 16.5 ft., shows fair scar.  
 Rescribed "N.W. DLC 37 CS BT".  
 New BT: 10" D.Fir S.75°E. 30.5 ft. mkd: NW DLC 37 CS BT.  
 This corner lies 100 ft. south of small creek, course S.E.

136

N. W. Corner D. L. C. No. 38.  
 Found - 3/4" I.R. alongside 10"x4"x2" Sandstone mkd: "CS L38". (badly  
 Remains of fence corner post S.66°E. 3.0 ft., used as B. O., decayed)  
 5', now 6" Maple, dead, S.62°E. 363.3 ft., we open & find scribe.  
 Set - Brass Cap at Cor.Mkd: County Surveyor's T 28 S R 8 W  
 Office, 1969 N.W. DLC /38  
 Reset stone alongside, & 6' steel fence post alongside.  
 This corner lies 594.62 ft. N.1°38'50"E. from S.E. Cor. DLC 37 on  
 east line of claim 37.  
 New BT: 16" Ash N.57°E. 118.7 ft. mkd: "NW DLC 38 CS BT".

137

S. W. Corner D. L. C. No. 37, AP3.  
 Found - Unrecorded 1924 GLO Brass Cap mkd: " DLC 37 / AP3 1924".  
 Orig. 12", now 16" W.Oak, dead snag, N.14°E. 83.8 ft. (Rec. N.10E)  
 We open & find scribe marks.  
 Unrecorded 11", now 12" D.Fir sawed stump, N.28°E. 25.2 ft.,  
 We open & find scribe marks "C37 BT".  
 New BT's: 14" D.Fir N.31°E. 63.1 ft. mkd: "S.W. DLC 37 CS BT".  
 13" D.Fir N. 4° E. 23.0 ft. mkd: "SW DLC 37 CS BT".  
 This corner lies on easterly slope at old fence corner, course N-E.

FO BRASS CAP  
 BY DAVID R.L.  
 2/86  
 M10024

138

Interior "L" D. L. C. No. 37.  
 Found - Unrecorded 1924 GLO Brass Cap mkd: "DLC 37 / AP 5/  
 Orig. 8", now 26" W.Oak, alive, S.32°W. (Rec. S31W) 24.4 ft.,  
 shows good scar. We do not open. Rescribe "Int. L DLC 37 CS BT".  
 Unrecorded 20" W.Oak, alive, S.53 1/2°W. 48.1 ft., shows good  
 scar. Rescribe "Int. L. DLC 37 CS BT".  
 This corner lies on top of ridge, sloping N.W.  
 The 1/4 corner to sections 25 & 36, Ren. #131, bears S.89°09'40"W. 826.99 ft.

James W. Byron, County Surveyor  
 Vernon "Ray" Tracy and Crew  
 January, 1969  
 C. S. File No. 54/78