

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 28 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

139

$\frac{1}{4}$  Corner to Sec. 34, T28-8W. and Sec. 3, T29-8W.  
At the proportional point midway between Section Corners,  
Set - Brass Cap at Cor. Mkd: County Surveyor's T28S R8W  $\frac{1}{4}$  S  $\frac{34}{3}$   
Office, 1969 T29S S 3  
New BT's: 14" D.Fir N. 72° E. 89.2 ft. mkd: " $\frac{1}{4}$  S34 CS BT".  
12" D.Fir S. 64° E. 65.1 ft. mkd: " $\frac{1}{4}$  S 3 CS BT".  
No trace of original bearing trees. This corner lies betwn. old  
cat logging roads on moderate S.E. slope approx. 400 ft. W. of Muns Creek.

James W. Byron, Co. Surveyor  
Vernon "Ray" Tracy & Crew  
January, 1969 - For Doug. Co.  
C.S. File 54/80 Map M 37 - 25

140

$\frac{1}{4}$  Corner to Sec. 35, T28-8W. and Sec. 2, T29-8W.  
Found no trace of original BT's. At the proportional point midway  
between Section Corners:  
Set - Brass Cap at Cor. Mkd: County Surveyor's T28S R8W  $\frac{1}{4}$  S  $\frac{35}{2}$   
Office, 1969 T29S S 2  
New BT's: 12" D.Fir N. 55° W. 42.5 ft. mkd: " $\frac{1}{4}$  S35 CS BT".  
13" D.Fir S. 60° W. 47.9 ft. mkd: " $\frac{1}{4}$  S 2 CS BT".  
This corner lies 10 ft. east of creek, 2 ft. wide, course S.E.  
curving to south.

141

$\frac{1}{4}$  Corner to Sec. 33, T28-8 and Sec. 4, T29-8W.  
Found - Brass Cap, pulled out when N. E. BT. fell, REN. #77  
48" D.Fir, now down, N.40°E. 2.6 ft., bark scribe visible.  
48" D.Fir Stump S.65°W. 19.8 ft., "B" visible.  
10", now 12" R.Cedar, S.38°E. 37.1 ft., scribe visible.  
Reset - Brass Cap at  $\frac{1}{4}$  Cor., property marked in 1957.  
New BT: 12" R.Fir N.50°W. 11.0 ft. mkd: " $\frac{1}{4}$  S33 CS BT".  
As noted this corner lies about 40 ft. west of small creek.

John M.  
Powell & Crew  
C.S. File  
No.  
54/38

142

$\frac{1}{4}$  Corner to Sections 11 and 14.  
Found - Axle found at  $\frac{1}{4}$  Corner referred to in Ren. #25.  
10", now 12" Laurel, N.53°E. 23.6 ft., shows good scar.  
14", now 24" D.Fir, S.15°E. 49.6 ft., shows good scar.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T28S R8W  
(Set alongside Axle) Office, 1970 S  $\frac{11}{14}$   
Bearing Trees N. N. and Tagged. S 14  
**RE-RENEWED, SEE CORNER NO. #180**  
This corner lies 10 ft. South of E - W Fence Line approx. 60 ft. west of  
County Road.

John M. Powell  
Frank Jones & W. Penley  
C.S. File No. 52/79

3/3/70

143

S. E. Corner D. L. C. No. 41. *FD OK BY Bentz 11/16-57*  
Found - Axle at Corner, See Ren. #15.  
16" Hemlock, now stump, N.25  $\frac{3}{4}$ °W. 55.0 ft., found scribe,  
part of "T".  
12" Hemlock, now snag, N.2  $\frac{1}{2}$ °W. 34.0 ft.  
Fir Stump N.43°W. 89.1 ft., bark scribed "T" visible. REN. #9  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 28 S R 8 W  
(Set alongside Axle) Office S.E. Cor. D.L.C. #41  
1970  
New BT's: 12" Hemlock S.38°W. 7.4 ft. mkd: S.E. DLC 41 CS BT.  
8" W.Fir N.21°W. 52.3 ft. mkd: S.E. DLC 41 CS BT.  
This corner lies 10 ft. south of Creek.

3/3/70

144

$\frac{1}{4}$  Corner on South Side Section 33, T27  $\frac{1}{2}$ -8W.  
Found - 1961 Cad. Brass Cap, properly marked and set.  
9" Chinquapin, alive, N.27°W. 11.9 ft., bark scribed " $\frac{1}{4}$  S33 BT" low  
& bark scribe "BT" 5 ft. high. (Rec. as Oak)  
We Rescribe in wood: " $\frac{1}{4}$  S33 CS BT".  
No trace of N.E. BT. due to cat skid trail.  
New BT: 8" Hemlock N.68°E. 75.4 ft. mkd: " $\frac{1}{4}$  S33 CS BT".  
This corner lies on top of spur, sloping W. & the Stand.  $\frac{1}{4}$  Cor.  
Sec. 4, T28-8W. bears S.89  $\frac{1}{2}$ °W. 27.1 ft.

5/18/70