

Douglas County Surveyor's Record of  
Government Corners Renewed

T 28 T. S. R 8 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 31891

165

1/4 Corner for Secs. 23 and 26.  
Set - Brass cap in 1973. Ren. #156  
Re-established - July 1975  
9" W. Fir bears S.50°W., 17.3 ft.  
6" W. Fir bears N.65°W., 8.9 ft.

Glenn Baughman  
For: Larry Thomas  
Revised map.  
April 1978  
M 70 - 6

4/78

166

Section corner for Secs. 2, 1, 11 and 12.  
Found - A 1 1/2" I.P. firmly set and approx. 10" high, attached  
brass cap is marked "County Surveyor Office" T 28 S R 8 W  
2 1 1 12 Cor Secs. 1956. Ren. #28  
Orig. 30" Fir now a decayed stump bears S.78°W., 18.5 ft. Find #176  
frag. scribing "BT".  
A Fir, 14" now 18", bears N.24°W., 6.8 ft. Tree has well healed  
double blaze.  
A 14" Fir, now an 18" stump bears S.76°E., 13.3 ft. Has well  
healed blaze.  
A 22" now 32" Hemlock stump with partially healed double blaze  
bears S.17 1/2°W., 23.5 ft.  
A Fir, 14" now 20" with well healed double blaze bears N.22 1/2°E.,  
29.0 ft.

WE REMOVE- The 18" Fir stump bearing S.76°E., 13.3 ft. Stump to be used  
as County Fair exhibit.

8/7/78

Center Section corner Sec. 36

Set - 5/8" Iron Rod  
BT - A 6" Fir bears S.82 E., 24.7 feet.  
Note - This corner set by intersection of N - S and E - W mid section  
lines.

167

Herbert L. Northcraft  
For: Max Lockwood  
May 1970  
M 81 - 46  
Survey filed 12-79

5/70

168

1/4 Corner for Secs. 23 and 24.  
Found - Old 24" Oak snag now fallen and rotted. Reverse scribing visible  
"1/4 S23". See Renewals #5 - 65 and 118.  
Set - Brass cap  
New BT's - A 7" Maple bears N.50°W., 51.8 ft. scribed "E 1/4 S23 BT" on a  
double face.  
A 13" Myrtle bears S.4°E., 113.8 ft. scribed "W 1/4 S24 BT  
on a double face.

George Grubb  
For: Carl Hale  
March 1980  
M 83 - 10

3/80

169

1/4 Corner for Secs. 23 and 24.  
Found - A 2 1/2" brass cap on a 1" iron pipe protrudes 13" from ground,  
firmly set, properly marked. Ren. #168. No evidence of  
previous monuments is found. FD. OK 9/93, BAUGHMAN  
Original bearing trees are searched for and not found. M117-63  
From Ren. #5:  
A white oak, 18" now a dead rotted & fallen Oak snag 18" diam.  
and 12 feet long lying with lower end in clearly evident rotted  
root crown. This tree bears S.39 1/2°W., 217.5 ft. & has the  
scribing 1/4 S visible on an opened blaze, possible from re-  
scribing recorded in Ren. #55.  
The other bearing trees from Ren. #5 and #65 are searched for but not found  
Found from Ren. #118:  
The southeast bearing tree (only new tree Ren. #118) has been  
removed by quarry road work.  
From DCSSO corner reference file C.S. 59/30 (now attached to this renewal)  
A 5/8" I.R. protruding 10" from ground and firmly set bears  
N.88°W., 41.5 ft. (Rec. due west, 40 ft.)  
Three more 5/8" I.Rs set in a line running west from above I.R.  
are found as recorded.  
The iron rods set to the southwest are searched for but not found.  
From Ren. #168:  
A 7" Maple now an 8" DBH Maple bears N.54 1/2°W., 51.8 ft. (Rec.  
N.50°W., 51.8 ft.) & is scribed "E 1/4 S23 BT" on a partially  
healed double blaze.  
A 13" Myrtle now a 14" DBH myrtle bears S.06°E., 112.0 ft. (Rec.  
S.4°E., 113.8 ft.) and is scribed "W 1/4 S24" on a partially  
healed double blaze.

Stephen Flause  
Deputy, Doug. Co.  
Surveyors Office  
Karen Mosley  
April 29, 1981  
C.S. 61/19