

Douglas County Surveyor's Record of
Government Corners Renewed

T 28

T. S.

R 8

R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97101

C O N T - - -

Stephen J. Flause
Deputy, Doug. Co.
Surveyors Office
Karen Mosley
April 29, 1981
C.S. 61/19

(1/4 Cor. Secs. 23, 24)

169

Set - Because bearing and distance to fallen Oak from Ren. #5 agree with the record and because this bearing tree was established when evidence of original bearing trees existed, the monument location is accepted. Steep terrain near monument may account for discrepancies from records found with other bearing trees.
Found bearing trees are tagged with new Douglas County Surveyor Office bearing tree tags.

4/29/81

170

Howard Johnstone
For: Rsb. Lmbr. Co.
March 8, 1982
M 91 - 51

Center 1/4 Sec. corner of Sec. 8.

Set - 5/8" x 36" I.R. w/ Alum. Cap marked LS 498.

BTs - 18" fir bears S.19°W., 17.3-ft. (scribed).

18" fir bears S.74°W., 21.0-ft. (scribed).

Note - Brass disc marked PLS 498 nailed to the BTs faces.

3/8/82

171

1/4 Corner for Sections 6; and Sec. 1 of T.28-9

Found - A 12" Chinquapin bears S.70°E., 36 links (orig. rec. 56 links) now a rotting snag with scribing clearly visible inside.

A 12" Chinquapin bears S.85°W., 23 links scribing visible but very badly rotting log on the ground. (orig. Rec. 25 links.)

New BT's - 7" fir bears N.4°E., 9.1 ft. marked "1/4 S BT."

8" fir bears S.89°30'W., 4.2 ft. marked "1/4 S BT."

These trees also have a PK nail in them at the blaze with the letter W on them, & each BT is painted red, has a BLM tag attached, a Weyerhaeuser tag attached & are also ribboned. A third Weyerhaeuser marked tree has been cut down and was a 10" hemlock bearing N.57°E., 39.0 ft. with tag & PK nail.

3/23/82

Floyd Vandervelden
Burnt Mountain Eng.
BLM AS 1047
March 1982
C.S. 61/33

1/4 Corner for Sections 6 and 7.

Found - Original fir bearing tree had fallen down and the bole subsequently logged.

The two new bearing trees that Byron marked were in poor shape because the chinquapin rotted completely away & the blazes and marks on the yew tree were burned out due to the slash fire.

1957 County Brass cap Ren. #50

New BT's - A 16" yew bears S.49°E., 20.2 ft. marked 1/4 S BT using old burned out blazes.

A 14" chinquapin bears N.32°15'W., 34.0 ft. marked 1/4 S BT.

Trees are painted red and marked with BLM BT tags.

3/23/82

173

1/4 Corner for Sections 6 and 7

Found - 1957 County brass cap properly mkd. firmly set and protruding 2" out of ground. Ren. #50

Orig. 32" now 40" fir which had fallen over and later logged.

Root hole bears N.8°E., 21.1 ft. previously opened face was burned over and had no scribing visible.

16" yew now 16" snag approx. 30 ft. tall with burned out double blaze. Scribed "1/4 S BT" visible. Tree bears S.49°E., 20.2 ft. Ren. #50 and #172

8" chinquapin now 8" rotted stump with the remainder of the tree lying alongside also rotted, with scribed "4 S6 CS BT" visible in partially healed double blaze bears N.30°W., 9.7 ft. (Rec. N.27 1/2°W.) Ren. #50

14" chinquapin scribed "1/4 S BT" bears N.32°15'W., 34.0 ft. Ren. #172

New BT's - 19" chinquapin scribed "1/4 S7 CS BT" in double blaze bears S.89°W. 107.6 ft.

14" fir scribed "1/4 S6 CS BT" in double blaze bears N.84 1/2°E., 84.4 ft.

4/22/82

Gregory Quibell,
Deputy, Doug. Co.
Surveyors Office
Karen Reed; Terry
Plouff; John
Powell
April 22, 1982
C.S. 61/30