

Douglas County Surveyor's Record of
Government Corners Renewed

T.28 T.S. R.8 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
August 5, 1992
C.S. 64/31

1/4 Corner for Section 31 & Section 6 of T.29-8. 206
Found - 3 1/2" B.L.M. Brass cap (1964 properly marked) on a 2 1/2" O.D. iron pipe protruding 3" above ground.

Accessories Found -
6" now 17" dia D. fir with a fully healed single blaze, bears S.50 3/4°W., 109.4 ft.
16" now 24" dia. D fir with a fully healed blaze bears N.50 3/4°E., 88.4 ft. (rec. N.49 3/4°E., 88.4 ft. 1964 BLM)
3/4" O.D. iron pipe flush with ground, bears S.63/4°E., 6.6 ft. (agrees with record)(C.S.23/47?) Remnants of old fence from west coming into I.P.
No original B.T.s found.
Iron bar 6 ft. west of cor. (C.S. 23/47) not found.

New Accessories -
8" dia. W. Fir double blazed and scribed "1/4 S6 CSBT" bears S.72°E., 41.0 ft. 8/6/92

NE Corner D.L.C. No. 40 207

Set- 5/8" X 30" iron rod w/cap Marked "i.e. Engineering" with the following accessories:
12" Douglas Fir S 40° 30' 00" E 7.33'. Blazed & painted with PK nail in the center of the blaze.
14" Douglas Fir N 32° 00' 00" W 6.25'. Blazed & painted with PK nail in the center of the blaze.
24" Douglas Fir S 24° 30' 00" E 8.84'. Blazed & painted with PK nail in the center of the blaze. 12/92

1/4 Corner for Sections 30 & 31. 208

Found - 3 1/4" Brass Cap on a 2" iron pipe properly marked from which:
22" D.Fir (rec. 10"), face overgrown, bears N.61 1/2°W., 18.8'
12" D.Fir (rec. 9"), face overgrown, bears S.8 1/4°W., 38.6'

New Accessories -
10" D.Fir, bears S26°W., 6.4 ft. Scribed "1/4 S31 BT"
16" D.Fir, bears N.12 1/2°E., 63.1 ft. Scribed "1/4 S30 BT"

Note - Corner is N.60°W. ± 500 ft. from where logging road crosses live stream.

1/4 Corner for Sections 19 & 30. 209 See renewal # 66

Found - 2 1/2" Brass Cap properly marked on a 1" iron pipe from which:
20" W.Fir, (rec. 12") face overgrown, bears N.61°E., 13.7'.
24" W.Fir, (rec. 14") face overgrown, bears S.62°E., 20.0'.
72" D.Fir snag, no face or marks now visible, bears South 24.4' to face.
Laurel snag Orig BT. N.35°W., 6.6 ft. now gone.

New Accessories -
12" W.Fir, bears S.28°W., 28.3 ft. Scribed "1/4 S30 BT"
8" W.Fir, bears N.3°W., 10.8 ft. Scribed "1/4 S19 BT"

Note - Corner is N.30°E., ± 500 ft. from end of old logging road to the west.

1/4 Corner for Sections 30 & 29. 210 See renewal # 161

Found - 5/8" x 34" Iron Rod w/plastic cap, from which:
18" D.Fir stump (rec. 16") scribes "BT" visible bears N.84°E., 18.5 ft. (rec. N.79°E.)
16" Madrone (rec. 14") scribes "1/4" visible bears N.75°W., 28.8 ft. (rec. N.81°W.)

Set - 2 1/2" Brass Cap mounted on a 1" x 30" iron pipe in place of the 5/8" iron rod & then placed iron rod alongside Brass Cap. Brass Cap marked: SHANER ENGR

1/4 S
S 30 | S 29
T28S R8W WM
RLS 430 1993

New Accessories -
6" D.Fir, bears N.80°E., 4.6 ft. scribed "1/4 S29 BT"
14" Cedar, Bears N.62°E., 13.8 ft. scribed "1/4 S29 BT"
8" W.Fir bears S.60°W., 8.0 ft. scribed "1/4 S30 BT"

Note - Corner is approx 1000 ft. west of logging road.

Bruce Shaner
For: Superior Lumber Co
June 1993
M 112-78; C S. 63/153

Don Bentz
For: Richard Willis
December 1992
M 116 - 57