

Douglas County Surveyor's Record of  
Government Corners Renewed

29 T. S. 1 R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21001

John H. Markham, Jr.  
For Stomar Lbr. Co.  
Wit. J.R. Markhm  
August 1, 1960  
C.S. File No. 51/121

T29S  
Section Corner  $\frac{S31}{S6} | \frac{S32}{S5}$  RLW

T30S  
22" W. Fir S.38°E. 32.9 ft. O. B.T.  
30" Laurel bears N.88°E. 36.3 ft., O.B.T., I rescribed  
S32 T29S RLW BT.  
24" Fir Stump, logged, N.61°W. 25.1 ft., O.B.T.  
At Corner Point found Stone & Set 1" x 30" I. B. from which:  
8" W. Oak bears N.85°W. 9.6 ft. dist. mkd. S31 RLW BT.  
10" W. Fir bears S.11°W. 19.3 ft. mkd. S6 RLW BT.

1  
97

James W. Byron, Deputy  
Dale McFarland & John Powell  
May 28, 1962  
C. S. File No. 52/121

$\frac{1}{4}$  Corner to Sections 9 and 10.  
Found - Brass Cap at corner.  
Orig. 48", now 40" Fir Snag S.29°W. 5.0 ft., not 40.9 ft.,  
shows old axe work, no scribing found.  
Orig. N. E. BT. not found.  
Note - This corner in old burn area & lies at top bank and on  
East side of Dumont Creek.  
New BT's: 14" R.Fir bears S.19°E. 43.4 ft. scribed  $\frac{1}{4}$  S10 CS BT.  
4" R.Fir bears N.44°E. 10.5 ft. scribed  $\frac{1}{4}$  S 9 CS BT.

2

Section Corner to Sections 9 - 10 - 15 - 16.  
Found - All Original Bearing Trees except S.W. BT. We do not open.  
Stone at corner as recorded. BT's. show good scars.  
Set - Brass Cap alongside Corner Stone & Mkd:  $\frac{S9}{S16} | \frac{S10}{S15}$  T29S RLW  
County Surveyor's Office, 1962 # 38 & 39  
New BT's: 15" R.Fir bears S.22°W. 15.0 ft. scribed S16 T29S RLW CS BT.  
14" R.Fir bears N.62°E. 32.0 ft. scribed S10 T29S RLW CS BT.

3

John H.  
Markham, Jr.  
For: Stomar Lbr.  
Aug. 1, 1960  
C.S. File  
No. 51/121

North  $\frac{1}{4}$  Corner to Section 6, T30-1W. as det. by Old BT'S:  
30" Fir Stump, logged, bears N.70°W. 21.8 ft. O.B.T.  
30" Fir Stump, logged, bears S.88°E. 31.8 ft. O.B.T.  
At Corner Point, Set 1" x 30" Iron Rod from which:  
15" Sugar Pine S.15°W. 9.0 ft. Mkd:  $\frac{1}{4}$  S6 BT.  
12" Fir bears N.75°W. 19.0 ft. mkd:  $\frac{1}{4}$  S31 BT.  
8" Fir bears N. 4°E. 17.4 ft. mkd:  $\frac{1}{4}$  S31 BT.  
14" Alder  $\frac{1}{4}$  S.67°E. 7.5 ft. Mkd:  $\frac{1}{4}$  S 6 BT.

4  
98

MICROFILM TO HERE 10/67

John M. Powell  
Frank Jones & W. Penley  
December, 1967  
C. S. File No. 54/59

Sec. Cor. to Secs. 32 & 33, T29-1W. and Secs. 4 & 5, T30-1W.  
Found - 20x12x10 Stone mkd: 4 notches on west side & 2 notches on east.  
Orig. 8", now 0" W.Oak, N.38°E. 47.5 ft., opened for scribe.  
Orig. 12", now down D.Fir, S28°W. 17.8 ft., opened for scribe.  
Orig. 20", now 24" D.Fir, S.55°E. 5.3 ft., shows good scar.  
Orig. 10", now 15" D.Fir, N.81°W. 35.0 ft., shows good scar.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 1 W  
Office S 32 | S 33  
1967 S 5 | S 4  
New BT's: 16" D.Fir S. 62° W. 41.4 ft. mkd. T30S RLW S5 CS BT.  
8" S.Fir N. 16° E. 29.6 ft. mkd. T29S RLW S33 CS BT.

5

Township Corner: R T29S R  
2 S 36 | S 31 1 Found Brass Cap as Marked.  
W S 1 | S 6 W General Land Office, 1917.  
T30S 1917

Found - Orig. 30" Pine, now down & burnt, S. 8° W. 24.2 ft.  
Orig. 18" Oak, now rotted out, N. 70° W. 37.0 ft.  
Orig. 18" Oak, now stob, N. 8° E. 47.5 ft.  
Org. 12", now 17" Oak S. 49°E. 11.8 ft., opened for Scribe "BT".  
(Fell this tree as very rotten & would be a hazard)

New BT's: 16" D.Fir N. 45° W. 28.8 ft. mkd. T29S RLW S36 CS BT.  
15" D.Fir N. 75° E. 17.5 ft. mkd. T29S RLW S31 CS BT.  
Reblzd. & Resorbd: 16" D.Fir S.9°E. (Record S.12°E) 13.0 ft. mkd. T30S RLWS6CSBT.  
1904 BT's: 10" D.Fir S.41°W. (Recd. S.39°W.) 33.0 ft. mkd. T30SR2W S1CSBT.  
Jan. 15, 1968

6

RE-RENEWED CORNER NO. #132