

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 29S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

$\frac{1}{4}$  Corner to Section 30 only  
Found - 2 bearing in excellent condition. No trace of basalt stone  
20X6X6  
10" S. Pine, now 16", N 45°E 19.8 Ft. Shows good scar and is good  
for bearing and dist.  
6" R Fir, now 10", S 42°E 25.5 Ft. Shows good scar and is good for  
bearing and dist.

Note: Place yellow tags on both trees.  
Set - Brass cap at bearing and dist. from both Bearing trees. Mkd.  
County Surveyors T 29 S  
Office, 1969  $\frac{1}{4}$  S 30 RLW  
Note: This  $\frac{1}{4}$  S 30 only lies South 33.7 Ft. from  $\frac{1}{4}$  S 25 only on the range  
line of R1, 2W of T 29 S. Plus these corners lie on steep West slope.

4-24-69

Section Corner 25 and 36 T 29 - 2W Only  
Found - a 18x10x7 basalt corner stone properly marked and set at Sec.  
Cor. point.  
10" D Fir, now 16", S 5 $\frac{1}{2}$  W. 13.9 ft. Shows excellent scar and is good  
for bearing and dist.  
6 D. Fir, now 10", N. 17° W. 31.7 Ft. Shows excellent face and is  
good for bearing and dist.

Note: Place yellow tags on both bearing trees.  
Set - Brass cap in place of corner stone Mkd.  
County Surveyors R T 29 S R  
Office, 1969 2 S 25 I  
W S 36 530 W  
Note: Place corner stone by brass cap  
Note: This Sec. Cor of S 25, S 36 lies North 18.5 from Sec. Cor. of  
S 30, S 31 on Range line of R 1, 2 W of T 29 S.

Section Corner 30 and 31 only  
Found: A 15x10x6 basalt corner stone, properly Mkd, and set a Sec. Cor.  
point.  
16" R Fir, now 28", N 80°E 46.2 Ft. Has open face and scribe of  
(W, S, 3,)  
12 R Fir, now 20", S 66°E 39.6 Ft. has open face shows cribe of  
(T29S R 1 W S 81 Bt)

Note: Place yellow tags on both bearing trees.  
Set - Brass cap in place of corner stone Mkd:  
County Surveyors T 29 S  
Office, 1969 R S 30 R  
2' S 31 1  
W S 31 W  
Note: Place corner stone by brass cap.  
Note: This Sec. Cor. of S 30, S 31 lies South 18.5 from Sec. Cor. of  
T 29 S.

4-24-69

$\frac{1}{4}$  Section Corner 31 Only  
Found - 20" D. Fir, now 25", N 28E 67.3. Scribe Visible  $\frac{1}{4}$  S 31 BT  
36" D. Fir, now 40", East 49.5 Scribe visible  $\frac{1}{4}$  S 31 BT  
No trace of cor. stone  
Set - Brass cap at  $\frac{1}{4}$  cor Mkd:

County Surveyors T 29 S  
Office, 1969 R  $\frac{1}{4}$  R  
2' S 31 I  
W S 31 W

New Bearing trees: 8" D. Fir N 23 $\frac{1}{2}$  E 7.0' Scribed  $\frac{1}{4}$  S 31 C S BT  
6" D. Fir S 42 E 3.9' Scribed  $\frac{1}{4}$  S 31 CS BT  
Note: This cor. lies 23.8 South of  $\frac{1}{4}$  Cor. S 36

4-25-69

JOHN M. POWELL  
Frank Jones & W. Penley  
April & May, 1969  
C. S. File No. 54/82