

Douglas County Surveyor's Record of
Government Corners Renewed

T29

T. S. R 1

R.W.W.M.

ROCKE-CHAPMAN CO., EUGENE, ORE. 21881

Sec. Corner, Secs. 31 & 32, T29-1; Secs. 5 & 6, T30-1
Found - Brass cap mkd. T29S, RLW, S31, W32, T30S, RLW.
S6, S5, RLS 222 1970 Ren. #97
15" x 12" x 6" orig. stone & 1 1/4" x 27" iron
bolt alongside brass cap.
30" org. madrone, blown down, bears N.88°E., 32.9
22" orig. white fir, blown down, bears S.38°E., 32.9 ft.
24" orig. D. Fir, stump, bears N.61°W., 25.1 ft.
12" white fir, scribes visible, bears S.11°W., 18.9 ft.
10" black oak, scribes vis. bears N.85°W., 9.6 ft.
New BT - 6" Douglas fir, scribed T29S, RLW, S32 BT, bears
N.12 1/2°E., 45.8 ft. & nailed a brass washer
to lower face.

112

Bruce A. Shaner
for Umpqua Nat'l
Forest

M 49 - 43
10/23/73

JAN 75

Closing Corner to Secs. 3 and 4
Found: A 2" Iron pipe, leaning slightly in the ground, with
brass cap attached, marked:

113

Gary L Langlitz
Clell E Goodwin
M. Lenora Ladig
6/4/75
C.S. 57/30

U.S. GENERAL LAND OFFICE T 28S RLW S33
SURVEY 1922 S4 | S3

RE-RENEWED, SEE CORNER NO. #150

From which: An Orig. 10" now 22" sugar pine bears S.39°E., 4.6 ft.
alive and well healed and
an orig. 6" chinquapin, now a 7" rotten snag bears
S.42°W., 14.5ft., with some illegible scribing
remaining on a well rotted unhealed face.

We mark a new bearing tree as follows:

A 9" grand Fir bears S.37°W., 5.3 ft., scribed "T29S RLW S4
CC CS BT" on a double blaze Compass Declination 20°E.

114

1/4 Corner of Sec. 33 T28S RLW

Found: A stone, 5" x 16" x 10" above ground, firmly set and
Marked with a chiseled "1/4" on the north face,
From which: An orig. 9" Fir, still 9" in diameter bears N.30°W.,
10.6 ft., alive and well-healed and
an Orig. 15" now 19" fir bears N.14°E., 11.2 ft.,
alive and well-healed.

At the corner point, we set a 1" x 30" Iron pipe with Brass Cap
Attached, Marked: #151

County Surveyors
Office 1975

T 28S RLW
1/4 S33

We placed the original stone alongside the brass cap.
Compass Declination setting 20° East.

115

1/4 Cor. for Secs. 32 and 33.

Found - 1969 County Surveyor B.C. 1" Iron pipe mon., Stone
alongside mkd. "1/4". Ren. #45

10" D. Fir, N.23°E., 4.5 ft.
11" W. Fir, dead, S.46°W., 12.8 ft.

New BT - 17.3" W. Fir, S.60°W., 19.8 ft. "1/4 32 BT".

Charles H. Hurst
For: U.S. Forest
Service

116

1/4 Cor. for Secs. 33 and Sec. 4 of T30-1

Set - 2" x 30" I. Pipe with 3" Brass cap properly stamped and
with PLS 483 marked.

New BT's - 18" Incense cedar, N.6 1/2°E., 64.4 ft. mkd. "1/4
33 BT".

11.2" P. Pine, S.2 1/4°W., 32.9 ft. mkd. "1/4 S 4 BT"

Note - Orig. Cor. not found. Proportionate cor. falls in center
of paved road & is set 6" below surface.

Oct. 20, 1975
M. 58 - 38