

Douglas County Surveyor's Record of
Government Corners Renewed

T 29 T. S. R 1 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

117

Charles H. Hurst
For: U.S. Forest
Service
Oct. 20, 1975
M 58 - 38

Center 1/4 Cor. Sec. 33
Set - 2" x 30" I. pipe with B.C. properly mkd. and with stamp
PLS 483.
New BT's - 8" D.Fir, N.2 1/2° E., 21.9 ft. mkd. "C 1/4 S33 BT"
9.3" D.Fir, S.48 1/4° E., 44.7 ft. mkd. "C 1/4 S33 BT"

3/77

118

Section Corner for Secs. 34 and 35 only.
Found - Stone, 8"x8"x10" above ground surface. Stone is solidly set &
marked with 2 notches on east edge and 4 notches on the west edge.
A 2 1/2" Alum. cap on a 3/4" I.R. is set so the cap is over the
SW edge of the corner stone. The Al. cap, not of record, is
stamped 1967 U.S.P.C. Prop. Cor. RE 4287 34 35 3 RLW. Do not disturb
The orig. 48" now 53" D. Fir bears N.59 1/2°W., 56.8 ft. Has a
healed scar. This tree is almost dead.
Orig. BT to the NE is down & well decayed. Stump hole bears N.58°E.,
12.54 ft.
Bearing trees not of record, as follows:
A 14" D. Fir bears N. 1 1/2°W., 14.5 ft. Has a single healed blaze.
A 23" W. Fir bears N.49°E., 30.7 ft. Some scribing visible on a
nearly healed blaze.
A 6" D. Fir bears S.29 1/2°W., 7.0 ft. scribing visible on a single
blaze "S3 BT T30S RLW".
I placed BT signs on all accessories.

11/17/77

119

Section Corner for Secs. 3 and 2 only, T30-1.
Found - 2 1/2" Alum. cap stamped US.P.C. Prop. Cor. 1967 Do not disturb,
T30S RLW 35 3 2 RE 4287 Ren.#18
Orig. Cedar now a 32" stump bears S.85°E., 38.6 ft. (Rec. 39.4 ft.)
scribing visible "RLW S2 B" on a partly healed blaze.
A 8" D. Fir bears S.56°E., 22.5 ft. Has a single healed blaze.
A 15" D. Fir bears S.27°W., 27.0 ft. (Rec. 27.5 ft. Some scribing
visible on a nearly healed blaze.
A 8" D. Fir bears N.20°W., 42.6 ft. (Rec. 42.95 ft.) Scribing
visible "5 BT T29S RLW". The orig. BT to the SW is gone.
I placed BT signs on all accessories.

11/17/77

120

SE Corner for Sec. 36 only, T28-2.
Found - A 3 1/2" Brass cap on a 3" I.P. wet solidly in ground stamped:
U.S. General Land Office Survey T28S 1922
R2W
S36 S 6
T 29 S R 1 W
A10" orig. 5" D. Fir with a healed blaze bears N.70°W., (Rec. N.73°W.)
2.64 ft. to face & 2.9 ft. to center of tree.
A 24" Cedar, orig. 18", bears N.10°W., 45.54 ft. Has a healed scar.
Condition report only. Did not re-monument.
Placed County BT signs on both trees.

3/16/78

121

West 1/4 Corner for Sec. 6 only.
Found - 2 1/2" brass cap on a 1" I.R. set firmly in the ground with brass
cap flush to surface material. (duff). stamped U.S. General Land
Office Survey 1/4 S6 1922. This is the W 1/4 corn. for sec. 6
only, T29S RLW. I add "T29S RLW" to brass cap on East side of
stamping 1/4 S6.
A 30" Cedar bears S.74°E., 12.9 ft. (Rec. 13.2 ft.) has a healed blaze
A 18" Hemlock bears N.77°E., 27.3 ft. (Rec. 27.06) Has a healed blaze.
Condition report only. Did not re-monument.
Place County BT signs on both trees.

3/16/78

Dennis Gaylord, U.S.F.S.
Deputy - Doug. Co. Surveyors Office
Witness - Randal Lopez
November 17, 1977
C.S. 59/42

Dennis Gaylord
U.S.F.S.
Deputy, Doug.
Co. Surveyors
Office.
March 16, 1978
C.S. 59/46