

Douglas County Surveyor's Record of  
Government Corners Renewed

T 29

T. S.

R 1

R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 97301

147

CONT - -

Jim Landrum, U.S.F.S.  
Deputy, Doug. Co.  
Surveyors Office  
Witness: L. Herzstein  
June 7, 1983  
C.S. 62/10

20" I. Cedar stump, S.38°W., 25.2 ft. with scribe marks "BT" visible on partially healed blaze and a 1 1/2" brass washer stamped "RS 430" nailed to base of blaze.  
16" W. fir, N.51°W., 15.5 ft. with healed double blaze.  
New BT - 12" W. fir, S.51°W., 7.1 ft. scribed "CE 1/16 S31 CS BT" on a single blaze.

6/7/83

148

Maurice E. Farr  
L.S. #1181  
U.S.F.S.  
Leonard Herzstein  
Randy Lopez  
January 21, 1985  
C.S. 62/26

1/4 Corner for Sections 27 and 28  
Found - 1 1/4" outside dia. I.P., firmly set, projecting 15" above ground with County brass cap properly mkd. attached. Ren. 24  
Original stone 18"x10"x8" found lying along-side I.P. with marks "1/4" visible.  
50" S. pine stump N.67°E., 12.9 ft. (rec. 13.2 ft.) with scribe marks "S 4 BT" visible on partially healed blaze. (orig.)  
10" D. fir, N.24°E., 11.4 ft. with healed double blaze. Ren. #24  
11" ponderosa pine snag (rec. Sugar pine) S.27°W., 18.0 ft. with scribe marks "CS" visible on partially healed double blaze. #24  
Add - 3 ft. dia. mound of stone. Iron pipe now projects 6".  
New BT - 16" D. fir, N.27°W., 16.3 ft. scribed "1/4 S28 BT" on a double blaze with a brass washer stamped "LS 1181" nailed flush to lower blaze.  
Corner is 40 ft. east of USFS Rd. #2827. A steel fence post with USFS signs #54-2 and #54-4 bears N.0 3/4°E., 4.0 ft.

1/21/85

149

Loyd R. Moffit  
L.S. #944  
For: U.S.F.S.  
May 1985  
C.S. 63/8

Section corner for Section 2 and 1 only of T.30-1  
Found - 2 1/2" alum. cap on 3/4" iron pipe. Ren. #20  
30" fir bears S.62°W., 17.2 ft. scribe visible.  
48" dead fir bears S.46°E., 20.5 ft. scribe visible.  
40" fir bears N.10°E., 88.9 ft. scribe visible.  
New BT - 10" fir bears S.33°E., 24.1 ft. scribed T30S R1W S1 BT.

5/85

150

Douglas Co. Surveyor  
Office  
Randall Smith  
Stephen Flause  
June 13, 1985  
C.S. 62/28

Closing corner for Sections 3 and 4 only.  
Found - 1922 US GLO brass cap on a 2" I.P. protruding 15" above ground and leaning 10" westerly, properly marked. Ren. #113  
10" dia. now 24" dia. 2 ft. high sugar pine stump with a single well healed blaze bears S.34°E., 5.0 ft. (Rec. S.39°E., 4.6 ft. dist. is to face of blaze.) (Orig.)  
6" dia. now 7" dia. 25 ft. high chinquapin snag with rotted evidence of a blaze bears S.42°W., 14.5 ft. (Dist. is to center of root crown and face of blaze due to leaning growth of tree) (Orig.)  
9" dia. grand fir now a 12" dia. white fir with a double well healed blaze bears S.42 1/2°W., 5.8 ft. (Rec. S.37°W., 5.3 ft. is to cap on leaning monument.)  
Set - Straightened GLO cap on pipe to plumb and surrounded by a 24" dia. 15" tall mound of stone. Because both orig. face measurements and one orig. brg. agree with plumb position we accept plumb position.  
New BT - 28" dia. sugar pine double blazed and scribed "T29S R1W S4 CC CS BT" bears S.70 1/2°W., 50.1 ft.  
Note: From end of USFS Rd. #2813-607 proceed easterly 600 ft.  $\perp$  along ridge and cut line then south below ridge 40 ft.  $\perp$  to corner.

6/13/85

151

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
June 13, 1985  
C.S. 62/28

South 1/4 Corner for Section 33 of T.28-1 only.  
Found - 1975 County brass cap on I.P. firmly set and protruding 8" above ground. Ren. #114  
A stone, from orig. survey, marked 1/4 on North face, protrudes approx 5" from ground at NE edge of brass cap. Portion of stone exposed measures approx. 5 x 13 inches.  
Orig. BT, a fir 12" dia. now a 19" dia. 42" tall fir stump bears N.14°E., 11.2 ft. This tree has a well healed single blaze pointing approx S.54°W.  
Orig. BT, a cedar, 24" dia. now a 36" dia. 15" tall cedar stump, bears S.16°W., 29.7 ft.. Shows signs of 1922 obliteration of original blaze (This is no longer a BT for the S 1/4 of S.33)