

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S. T. S. R. 2 W. R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, OR., 21881

Vernon "Ray" Tracy
Jack Heritage & V. Perron
November, 1969 C.S. File No. 54/96

Corner No. 6, H. E. S. No. 140. 62
Found - Old Corner Stone, in place, mkd: "+" on top & "6 HES 140" on South.
Orig. 10", now 30" Cedar, 15' high snag, S. 63° E. 47.9 ft., shows scar.
Orig. 14", now 25" Fir, alive, N. 62° W. 2.0 ft., shows good scar. We Tag.
Set - Brass Cap at Cor. Mkd: County Surveyor's T. 29 S R 2 W
(Reset Old Cor. Stone Alongside) Office, 1969 Cor. #6 HES 140
New BT's: 12" D. Fir S. 46° W. 6.1 ft. mkd: "6 HES 140 CS BT".
13" Cedar N. 73° E. 7.9 ft. mkd: "6 HES 140 CS BT".
This corner lies on moderate N.W. slope.

End. OK by
HERZSTEIN
9/22/01 C.S. 4/27
11/18/69

Corner #7, H. E. S. No. 140. 63
Found - Old Corner Stone, in place, mkd: "X" on top & "7 HES 140" on South
Orig. 7", now 23" Fir, alive, S. 4° W. 12.2 ft., shows scar, freshen blaze
and tag.
Orig. 7" Fir(?), now 18" Cedar, broken off 40' above ground, N. 73° W. 19.5 ft.,
shows scar, We Tag.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 2 W
(Reset Old Stone Alongside) Office, 1969 Cor. #7 HES 140
New BT: 7" D. Fir N. 62° W. 4.1 ft. mkd: "7 HES 140 CS BT".
This corner lies on moderate southerly slope.

Corner #1, H. E. S. No. 141. 64
Found - Orig. 30", now 36" Fir Corner Tree, alive, shows good scar
on N. W. Side.
Orig. 16", now 18" Fir, alive, S. 55½° W. 7.3 ft., shows very good scar, Tag.
Orig. 12", now 15" Fir, alive, N. 8° W. 25.7 ft., shows good scar, We Tag.
At Base of Corner Tree, 18" due West of Center Set:
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 2 W
Office, 1969 Cor. #1 HES 141
This corner lies on steep westerly slope about 155 ft. E of Deadman Creek.

Corner #2, H. E. S. No. 141. 65
Found - Old Corner Stone, in place, mkd: "+" on top & "2 HES 141" on East.
Orig. 20", now 22" D. Fir, alive, N. 42° E. 16.5 ft., shows very good scar, Tag.
Orig. 15", now 18" W. Fir, alive, S. 14° E. 5.9 ft., shows scar.
We Rescribe "2 HES 141 CS BT".
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 2 W
(Reset Stone Alongside) Office, 1969 Cor. #2 HES 141
This corner lies on top of small spur sloping N. and about 150 ft.
west of Deadman Creek Access Road.

Corner #3, H. E. S. No. 141. 66
Found - Old Corner Stone, in place, mkd: "+" on top & "3 HES 141" on E. face.
Orig. 36", now 42" Fir, dying, S. 34 3/4° W. 17.2 ft., shows good scar.
Orig. 22", now 28" Sawed Fir Stump, S. 61½° W. 6.6 ft., shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 2 W
(Reset Stone Alongside) Office, 1969 Cor. #3 HES 141
New BT's: 15" D. Fir N. 44° W. 25.0 ft. mkd: "3 HES 141 CS BT".
11" W. Fir South 28.3 ft. mkd: "3 HES 141 CS BT".
This corner lies on steep easterly slope about 50 ft. west of Deadman
Creek Access Road.

Corner #6, H. E. S. No. 141. 67
Found - Orig. 24", now 32" Fir Corner Tree, alive, shows good scar on S.W.
Orig. 18" Fir, now only remains of stump, N. 87 3/4° E. 38.9 ft.,
reverse scribe marks found.
Orig. 10", now 17" Fir, alive, N. 65° W. 40.3 ft., shows good scar.
We Rescribe "6 HES 141 CS BT".
On South Side at Base of Corner Tree, 2 feet from center, Set:
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 2 W
Office, 1969 Cor. #6 HES 141
New BT: 11" D. Fir S. 27° E. 37.0 ft. mkd: "6 HES 141 CS BT".
This corner lies on N. side of claim access road.

RE-RENEWED SEE CORNER NO. #118
RE-RENEWED SEE CORNER NO. #115
RE-RENEWED SEE CORNER NO. #114
RE-RENEWED SEE CORNER NO. #116

11/21/69