

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 29 S. T. S. R. 2 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

Corner #13 of H. E. S. No. 141. #125  
Found - Old Corner Stone, in place, mkd: "+" on top & "13 HES 141 on side.  
Orig. 15", now 20" W. Fir Snag, N. 58 $\frac{1}{2}$ ° E. 17.2 ft., we open & find scribe.  
Orig. 36" W. Fir, decayed remains of stump, S. 54° E. 13.9 ft., no scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 2 W  
(Reset Stone Alongside) Office, 1969 Cor. #13 HES 141  
New BT's: 11" W. Fir S. 13° W. 21.5 ft. mkd: "13 HES 141 CS BT".  
15" Pine N. 43° E. 32.8 ft. mkd: "13 HES 141 CS BT".  
This corner lies 20 ft. above bottom.

11/21/69

Corner #14 of H. E. S. No. 141. 75  
Found - Corner Stone, out of place.  
Orig. 24", now 36" Cedar, alive, N. 57 $\frac{1}{2}$ ° W. 29.7 ft., shows scar, we tag.  
Orig. 16", now 22" W. Fir, alive, N. 10° W. 38.3 ft., open, scribe visible, tag.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 2 W  
(Reset Stone Alongside) Office, 1969 Cor. #14 HES 141  
Brass Cap set under 20" Fir Log.  
New BT: 8" D. Fir N. 74° W. 18.0 ft. mkd: "14 HES 141 CS BT".  
Corner No. 10, same HES bears S. 2° E. 36.3 ft. (Rec. S6° 21' W. 32')

11/21/69

Corner #15 of H. E. S. No. 141. 76  
Found - No trace of Corner Stone.  
Orig. 20" Fir(?), now 36" Pine, N. 9 $\frac{1}{2}$ ° E. 20.5 ft., alive, faint scar.  
Orig. 16", now 30" W. Fir N. 35 $\frac{1}{2}$ ° E. 52.1 ft. alive, we open & find scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 2 W  
Office, 1969 Cor. #15 HES 141  
New BT's: 7" D. Fir S. 35° E. 13.8 ft. mkd: "15 HES 141 CS BT".  
14" W. Fir N. 4° W. 33.5 ft. mkd: "15 HES 141 CS BT".  
This corner lies S.W. slope about 50 ft. from flat. Cor. #9, same HES  
bears S. 55° W. 42.5 ft.

11/21/69

Corner #16 of H. E. S. No. 141. 77  
Found - Orig. 18", now 24" Cedar, alive, S. 71° E. 45.5 ft., scribe visible.  
We Rescribe: "16 HES 141 CS BT".  
Other Orig. BT. down & badly decayed. - No Corner Stone found.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 2 W  
Office, 1969 Cor. #16 HES 141  
New BT: 11" W. Fir N. 30° E. 24.0 ft. mkd: "16 HES 141 CS BT".  
This corner lies on flat. Cor. #8, same HES bears S. 52° W. 41.9 ft.

11/20/69

South  $\frac{1}{4}$  Corner to Section 33 only, T28-2W. 78  
Found - Stone mkd: " $\frac{1}{4}$ " on N. face, as called for & Orig. BT's., as follows:  
Orig. 10", now 22" Fir, alive, N. 23° W. 4.0 ft., shows good scar.  
No trace of 1917 Orig. BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T28S R2W S 33  
Office, 1970 T29S  
(Reset old Stone alongside)  
New BT: 7" W. Fir N. 7° E. 55.1 ft. mkd: " $\frac{1}{4}$  S33 CS BT".  
This corner lies in shallow ravine, course south.  
The record dist., 258.1 ft., from this  $\frac{1}{4}$  cor. to sec. cor. 3 & 4,  
T29-2W., appears to be very close. We do not measure due to logging  
debris on line.

10/26/70

Section Corner to Sections 4 and 3, T29-2W. 79  
Found - Old Corner Stone, in place, as called for & BT's., as follows:  
Orig. 8", now 12" Hemlock, Alive, S. 17 $\frac{1}{2}$ ° W. 9.2 ft., we open & find "T29".  
No trace of other Orig. BT. due to logging.  
Set - Brass Cap at Cor. Mkd: County Surveyors T28S R2W S 4 | S 3  
Office, 1970 T29S  
(Reset old stone alongside)  
New BT's: 18" D. Fir S28° W. 16.2 ft. mkd: "T29S R2W S 4 CS BT".  
20" Hemlock S. 72 $\frac{1}{2}$ ° W. 36.6 ft. mkd: "T29S R2W S4 CS BT".  
There are no trees close in Section 3 due to clear cut.  
This corner lies approx. 300 ft. N. of logging access road, #U.S.F.S. 2852.

10/26/70

Vernon "Ray" Tracy  
Jack Heritage & V. Perrón  
November, 1969  
C. S. File No. 54/96

Vernon "Ray" Tracy  
Jack Heritage & V. Perrón  
October 26, 1970  
C. S. File 54/40