

Douglas County Surveyor's Record of  
Government Corners Renewed

29 T. S. 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

All alive and well healed. Orig. SW BT is Downed and gone Fd; Stump hole at called bearing & dist.  
New: 10" fir bears S 43°W., 21.4ft. scribed (T29S R2W S28 CS BT) in a  
double blaze. Compass Declination 20° East.

1/4 Corner Sections 28 & 33  
Found: G.L.O. brass cap (1917) properly marked. **93**  
From which: An orig. 24" Fir now 36" alive and well healed bears S 64°W.,  
12.5 ft.  
An orig. 28" Fir now 28" rotted stump with no visible scribe marks bears  
N 37 1/2°E., 45.5 ft.  
New: A 7" Fir scribed "1/4 S 28 CSBT" in a double blaze bears N 18 1/2°E.,  
30.3 ft. Compass Declination 20° East 10/1/75

Clell Goodwin  
Vic Cangie  
Lenora Ladig  
C.S. 57/36  
10/1/75

1/4 corner to sec. 32 and 33  
Found- 1917 GLO brass cap firmly set and properly marked. **94**  
An orig. 12" D. Fir now a 14" snag, with a good scar, bears S42 1/4°E.,  
21.8 ft.  
An Orig. 24" now 29" D. Fir alive and well Healed bears N87 1/2°W.,  
44.2 ft., (Rec. N 87 1/2°W., 45.5 ft)  
New BT's - 20" D. fir bears N 18°E., 46.0 ft., scribed "1/4 S33 CS BT" in a  
double blaze. Compass declination setting 20° East 12/24/75

Gary L Langlitz  
M. Lenora Ladig  
12/24/75  
C.S. 57/39

1/4 Corner sec. 33 (South) REN. #37 **95**  
Found-1917 U.S. GLO Brass cap properly marked and stamped.  
15" dia. cedar bears N22°E., 70.7 ft. (Rec. N20 1/2°E., 69.3 ft) Tree has good  
blaze partial scribing visible.  
28" dia. Fir stump bears N54°W., 47.8 ft. (Rec. N56°W., 48.2 ft) has old scar.  
10" dia. Hemlock bears N49°W., 34.5ft. Tree is scribed "1/4 S33 CS BT".  
This corner lies 43.7 ft. west of the north quarter corner of section 4  
t30s R2W (rec. 44.2 ft.) 12/28/75 Mag. Dec. 20°E

L.E. Monrean  
P.L.E.  
J.H.C.  
12/18/75

CS 57/39

Section Corner Sections 29, 28, 32 and 33. **96**  
Found - A 2" I.P. firmly set with brass cap stamped properly. This monument is in  
good condition.  
An 18" now 27" Orig. Fir, bears N.66 1/4°E., 25.7 ft. Healthy &  
shows good scar.  
An orig. 14" now 20" Cedar bears S.79°E., 25.1 ft. Healthy & shows  
good scar.  
An Orig. 24" now 38" Fir, bears S.45 1/2°W., 68.6 ft. Healthy and shows  
good scar.  
An 18" Fir windfall that fits reasonably well for bearing &  
distance for the orig. NW BT but we find no evidence to verify  
it as a BT.  
New BT - A 10" W. Fir, bears N.9°W., 44.0 ft. mkd. "T29S R2W S29 CS BT" in  
a double blaze.  
Note: We stamp "CS 1976" on found brass cap.

A. Victor Cangie  
Mike Tompkins  
Doug. Co. Surveyors Office  
Nov. 16, 1976  
C.S. 56/26

11/16/76

Section Corner for Sec. 1, and Sec. 6 of T.29-1. (North boundary) **97**  
Found - 1917 GLO brass cap on 3" I.P. solidly set in ground and  
properly stamped.  
A 18" D. Fir stump with a healed blaze bears S.35°W., 9.24 ft.  
A 14" D. Fir stump with healed blaze bears S.66°E., 31.8 ft.  
(Rec. 30.36 ft.)  
New BO's- A 3/4" Iron Rod set in a 20" Cedar stump, 1" Alum. cap stamped  
R.M. on iron rod, bears N.58°W., 11.2 ft.  
A 3/4" Iron rod with 1" Alum. cap stamped R.M. set in a 19" D. Fir  
stump bears S.88°E., 39.0 ft.  
Placed County BT signs on all 4 stumps. Corner in a clearcut unit. No trees  
near by.

Dennis Gaylord, U.S.F.S  
Deputy, Doug. Co. Surveyors Off.  
Witness: Randal Lopez  
March, 1978  
C.S. 59/46

3/16/78

Section Corner for Secs. 3 and 2 only. North boundary. **98**  
Found - Orig. 14" now 17" Fir stump bears S.40°W., 12.54 ft. (Rec. S.36°W)  
Has a healed scar.  
Orig. 14" now 16" Pine stump bears S.79°E., 29.70 ft. (Rec. S.78°E)  
scribing visible on unhealed blaze; "T29S R2W S2 BT"  
Set - Using record distances & bearing tree stumps, at the intersect  
point I SET a 2 1/2" brass cap on a 1" G.I. Pipe stamped.