

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 29 - T. S. R 2 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

C O N T. -----

98

Set brass cap stamped: County Surveyor's Office T 28 S
1978 S 34 R
S 3 | S 2 2
T 29 S W

New BT's- A 16" D. Fir bears S.10°E., 144.4 ft. scribed "T29S R2W
S2 CS BT" on a double blaze.
A 22" D. Fir bears S.37°30'W., 115.8 ft. scribed "T29S R2W S3
CS BT" on a double blaze.

Placed County BT signs on all BT's and stumps.
Corner lies 50 ft. North of Rd. No. 274 in a clearcut unit.
----- 3/9/78

Dennis Gaylord
U.S.F.S.
Deputy, Doug. Co.
Surveyors Office
Witness: Randal
Lopez
March 1978
C.S. 59/46

99

1/4 Corner for Sec. 36 only, T28-2
Found - 2 1/2" 1923 GLO brass cap on 3/4" I.P. set solidly in ground.
Brass cap stamped U.S. General Land Office Survey 1/4 S36 1923.
I add "T28S R2W" to brass cap above the 1/4 S36.
A 51" Fir stump with a railroad spike in top. Spike bears N.52°W.
10.1 ft. (Not of record).
A 45" Cedar stump with a railroad spike in top. Spike bears
N.9°30'W., 14.7 ft. (Not of record).
No trace remains of orig. BT's.

No new monuments or accessories.
Placed County BT signs on both stumps. Corner in a clearcut unit. No
trees near by.

----- 3/16/78

100

Section Corner for secs. 2 and 1 only.
Found - Orig. corner stone set firmly in place. No visible marks on
stone, which is soft & somewhat wathered. Stone measures
15" x 12" x 6".
A 20" Hemlock bears S.35°45'E., 23.1 ft. some scribing visible
on partly healed blaze.
A 16" D. Fir bears S.55°W., 23.1 ft. (Rec. S.45°W., 23.1 ft.)
Has a healed blaze.

Placed County BT signs on both trees.
Set - Moving corner stone aside, I SET in it's place a 2 1/2" Brass
cap stamped: County Surveyor's Office T 28 S
1978

S 2 | S 1
T 29 S R 2 W

I bury corner stone alongside & build a rock mound around I.P.
No new accessories.

----- 3/23/78

101

1/4 Corner for Sec. 35 only of T28-2.
Found - 2 1/2" brass cap on 1" I.P. stamped U.S. General Land Office
Survey 1/4 S35 1923. I ADD "T28S R2W" to brass cap above
the 1/4 S35.
A 16" D. Fir bears N.23°W., 1.98 ft. Has a healed blaze.
A 17" D. Fir bears N.89°E., 13.8 ft. (Rec. 13.2 ft.). Has
a healed blaze.

Placed County BT signs on both trees.
Did not remonument or add accessories.

----- 3/23/78

102

Section Corner for 3, 2, 10 and 11.
Found - 1917 GLO brass cap on a 1 1/2" I.P set firmly in ground and
properly stamped.
A 12" Sugar Pine (orig. 6") bears N.17°W., 17.3 ft. (rec. 17.82)
Has a healed scar.
A 21" D. Fir, (orig. 12") bears S.68°W., to center of tree, (rec.
S.74°W.) 8.58 ft. Has a healed scar.
A 11" D. Fir (orig. 10") bears S.29°E., 22.9 ft. (rec. S.28°E.,
23.1 ft.) Has a healed scar.
A 21" D. Fir (orig. 16") bears N.51°30'E., 16.2 ft. (Rec. N.50°
30"E., 17.2 ft., slope dist. is 17.2 ft.) Has a healed scar.

Placed County BT signs on all BTs.
No new monument set or new accessories.

----- 3/30/78

Dennis Gaylord, U.S.F.S.
Deputy, Doug. Co.
Surveyors Off.
Randal Lopez
March 1978
C.S. 59/46

Dennis Gaylord
U.S.F.S.
Deputy, Douglas Co.
Surveyors Office
Randal Lopez
March 1978
C.S. 59/46