

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 29 S T. S. R 2 W R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, OR., 91881

Leonard Herzstein, U.S.F.S.  
Deputy, Cou. Surveyors Office  
J. Landrum  
T. Wolford  
May 19, 1981  
C.S. 61 / 24

( CONTINUED FROM LAST PAGE )

116

bearing tree is girdled at base by a wirerope which may kill it in the future.

- Set - Add marks "B.O." to Brass Cap  
Add 2' mound of stone; I.P. now projecting 6".  
\* NOTE - Corner is on the North side of old claim access road.

Cor.# 7 H.E.S. No. 141. Renewal # 68.

117

Found - 1" I.P. firmly set, projecting 10" above a 3' mound of stone with B.C. marked County Surveyors Office 1969 T29S R2W Cor./#7 HES 141.

Orig.BT's: 30" D. Fir stob bears N.44 3/4°E., 55.4-ft., with no marks visible.

16" D. Fir snag bears N.78 1/2°W., 4.3-ft., with healed blaze and re-scribed by Tracy in 1969 with 7 HES 141 CS BT visible on partly healed blaze.

1969 BT's: 36" I. Cedar bears N.34°E, 31.4-ft., (Rec. 31.0-ft.) with scribe marks 7 HES 141 CS BT visible on partly healed blaze.

New BT: 14" Maple bears N.31°W., 16.7-ft., scribed 7 HES 141 CS BT on double blaze.

\* NOTE - Corner is on North side of old claim access road on top of cutbank

Corner # 7, H.E.S. No.140.

118

Found - 1 1/4 " I. P., firmly set, projecting 15" above ground, with Brass Cap, properly marked. Orig. corner stone is alongside with marks "+" on North side and "7 HES 140" on top.

BT's - 24" D. Fir (orig.BT), bears S.4°W., 12.2-ft. w/ healed dble blaze.  
18" I. Cedar snag (orig.BT) N.73°W., 19.5-ft.w/healed dble blaze.  
7" D. Fir snag bears N.62°W., 4.1-ft. w/scribe "7HES 140 CS BT" visible on partly healed blaze. Ren. # 63.

New BT's- 12" D. Fir bears N.78°E., 36.8-ft., scribed "7 HES 140 CS BT" on double blaze.

Note - Corner is 100-ft. South of USFS Rd.#274-P.

9/21/81

1/4 Corner to Section 31 only (South) Renewal # 34

119

Found - A U.S. G.L.O. Brass Cap on an I.P., protruding 14 ins. above ground. Properly marked. (1917)

BT's - 20" now 22" diam. D. fir tipped out with covered face, center of root hole bears N.8 1/2°E., 12.5 ft. (Agrees with original)  
30" now 38" diam. D. fir with a well healed single blaze, bears N.32 1/2°W., 19.8 ft. (Agrees with orig.)  
20" now 24" diam. D. fir with a well healed single blaze, bears N.30°E., 25.1 ft. (Agrees with Ren. #34)

New BT's - 7" Cedar, double blazed and scribed "1/4 S31 CS BT", bears N.76 3/4°E., 9.7 ft.

5" D. fir, double blazed and scribed "1/4 S31 CS BT", bears N.60 3/4°W., 30.9 ft.

NOTE: Corner is S.89°50'26"W., 88.18 ft. from N 1/4 Cor. of Sec. 6, T30-2W. (See M97 - 65)

North 1/4 sec. Corner for Section 6 only, T30S R2W. REN #33

120

Found - Orig. Porphyry stone, measuring approx. 14" x 12" x 6" with possible "4" marked on South face; this stone is loosely set on surface of ground at east edge of brass cap monument. (1909)

An iron pipe and brass cap monument (REN #33) properly mkd, and firmly set, protruding 12 ins. from ground.

Orig. BT, A 10 in. now 16 in. DBH D. Fir with x chopped in bark and a partially healed, obliterated face, bears N.35°E., 2.6 ft. dist. (Rec. N.35°W., 2.6 ft.)

Orig. BT, a 6 in. madrone, now 9 ins. DBH madrone with a partially healed rotted out blaze, bears S.57°W. at center of root crown, and S.40°W. at center of trunk, blaze height, 2.3 ft. dist. (Rec. S.40°E., 2.3 ft.)

A 12" diam. Fir, now a severely rotted, 6 in. tall broken fir stub with no identifiable marks (1917 resurvey) bears S.2 1/4°E., 12.7 ft. dist. to center of apparent root crown, (Rec. S2 1/4°E., 13.2 ft. dist.)

CONTINUE ON NEXT PAGE....

Leonard Herzstein, USFS  
Deputy Doug. County  
Surveyors Office  
Jim Landrum, &  
Jerry Pierce, witnesses  
Sept. 21, 1981  
C.S. 61 / 27

Douglas Co. Surveyor's  
Office  
Randall W. Smith, &  
Stephen J. Flause  
June 24, 1985  
C.S. 62/28

Douglas Co. Surveyor's  
Office  
Stephen J. Flause, &  
Randall W. Smith  
June 6, 1985