

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 3 R. W. W. M.

17

1/4 SECTION CORNER BETWEEN SECTIONS 17 and 20.

Position identified from original B.T.s. Fir snag with scribe marks legible and maple stump with scars, but scribe marks gone.

Drove 1 1/2" Iron Pipe for corner with 6" x 8" Yew Wood Post along side. Scribed 1/4 S. 17 on N. face and S. 20 C.S. on South. Marked

White Fir 10" dia. N.43°40'W., 81 ft. scribed 1/4 S. 17 C.S.B.T.
Yew Wood 8" dia. S.29°35'W., 34 ft. scribed 1/4 S. 20 C.S.B.T.

18

SECTION CORNER 17, 18, 19 and 20.

Corner is a tree now fire killed and leaning against an adjoining tree. Three O.B.T.s alive and standing except scribe marks obliterated or partially so by fire. Fourth B.T. is cut. The stump is in place and sound.

Set for corner a Yew Wood Post 6" x 6" x 48" scribed T. 29 S. Se. 17 on N.E. face, R. 3 W. S. 20 on S.E. face, S. 19 on S.W. face and S. 18 C.S. on N.W. face. Reblazed and scribed Original B.T.s where in good condition

28" Fir S.30°W., 31 lks. O.B.T. T. 29 S., R. 3 W. S. 19 C.S.B.T.
24" Fir S.70°E., 28 lks. O.B.T. T. 29 S., R. 3 W. S. 20 C.S.B.T.
30" Sugar Pine N.27°W., 61 lks. T. 29 S., R. 3 W., S. 18 C.S.B.T.
20" Cedar N.75°E., 55 lks T. 29 S., R. 5 W., S. 17 C.S.B.T.

19

1/4 SECTION CORNER BETWEEN 19 and 20.

Location identified from stump of O.B.T. Scribe marks legible. Other O.B.T. gone but stump standing and burnt.

Iron Bar for corner. Marked

4" Oak N. 5°20'E., 153.6 ft. 1/4 S. 20 C.S.B.T.
28" Pine N.25°10'W., 317.1 ft. 1/4 S. 19 C.S.B.T.

19A

S.E. CORNER OF D. T. CRAIG D.L.C. NO. 37

Set Cedar post 4" x 4" x 3' for corner. Marked

R. B. Cedar 6" dia. N.57°45'W., 53 lks.
R. B. Cedar 5" dia. S.59°35'W., 102 lks.

1/4 SECTION CORNER BETWEEN SECTIONS 1 and 12

20

Set the 1/4 cor. for Sections 1 and 12 at halfway point between the section corners. Set a 4" x 4" Cedar post marked 1/4 S on E & W sides, S 12 on South side, and S 1 on North side (Neither of two original BTs found.)

I marked two BTs which bear

Red Fir 30", bears N 45° E 9 lks.
Red Fir 30", bears S 50° W 31 lks.

1/4 SECTION CORNER BETWEEN SECTIONS 12 and 13

21

Found iron markings, but markings nearly all gone.

I reset corner from the original BT. Set a 4" x 4" cedar post at corner, and remarked the original BT with 1/4 S BT.

(Original remarked) Laurel 10" dia. N 35° E 16 lks.
Marked a new BT (Fir 12", bears N 50° E for 18 lks. marked 1/4 BT)
Marked a new BT (Laurel 10", bears S 30° E for 9 lks, marked 1/4 BT)

Ben B. Irvine Dep't. Co. Sur.
Witnesses
N. E. Richardson
June 26 and 27, 1920

Ben B. Irvine Deputy
Witnesses
J. R. Hall
N. E. Richardson
June 2, 1931.

Claude Kerr
6/6/50
C. S. 110/252

Claude Kerr
June 6, 1950