

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 3 R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

East $\frac{1}{4}$ Section Corner to Section 24. Determined by O.B.T. 30
30" Fir bears N.69°W. 18.0 ft. found scribe.
26" Fir bears S.33°W. 33.3 ft. O. B. T.
At Corner Point found stone and 1 $\frac{1}{4}$ " X 24" Iron Pipe. from which:
26" Fir bears S.64°E., 41.0 ft. dist. mkd. $\frac{1}{4}$ S24 B.T.
12" Fir bears N.82°E., 30.5 ft. dist. mkd. $\frac{1}{4}$ S24 B.T.
Section Corner 19 - 30 (T29S R2W) = brass cap bears North 16.0 ft.
Main Top and road bears North 585.0 ft. distance.
7/73 FO. O.K. V.R.T. C.S. 56/34 - RESET STONE

Section Corner to Sections 14, 13, 23, & 24. Determined by O.B.T. 31
70" Fir Snag bears S.58°E. 25.0 ft. Found Scribe.
Stump hole bears N.89°E., 15.1 ft.
At Corner Point Set Truck Axle with flange up from which:
20" Alder bears S.54°W. 37.6 ft. dist. mkd. S23 T29S R3W B.T.
10" Maple bears N.79°W. 20.8 ft. dist. mkd. S14 B.T.
15" Hemlock bears S.86°W. 33.0 ft. dist. mkd. S23 B.T.
10" Fir bears S.85°E. 42.3 ft. dist. mkd. S24 B.T.
12" Fir bears N.87°E. 35.0 ft. dist. mkd. S13 B.T.
Creek bears South 60.0 ft. distance.
Road bears East 180.0 ft. distance.

$\frac{1}{4}$ Section Corner to Sections 11 & 14. 32
Found: Rotted stump of Fir, now 13" diam., N.40°W., 7.3 ft. with
bark scribing plainly visible. Portions of the " $\frac{1}{4}$ ",
all of the "S" and all of the "BT".
The location for the other tree falls in a cat road or fire
trail. No evidence of this tree found.
At Corner set 1" Iron Pipe with Brass Cap stamped "County Surveyor's
Office, 1957, T29S, R3W, $\frac{1}{4}$ S11 " CORNER NO. 81
From Which: S14
An 8" White Fir bears N.20°W. 1.5 ft. scribed " $\frac{1}{4}$ S 11 CS BT"
A 24" I. Cedar bears S.13°E. 5.6 ft. scribed " $\frac{1}{4}$ S14 CS BTW

Section Corner common to Sections 11, 12, 13, & 14. 33
Found: Laurel Tree, now 24" diam., N.40°E. 19.1 ft.
Laurel Tree, now 18" diam., S.55°E. 5.3 ft.
Both of these trees are alive & standing but have been
chopped out previously. Faces have rotted considerably, but
unmistakable fragmentary scribing was visible on both.
N.28°W. 33 ft. was a stump hole and dead and rotted Laurel
lying alongside. Found fragmentary reverse scribing inside.
S.25°W. 5.3 ft. (8 lks. instead of 18) was a live Laurel (now 25"
diam.) showing good scars, facing corner. I did not chop
out this tree, but blazed & rescribed it "T29S R3W S14 CS BT".
In digging hole for corner found charred & rotted wood (vertical)
about 1 ft. below surface.
Set 1" Iron Pipe for Corner with Brass Cap stamped S11/S12 T29S R3W County
1957 S14/S13 Surveyor's Office,
Blazed & Scribed New Trees: 9" Fir N.43 $\frac{1}{2}$ °W. 56.6 ft. (T29S R3W S11 CS BT)
15" Fir N.70 $\frac{1}{2}$ °E. 38.9 ft. (T29S R3W S12 CS BT)
30" Cedar S.37°E. 49.5 ft. (T29S R3W S13 CS BT)

Renew Section Corner 15 $\frac{11}{14}$ T29S R3W. 34
Found: Original 24" now 28" R. Fir snag S.35°E. 15.8 ft. Shows good
bark scribing "T29S R3W S14 BT".
Also find Original 15" now 26" R. Fir N.55°E. 20.5 ft. Shows 82
fair bark scribing.
Set $\frac{3}{4}$ " Iron Rod at Corner.
New BTs: 10" Cedar bears S.25 $\frac{1}{2}$ °E. 23.1 ft. scribed T29S R3W S14 CS BT.
18" Cedar bears N.10° W. 25.5 ft. scribed T29S R3W S15 CS BT.
Rescribe Orig. now 26" R. Fir N.53°E. 21.0 ft. Bark scribe T29S R3W S11 CS BT.

Renew witness corner for Section 5

John M. Markham, Jr.
Witness: R. G. Boyd
For Stomar Lumber Co.
Oct. 29, 1957
C. S. File 42/315

James W. Byron
M. Godfrey
S. Bilow
Dec. 17, 1957
C.S. File No. 49/47