

Douglas County Surveyor's Record of
Government Corners Renewed

14. W. W. S. 29 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

James W. Byron
M. Godfrey
S. Bilow
Dec. 18, 1957
C.S. File No. 49/47

35
Renew Witness Corner for Section Corner $\frac{10}{15}$ 11 T29S R3W.
Found : Original 18" Fir, now 26" Fir Snag S.15°W. 14.5 ft. Bark scribed "S 15".
I can find no trace of original N. W. BT. nor Corner Tree.
Set $\frac{3}{4}$ " Iron Rod at Corner.
New BT's: 7" R. Fir bears N.30°W. 24.3 ft. scribed W.C. S10 CS BT.
7" R. Fir bears S.36 $\frac{1}{2}$ °W. scribed W.C. S15 CS BT.

James W. Byron, Deputy
M. Godfrey
S. Bilow
June 11, 1958
C.S. File No. 49/47

36
Corner Sec. 6, T29S, R3W, Sec. 1, T29S, R4W, & Sec. 36 T28S, R4W.
Found - Both Original Bearing Trees:
Orig. 18" now 30" Fir, S.35°W 22.4 ft., now down, shows good scar.
Orig. 20" now 38" Fir S.30°E. 40.2 ft., I open & find good scribing "S".
Set Brass Cap at Corner Mkd: $\frac{S36}{S1/S6}$ T28S T29S County Surveyor's Office, 1958
R4W R3W
New BT's: 20" Cedar bears S.71°W. 55.2 ft. scribed S1 T29S R4W CS BT.
18" Cedar Bears S.30°E. 29.5 ft. scribed S6 T29S R3W CS BT.

James W. Byron, Deputy
M. Godfrey
S. Bilow
July 28, 1958
C.S. File No. 49/47

37
 $\frac{1}{4}$ Section Corner to Sections 25 & 36.
Found - Both Original BT's: - *Logged 5-1957 By STOMAR LBP. - SEE 42/315 & 20*
Orig. 18", now 36" Fir shows good bark scribing "BT" 0"
S.50°W. 19.8 ft.
Orig. 10", now 30" Fir N.60°W. 25.1 ft. Previously opened wood scribed "BT". Checks for ring count (record dist. 25.1 ft., I find should be 22.6 ft.)
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ $\frac{S25}{S36}$ T29S R3W County Surveyor's Office, 1958
New BT's: 9" R. Fir bears N.65°E. 26.5 ft. scribed $\frac{1}{4}$ S25 CS BT.
10" R. Fir bears S.43 $\frac{1}{2}$ °E. 30.6 ft. scribed $\frac{1}{4}$ S36 CS BT.

February 6, 1959
C. S. File No. 49/47

38
 $\frac{1}{4}$ Section Corner to Sections 33 & 34.
Found - Orig. 20", now 30" R. Fir shows good bark scribing " $\frac{1}{4}$ S BT", S.68°W. 7.3 ft.
Stump Hole that checks bearing & distance for Orig. N.E. BT.
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S33/S34 T29S R3W County Surveyor's Office, 1959
New BT's: 8" Cedar bears S.63°E. 23.5 ft. scribed $\frac{1}{4}$ S34 CS BT.
30" R. Fir bears S.68°W. 8.0 ft. scribed $\frac{1}{4}$ S33 CS BT.

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
Feb. 19, 1959
C.S. File No. 49/47

39
Section Corner to Sections 27, 28, 33, & 34.
Found - Stump of Orig. N.E. BT., I open & find good scribing "B".
Orig. 15", now 36" Fir N.62°E. 48.2 ft., shows good bark scribing.
Orig. 10", now 30" Fir S.89°W. 35.0 ft., previously opened, shows good scribing.
24" ^{Fir} Scribed by B.B.I., recorded S.6°E. 15.2 ft., should be South 9.5 ft.
 $\frac{1}{2}$ " Iron Pipe bears N.7°W. 5.7 ft. - *RBN. No. 13*
Note - I find three Orig. BT's., all check bearing & distance except the NW. & SW. BT's., which have distances reversed. I use Orig. BT's. to fix position of Section Corner.
Set Brass Cap at Corner Mkd: $\frac{S28}{S33}$ | $\frac{S27}{S34}$ T29S R3W County Surveyor's Office, 1959
New BT's: 15" R. Fir bears N.31°W. 29.0 ft. scribed T29S R3W S28 CS BT.
12" R. Fir bears N.34°E. 17.5 ft. scribed T29S R3W S27 CS BT.
17" R. Fir bears S.51°E. 45.2 ft. scribed T29S R3W CS BT.