

Douglas County Surveyor's Record of
Government Corners Renewed

29 T.S. 3 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Center 1/4 for Section 15.

Set - An iron post, 28" long, 2 1/2" diam., 20" in ground,
with brass cap mkd. T29S R3W W.M.
C 1/4 S15
1975

119

Bruce Shaner
For: B.L.M.
Nov. 22, 1975
M 58 - 77
C.S. 58/83

from which:

A cedar, 6", bears S.64°E., 19 lks. dist., mkd.
C 1/4 S15 BT.
A cedar, 16", bears N.61°W., 39 lks. dist., mkd.
C 1/4 S15 BT.

11/22/75

Section corner for Secs. 5 and 6 only.

Set - 1 1/2" x 3/4" Iron pipe with brass cap

From which:

A 6" Madrone bears S.53°W., 26.5 ft. mkd. T29S R3W S6 BT.
A 6" Cedar bears S.70 3/4°E., 37.3 ft. mkd. T29S R3W S5 BT.

120

Burton W. Holt
For: Sun Studs
April 19, 1976
M 59 - 77

4/76

Center 1/4 Corner Sec. 12

Set - 3/4" x 42" Iron Pipe.

BT's - 8" Maple bears N.32 1/2°E., 31.5 ft.
7" D. Fir bears South 43.0 ft.

121

Burton W. Holt
For: Sun Studs, Inc.
Oct. 1976
M 62 - 12

10/76

Section Corners for Sec. 22, 23, 27 and 26.

Found - 3/4" I.P. at section corner, pipe loose and badly bent. Ren. #3
Orig. 15" now 25" Maple, bears N.45°E., 6.6 ft. Tree has old
blaze.

Orig. Maple, 22", bearing S.35°W., 3.3 ft. is down and rotted.
A 12" now 20" Cedar, bears S.63°E., 102.8 ft. (rec. S.64°E.) Tree
has partially healed blaze. I open and find scribing "CS BT" Ren. #60
All other bearing trees are gone.

Set - As iron pipe is badly bent I replace marker with a 1" x 30" I.P.
with brass cap attached for section corner stamped:

"Douglas Co. Surveyor" T 29 S R 3 W
1976 S 22 | S 23
S 27 | S 26

FD 10/79
BLM ADMIN. SURVEY
SEE GIS FILE

New BT's-A 10" D. Fir, bears S.43°W., 62.9 ft. Tree is double blazed and
scribed "T29S R3W S27 CS BT".

No trees available for scribing in N.W. quadrant.

11/4/76

122

L. E. Monrean, Doug. Co. Survey-
ors Office
K. Cheney
Nov. 4, 1976
C.S. 59/26

1/4 Corner for Secs. 2 and 11.

Found - 2 1/2" I. P. with 3 1/4" 1964 Cadastral brass cap 3" above
ground. Properly marked.

A 6" now 8" D. Fir bears N.20°E., 35.3 ft. (Rec. N.19°E., 36.3 ft.) Doug. Co. Surveyor
with well healed blaze. Office

A 17" now 20" D. Fir bears S.48 1/2°E., 23.8 ft. with well healed
blaze. June 8, 1977
C.S. 59/34

Bearings and distances recorded on tags did not agree with records
or actual measurements to brass cap.

DID NOT RENEW

6/8/77

1/4 Corner for secs. 29 and 32.

Set. - Brass Cap.

BT's - A 10" cedar bears S.32° W., 11.4 ft. scribed 1/4 S32 BT.

A 12" D. fir bears N. 62° E., 14.6 ft. scribed 1/4 S29 BT.

123

R. B. Kimberling
P. L. Earle
Doug. Co. Surveyor
Office
June 8, 1977
C.S. 59/34

Center 1/4 of section 32.

Set - Brass Cap

BT's - A 16" cedar bears S. 34 1/2° W., 11.6 ft. scribed C1/4 BT.

An 8" D. fir bears N. 24° W., 41.5 ft. scribed C1/4 BT.

125

Glenn S. Baughman
For: John Westheimer
Aug. 1977
M 65-42

9-77

Same as above

12