

Douglas County Surveyor's Record of
Government Corners Renewed

29

T. S.

4

R. W. W. M.

✓ $\frac{1}{2}$ CORNER BETWEEN 5 and 32. (N. E. C. CORNER NO. 127, 8/61)
Renew corner from stumps of original wit. trees. Set charred post from which
A Red Fir 10" dia. bears S.39°05'E., 56 lks.
A Red Fir 5" dia. bears S.28°00'W., 60 lks.

✓ CORNER TO SECTIONS 5, 6, 31 and 32. (N. Bdy.) CORNER NO. 128
Renew corner from stumps of original B.T.s. Set Oak Post from which
A Fir 12" dia. bears N.37 $\frac{1}{2}$ °W., 108 lks.
A Fir 12" dia. bears N.34 $\frac{1}{2}$ °E., 92 lks.
Pine 42" dia. bears S.29 $\frac{1}{2}$ °E., 210 lks.
A Fir 22" dia. bears S.21°E., 160 lks.

✓ $\frac{1}{2}$ CORNER BETWEEN 5 and 6. CORNER NO. 129
Renew corner from old witness trees and marked new trees as follows
A Fir 40" dia. bears S.77°E., 78 lks.
A Fir 40" dia. bears N.64 $\frac{3}{4}$ °W., 68 lks.

✓ $\frac{1}{2}$ CORNER BETWEEN 4 and 5. CORNER NO. 192
Renew corner from original trees
A White Fir 12" dia. bears N.10°W., 32 lks.
A White Fir 40" dia. bears S.79°E., 33 lks.
Set an Oak post 4" x 4" x 3 $\frac{1}{2}$ ".

✓ S. W. CORNER OF SECTION 24. CORNER NO. 195
Reestablished (see Cody's Survey) from intersecting line. Set in 1 $\frac{1}{2}$ " x 40" Iron Pipe and a 5" Cedar Post from which
A Cedar 8" dia. bears N.46°40'E., 332 lks.
A Cedar 24" dia. bears S.47°00'E., 54 lks.
A Cedar 24" dia. bears S.63°00'W., 9 lks.
A Fir 40" dia. bears N.36°15'W., 25 lks.
No old B.T.s found.

✓ $\frac{1}{2}$ CORNER BETWEEN SECTIONS 23 and 24. (See Cody's Survey) CORNER NO. 171
Set in 1 $\frac{1}{2}$ " x 40" Galvanized Iron Pipe, from which
A Fir 18" dia. bears S.52°30'E., 20 lks.
A Fir 30" dia. bears N.72°15'W., 12 lks.

✓ $\frac{1}{2}$ CORNER ON EAST SIDE OF SECTION 24. (See Cody's Survey) CORNER NO. 147 & 57
Set in from old B.T.s a 2" x 20" Galv. Iron Pipe, from which
A Yellow Pine 40" dia. bears S.20°00'W., 2.10 chs. *57
A White Oak 18" dia. bears S.15°45'E., .77 chs.
A Fir 20" dia. bears N.28°30'E., .19 $\frac{1}{2}$ chs.

✓ N.W. CORNER OF SECTION 24. CORNER NO. 168
Set in from old B.T.s a 2" x 36" Iron Pipe, from which
A 36" Black Oak tree bears N.25°00'E., .05 lks.
A 18" Black Oak tree bears N.26°00'W., 54 lks.
A 30" White Oak tree bears S.54°30'W., 57 lks.

$\frac{1}{2}$ CORNER ON NORTH SIDE OF SECTION (See other records)

✓ SECTION CORNER BETWEEN 14, 15, 22 and 23. CORNER NO. 105 & 59
Original corner destroyed. Stumps of two old witness trees found. Set new corner, a 1" Iron pipe, from which
36" Bull Pine N.45°E., 143 lks.
6" Laurel S. S.85°E., 38 lks.
10" Laurel N.56 $\frac{1}{2}$ °W., 141 lks.
36" Fir stump S.47 $\frac{1}{2}$ °W., 32 $\frac{1}{2}$ lks. Original B.T.

Frank Cain Co. Surveyor
Witnesses
F. J. Cole
J. T. Plack
Wm. Berdine
W. H. Lawrence
May 1915.

June and July 1918.
W. C. Freer Dep. Co. Sur.
Witnesses
Jesse Smith
Ralph Smith
Jeff. Wiley

G. G. Stewart D.C.S.
Witnesses
Frank Evans
C. Crocker
February 3, 1922.

See Also M. 2-4

VOL 8 PG 225

VOL. 3 PG 102