

Douglas County Surveyor's Record of
Government Corners Renewed

29

T. S.

4

R. W. W. M.

A. Boyer D. C. S.
Ted Shellabarger
Ralph Schrader
Delb. Trask Oct. 18, 1938

Boyer, A. Boyer
Oct. 22, 1938
Wit. Delb. Trask
R. Schrader
Ted Shellabarger

Ben B. Irving D. C. S.
Richardson
Loren Weber
Dale Woodruff
Oct. 22, 1940.

N. E. Richardson Dep. C. S.
Wit. E. S. Woodford
May 1945

G. J. Wenderoth
Nov. 1946.
Dep. Co. Sury.
M 28-78

G. A. Barnhart
Surv.
Weber
Stubblefield
Witnesses
Dec. 1946
C.S. 40/19

G. A. Barnhart
Dec. 1946
C.S. 40/19

CS 16/4 M3-67

✓ 1/4 CORNER BETWEEN 9 and 16. **SEE CORNER NO. 120** 54
This corner is just off N. of old fence line running East. Both B.T.s dead. Set Cedar Post, set by Woods, #38 back in place from stump of Fir B.T. and down Oak which Woods used in 1925. Marked new trees for B.T.'s
N. 26 1/2° E., 256.0 ft. Fir 16" dia.
S. 50 1/2° W., 314.3 ft. Alder 18" dia. on creek bank, bark blaze, a 9" and an 18" Alder against this tree.

✓ MOST EASTERLY S.E. CORNER OF LOT 4, **Sec. 16** 55
Set 1883 by County Surveyor. Found his B.T. a "10" White Oak N. 46° 52' E., 30 lks.
Set a 4" x 4" Fir post and cut out B.T. to blazed scribe marks.

✓ S.E. CORNER OF N.W. 4 N.W. 4 SECTION 16. 56
Set in 1883 by County Surveyor. Found his B.T. A 12" White Oak S. 87° 08' W., 2.81 chs. cut out scribe marks.
Set a 4" x 4" Post for corner in open pasture.

✓ 1/4 CORNER ON EAST BOUNDARY, SECTION 24. **SEE CORNER NO. 147** 57
Iron pipe as set by F. C. Frear in 1916 in place. Fir 28 1/2° E., 19 1/2 lks. as set by Frear cut and scar burned out of stump. Oak S. 15 1/2° E., destroyed cut and stump by fire, stump hole and few roots only being visible. Pine S. 20° W., 2.10 chs. cut and stump burned, part of blaze still visible. Set new bearing trees as follows
A Fir 30" dia. bears N. 51 1/2° W., 29.3 ft. marked S. 24 C.S.B.T.
A Fir 30" dia. bears S. 33 1/2° W., 142.7 ft. marked S. 24 C.S.B.T.

✓ SECTION CORNER BETWEEN 19, 20, 29 and 30. 58
Renewed from old B.T.s. Set Iron spring and shackle for corner from which
A 30" Fir bears N. 32° E., 5.8 ft.
A 20" Fir bears S. 55° E., 32.4 ft.
A 18" Fir bears N. 45° W., 27.4 ft.
A 20" Fir bears S. 76° W., 18.9 ft.

✓ SECTION CORNER BETWEEN 14, 15, 22 and 23. 59
Renewed from old B.T.s and marked the following trees #16
A 8" Laurel S. 38° 45' E., 26.0 ft.
A 12" Fir N. 68° 00' E., 22.9 ft.
No other trees near. **SEE CORNER NO. 105**

✓ 1/4 SECTION CORNER BETWEEN 20 and 21. 60
Renewed from old B.T.s and marked
A 12" Alder N. 62° 00' E., 57.6 ft. **SEE PRIOR #39** 143

✓ 1/4 SECTION CORNER BETWEEN 5 and 32. (North line of Twp.) 61
Renewed from old B.T.s marked new B.T.s. **REN #8**
Drove 1 1/2 inch pipe for Corner. **SEE CORNER NO. 127**
A 14" Fir S 2° 10' W. 10.7 ft.
A 10" Fir S. 70° 36' W. 24.8 ft.

✓ COR. OF SECS. 29-30-31-32 **SEE CORNER NO. 93** 62
Found 18" Red Fir bearing tree (dead) measured N 5° E 23 links, set 3/4" iron rod 30" long for sec. cor. from which new B. T. were set.
A 8" Fir bears N 19° 52' W a dist. of 4.0 ft.
A 5" Fir bears N 45° 07' E a dist. of 20.3 ft.
A 5" Yew bears S 64° 57' E a dist. of 28.7 ft.
A 16" Cedar bears S 50° 03' W a dist. of 20.5 ft.

✓ 1/4 COR. BETWEEN SECS. 29-30 **SEE CORNER NO. 173** 63
Set a 3/4" iron rod 30" long, 2747.25 from the sec. corners and on a true line between them, from which:
A 12" fir bears S 68° 17' W 22.7 ft.
A 2" fir bears S 81° 58' E 4.2 ft.