

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORG. 97181

West $\frac{1}{4}$ Corner between Sections 23 and 24. **133**
The original BT destroyed by being cut down.
Set new post Fir 4x4 inches square 3 $\frac{1}{2}$ ft. long from which: $\$ 171$
Fir 20 inches diam. bears N 44 $\frac{1}{2}$ °E 50 lks.
Fir 16 inches diam. bears S 10 $\frac{1}{2}$ °W 23 lks.

Feb. 3, 1902
Volume 2/264
Presence of
A.M. Akers & C.D. Falla
(Fallan)

N.W. Corner Section 16 and S. W. Corner Section 9 (only) as Determined by
old Bearing Trees: 20 inch Fir S. 9°W., 22.4 feet O.B.T. **134**
10 inch Fir S. 43°E., 28.4 feet O.B.T.

There was 4 more Old bearing trees either dead or logged. **201**
At corner point found scribed post and set $\frac{1}{2}$ "x22" iron bar from which: *Rev/25*
18 inch Laurel bears S. 84°E., 18.2 feet marked S. 16 T. 29S, R. 4W., BT.
12 inch W. O. bears S. 26°W., 38.5 feet distance marked S. 17, BT.
28 inch Laurel bears S. 14°W., 90.0 Feet distance marked S. 17, T. 29S, R. 4W., BT.
Closing Corner 8/17 bears N. 9°E., 345.0 feet.

John H. Markham, Jr.
Work done for Stomar Lbr. Co.
Wit: R.G. Boyd
Sept. 10, 1957
C. S. 42/298

Closing Corner 8/17 = S.E. Corner 8 and N. E. Corner 17, as determined by
Old Bearing Trees: 20 inch Fir bears S. 33°W., 21.1 feet, O.B.T. **135**
14 inch Laurel stump bears N. 42°W., 72.0 O.B.T.
At Corner point set $\frac{1}{2}$ "x20" iron pipe from which: **202**
12 inch Fir bears N. 30°E., 53.3 feet distance marked S 9., BT.
24 inch Laurel bears N. 49°E., 106.5 feet distance marked S 9, T. 29S, R. 4W., BT.
32 inch Laurel bears S. 38°E., 61.2 feet dist. marked S 9, T. 29S, R. 4W, B.T.
Closing Corner 9/16 bears S. 9°W., 345.0 feet.

Section Corner to Section 1 & 2 T. 29S R. 4W and Secs. 35 & 36 T. 28S R. 4W. **136**
Found - Three Orig. BT's. All have open faces & show good scribing.
All check bearings & distances.
The N. W. BT. now down.
The N. W. & S. W. BT's now snags only.
Find Cedar Roots for Orig. S. E. BT.
Set Brass Cap at Corner marked $\frac{S35|S36}{S 2|S 1}$ T. 28S R. 4W County Surveyor's Office, 1958
New BT's: 12" Cedar bears S. 2°E. 16.7 ft. scribed S1 T. 29S R. 4W CS BT.
18" W. Fir " S. 81°W. 31.5 ft. scribed S2 T. 29S R. 4W CS BT.
18" Cedar bears N. 65°E. 7.6 ft. scribed S36 T. 28S R. 4W CS BT.
36" R. Fir " N. 2°W. 14.7 ft. scribed S35 T. 28S R. 4W CS BT.

James W. Byron, Deputy County Surveyor
M. Godfrey
S. Bilow
Feb. 26, 1958
C. S. File No. 49/67

$\frac{1}{4}$ Section Corner to Sections 2 & 1. **137**
Found - Orig. 10" now down & partly rotted Fir Snag Section at Base shows good scribing "BT".
Orig. N. W. BT. gone.
Set Brass Cap at Corner Marked $\frac{S2|S1}{\frac{1}{4}}$ T. 29S R. 4W County Surveyor's Office, 1958. *End. OK. by B. SHANER Oct. 1981 RM 3-54*
New BT's: 20" Hemlock bears S. 33°W. 26.5 ft. scribed $\frac{1}{4}$ S2 CS BT.
36" Cedar bears N. 5°E. 21.0 ft. scribed $\frac{1}{4}$ S1 CS BT.

$\frac{1}{4}$ Section Corner Common to Sections 16 & 17. **138**
as determined by O.B.T. & Post:
20" Fir Stump (logged) bears S. 43 $\frac{1}{2}$ °E. 33.0 ft. dist. O.B.T. found scribe.
At Corner point found 4"x4" wood post scribed $\frac{1}{4}$ S16 $\frac{1}{4}$ S17. - *REV #36*
I Set 1"x30" I. P. from which: **193**
5" La. bears S. 70°E. 12.1 ft. dist. mkd. $\frac{1}{4}$ S16 T. 29S R. 4W BT.
4" Cedar bears S. 7°E. 34.2 ft. dist. mkd. $\frac{1}{4}$ S16 BT.
5" La. bears S 54°W. 12.4 ft. dist. mkd. $\frac{1}{4}$ S17 T. 29S R. 4W BT.
11" Fir bears N. 45°W. 10.8 ft. dist., bark scribed $\frac{1}{4}$ S17 BT.
A North-South fence bears West 14.0 ft.
Section Corner 9-16 only bears North (21°10'Var.) 2206.0 ft. dist.

John H. Markham, Jr.
For Stomar Lumber Co.
March, 18, 1958
C. S. File No. 42/345