

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S. T.S. R. 4 W. R.W.W.M.

ROSE-CHAPMAN CO., EUGENE, ORE. 21881

177


1/4 Corner to Sections 15 and 14.
Found - Orig. 7", now down & mostly rotted B.Oak N.10°E. 16.5 ft.
shows what I believe to be faint reverse scribe marks.
Remains of Large Oak that checks for N.E. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
1/4 S15/S14 T29S R4W
New BT's: 9" Cedar bears N.56°W. 10.5 ft. scribed 1/4 S15 CS BT.
14" R.Fir bears S.16°E. 23.6 ft. scribed 1/4 S14 CS BT.
Note - We find 10" Laurel that bears N.5°W. 4.0 ft., shows
what appears to be bark scribing "R 32".

178

Section Corner to Sections 17 - 16 - 20 - 21.
Found - 1 1/2" I.P. at Cor. & at fence corner. - Ren #35
10", now 24" Fir S.67°E. 21.8 ft., shows good scar.
Stump Section of SW. BT. No trace of other BT's.
New BT's: 10" Cedar N.46°W. 55.5 ft. scribed S17 T29S R4W CS BT.
7" Pine bears S.50°W. 40.2 ft. scribed S20 CS BT.
8" W.Oak bears N.35°E. 37.7 ft. scribed S16 T29S R4W CS BT.

FD. OK
D.C.S.O. 9/93
C.S. 64/46

179

S. E. Corner to D. L. C. No. 39.
Found - Geared Axle at corner & N.E. BT., now dead. REN #50
N. W. BT. not found.
Fences Thus:  D.L.C. Cor.
New BT's: 5" R.Fir bears N.76°E. 42.1 ft. scribed SW DLC 38 CS BT.
11" R.Fir bears N.41°W. 52.5 ft. scribed SE DLC 39 CS BT.

James W. Byron, Deputy County Surveyor
Mike Darby and Wm. Stoffel
April 1963
C.S. File No. 52/126

180

1/4 Corner to Sections 9 and 16.
Found - Shaft at Corner & both Bearing Trees as recorded
by Marikham, 1956 - Corner No. 120.
Rescribed - (Wood) 7", now 9" Laurel N.50°W. 57.0 ft. 1/4 S9 CS BT.

RE-RENEWED

181

1/4 Corner to Sections 7 and 18.
Found - Brass Cap at Corner & Both BT's., now stumps, as recorded
Corner No. 83, C.S. File No. 45/234. Ren #83
Note - We now find Orig. 36", now 48" Laurel Snag N.7°W. 22.4 ft.
Open this BT. & find good scribing "B".
Orig. S.E. BT. not found.
Remove Brass Cap from 1954 location & reset to True Corner.
True Corner bears N.80°W. 13.0 ft. from Orig. Position of Brass Cap.
New BT's: 4" Laurel bears S.55°E. 93.0 ft. scribed 1/4 S18 CS BT.
10" R.Fir bears N.43°E. 29.0 ft. scribed 1/4 S 7 CS BT.

D. Bente
FD OK
11/87
M105-19

182

Section Corner to Sections 5 - 6 - 7 - 8.
Found - All BT's. as recorded by Cain, 1915. - Ren #6
S.E. & N.E. BT's. now stumps, show scribing.
N.W. & S.W. BT's. show scars.
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1963
1/4 S 6 | S 5
S 7 | S 8
New BT's: 15" R.Fir bears S.33°W. 16.9 ft. scribed S7 T29S R4W CS BT.
14" R.Fir bears N.18°W. 22.4 ft. scribed S6 T29S R4W CS BT.
12" R.Fir bears N. 8°E. 12.8 ft. scribed S5 CS BT.
No trees near to S. E.

RE-RENEWED CORNER NO. #256

183

1/4 Corner to Sections 6 and 7.
Found - 1/2" I.Pipe as corner & both BT's. as recorded by Thompson,
Shows good scribing. (See Corner No. 141)
Set - Brass Cap alongside 1/2" I.P. & Mkd: County Surveyor's Office, 1963
1/4 S 6
S 7
No new BT's:

RE-RENEWED

184

1/4 Corner to Sections 7 and 8. FD OK 12/94 By Olan (See Cor. #78)
Found - Brass Cap at Cor. & Both BT's. N.E. BT. now down.
New BT: 13" Cedar bears N.18°W. 46.8 ft. scribed 1/4 S 7 CS BT.

FD OK 11/87
M105-19
D. Bente