

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S. T. S. R. 4 W. R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 27 - 28 - ^{FD OK BY LANG M117-1 10-92} 33 - 34. 211
Found - 1" I. Pipe and 36" Fir N.60°E. 59.4 ft., good scar. - REN. #91
44" Cedar S.47°W. 17.8 ft., opened, scribing visible.
12" W. Fir N.16°W. 27.0 ft., scribing visible.
32" Fir S.60°E. 16.5 ft., Snag.
New BT: 12" Cedar S.85°E. 32.5 ft. T29S R4W S34 CS BT.

$\frac{1}{4}$ Corner to Sections 27 and 28. 212
Found - 1" I. Pipe and 30" Fir S.58°E. 19.2 ft., shows scribing.
26" Fir N.31°W. 10.3 ft., down. - REN. #18
New BT: 11" Fir N.42°W. 26.0 ft. $\frac{1}{4}$ S28 CS BT.

$\frac{1}{4}$ Corner to Sections 9 and 10. 213
Found - 1 $\frac{1}{4}$ " I. Pipe at Corner & both BT's. as recorded by Markham. REN. #122
Rescribed - (Wood) 20" Pine S.85°W. 40.8 ft., scribed $\frac{1}{4}$ S9 CS BT.

South $\frac{1}{4}$ Corner to Section 32, T29-4W. 214
Found - $\frac{3}{4}$ " I.P. at Cor. & Both BT's. as recorded by Markham, now down.
Both Original Bearing Trees, found. N.W. BT. down. #66
New BT's: 9" Fir bears N.56°W. 7.9 ft. scribed $\frac{1}{4}$ S32.
12" R. Fir bears N.83°E. 2.5 ft. scribed $\frac{1}{4}$ S32 CS BT.

$\frac{1}{4}$ Corner to Sections 21 and 28. 215
Found - 1" I.P. at Cor. & Both BT's. N.E. BT., now stump,
shows scribing. - REN. #101
New BT: 8" Laurel bears N.50°W. 156.0 ft. scribed $\frac{1}{4}$ S21 CS BT.

~~Corner to Sections 35 and 36 only, T29-4W. SEE COR. # 3~~
~~Found - 1" I.P. at corner. Orig. 12", now 24" Laurel N.66°W. 23.8 ft.,
We open & find good reverse scribe marks.
Find Stump Hole for N.W. BT.
60" Cedar bears S.32°W. 7.1 ft., bark scribed CS. We add in
wood "BT". 18" R. Fir bears N.9°E. 15.5 ft., shows
good scar. We do not open.
Note - I believe this corner was renewed by Frear, 1918, but
not of record.~~

Corner to Sections 2 and 1, T30-4W. 216
Found - 1" I. Pipe at Corner & BT's. as recorded by Frear, 1918.
New BT's: 9" Laurel bears S.3°W. 14.7 ft. scribed S2 T30S R4W CS BT.
11" W. Oak bears S.76°W. 33.5 ft. scribed S2 CS BT.

South $\frac{1}{4}$ Corner to Section 36 only. 217
Found - 1" I. Pipe at Corner 19.8 ft. East of $\frac{S}{S} \frac{2}{S} \frac{1}{S}$.
Orig. BT's. are same BT's. as for $\frac{S}{S} \frac{2}{S} \frac{1}{S}$.
New BT: 7" Laurel bears N. 3°E. 24.9 ft. scribed $\frac{1}{4}$ S36 CS BT.

North $\frac{1}{4}$ Corner to Section 2, T30S R4W. 218
Found - 1" Pipe at Corner and Frear BT.: 8" Fir S.45 $\frac{3}{4}$ °W. 5.1 kts.
Tree has been pushed down the hill about 60 ft., fd. scribing.
N. W. Bearing Tree not found
New BT's: 10" Cedar S.2°W. 14.0 ft. mkd: $\frac{1}{4}$ S2 CS BT.
6" Cedar S.23°E. 22.6 ft. $\frac{1}{4}$ S2 CS BT.

C.C. Corner to Sections 34 and 35 only. ^{FD OK BY LANG M117-1 10-92} 219
Found - 1" I.P. at Corner. 10" Pine N.50°E. 25.0 ft., shows scribing.
Fir BT. to N.W., now stump - REN. #116 - 116
New BT: 13" Laurel N.33°W. 62.2 ft. scribed S35 T29S R4W CS BT.

James W. Byron, Deputy County Surveyor
Mike Darby and Wm. Stoffel
May 1963
C. S. File No. 52/126