

Douglas County Surveyor's Record of
Government Corners Renewed

T 29

T. S.

R 4

R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97101

249

Section Corner for Secs. 9 and 16 only.

- Found - A 2" I.P. with standard BLM brass cap set 8" above ground, 1969, properly marked.
- A 12" now 26" Madrone (OBT) bears S.85°E., 16.5 ft. with scribing "CC S16 CS BT" in a partly healed single blaze on the left side of a rotted out blaze.
- A 16" now 18" Oak (OBT) is down, stump bears S.55°W., 9.2 ft. with a rotted out blaze. Ren. #134
- A 20" now 27" D. Fir bears S.11°W., 23.2 ft. (Rec. S.9°W. 22.4 ft.) with a well healed blaze.
- A 10" now 12" D. Fir bears S.41 1/2°E., (Rec. S.43°E) 28.4 ft. with a well healed blaze. I open to find scribing has been chopped out.
- A 12" now 14" Oak is down. Stump bears S.29°W., (Rec. S.26°W.) 38.5 ft. with scribing "S17 BT" in a double blaze.
- A 28" Madrone (Laurel) bears S.16 1/2°W., 91.3 ft. (Rec. S.14°W., 90.0 ft.) with scribing "29 R" in partly healed single blaze.
- A 15" now 20" Fir snag, 30 ft. high, bears N.6°E., 94.3 ft. (Rec. 95.0 ft.) with scribing "T29S R4W S9" in a partly healed double blaze. Ren. #201

No new monument set.

- New BT - A 9" D. Fir bears N.36°E., 10.8 ft. I double blaze and scribe "T29S R4W CS BT".
 - A 5/8" I.Rod bears S.22°E., 61.1 ft. in line with a "PK" nail in a 8" D. Fir which bears S.22°E., 103.2 ft.
- Corner is 20 ft. south of south edge of unit, 346 ft. south of CC for Secs. 8 and 17. 100 ft. east of BLM rd. #29-4-17.

3/21/78

250

Closing Corner for Secs. 8 and 17 only.

- Found - A 1969 Cadastral brass cap on a 2" I.P. set 8" above ground. properly marked.
- A 10" now 25" D. Fir (OBT) bears S.33°W., 21.1 ft. with a well healed blaze. Ren. #135
- A 12" now 16" Fir stump bears N.32°E., (Rec. N.30°E.) 53.3 ft. with scribing "RS 9" in a partly healed blaze.
- A 24" Madrone (Laurel) stump bears N.51°E., 104.2 ft. (Rec. N.49°E 106.5 ft.) with scribing "9S R" in partly healed blaze.
- A 32" Madrone (Laurel) stump bears S.38°E., 55.8 ft. (Rec. 61.2 ft) with a partly healed rotted blaze. Ren. #202
- A 24" D. Fir bears S.16°W., 45.2 ft. (Rec. S.15°W., 45.7 ft.) with a well healed single blaze.

No new monument set.

- New BT - A 6" D. Fir bears N.5°W., 4.9 ft. I double blaze and scribe "CC T29S R4W S8 CS BT".
- Corner is 50 ft. East of Rd. #29-4-17 in a clearcut. Be's are almost the only trees standing on a -36° East slope. A steel fence post is 0.1 ft. West of corner.

3/21/78

251

1/4 Corner common to Secs. 3, & 2.

- Found - Brass Cap, properly mkd. (set in 1965). Ren. #229.
- BTs. - 24" now 36" D. fir bears N.55°E., 12.1-ft., with the bark scribes visible. Ren. #229.
- 11" now 14" White fir snag bears N.70°W., 44.5-ft., with scribes visible Ren. #229.
- New BTs- 14" D. fir, I scribed "1/4 S3 BT", bears S.58°W., 68.0-ft. 12/81

Sec. Corner common to Secs. 3, & 2, and Secs. 34, & 35 of 28-4.

252

- Found - Brass Cap, properly mkd. (set in 1958 Resurvey).
- BTs. - 20" W. fir w/healed over face, bears N.30°E., 7.9-ft.
- 20" cedar BT, down, scribes visible bears S.35°E., 62.7-ft.
- 24" cedar BT w/healed over face bears S.80-1/2°E., 37.3-ft. (Rec. 36.3-ft.).
- 18" D. fir BT w/healed over face bears N.66-1/2°W., 42.9-ft.
- 18" cedar, now down, no marks visible bears S.80°E., 16.5-ft. (Orig.)
- 22" fir snag w/scribes visible, bears S.60°W., 27.7-ft. Orig.

* Note: The N.E. original BT rotted & scattered in general area.

(CONTINUED)

R. B. Kimberling
P. L. Earle
F. C. Silagy
Douglas Co. Surveyors Office
March 21, 1978
C. S. 59/46

Bruce Shaner
For: Longview Fibre Co.
Oct., 1981 thru Jan., 1982
Rm 3-54

1-79