

Douglas County Surveyor's Record of  
Government Corners Renewed

T 29

T. S. R 4

R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

FO OK 12/94 BY DOLAN M 121-29 258

Center 1/4 Corner for Section 8  
Found - 2" brass cap firmly set protruding 4" out of ground, properly marked. Ren. #245  
1/2" I. rod along south edge of brass cap flush with the ground. Ren: #245  
7" now 8" fir, now stump 6 ft. high with scribed "T29S R4W C 1/4 S8 CS BT" visible in partially healed double blaze, bears S.8°E., 29.6 ft.  
6" now 7" fir now stump 6 ft. high with scribed "C 1/4 S8 CS BT" visible in partially healed double blaze bears S.88 1/2°E., 18.4 ft. (Rec. S.87°E.) Ren. #245  
New BT's- 10" fir scribed "C 1/4 S8 CS BT" in double blaze bears S.38°E., 40.0 ft.  
14" fir scribed "C 1/4 S8 CS BT" in double blaze bears N.77°W., 42.2 ft.  
Sketch in C.S. file.

Gregory Quibell  
Deputy, Doug. Co.  
Surveyors Office  
T. Plouff  
July 20, 1982  
C.S. 61/36

7/20/82

1/4 Corner for sections 10 and 11. 259  
I cut open stumps in the vicinity of the proportioned 1/4 corner, but I was unable to find any evidence.  
Set - At proportional distance between section corners:  
1" galv. iron pipe 30" long, with 2 1/2" brass cap marked:  
T29S R4W 1/4 S10 S11 LS 866 1983.  
Set - 5 ft. steel fence posts with bearing tree signs attached:  
N.73°20'E., 1.2 ft. and  
S.73°20'W., 5.05 ft.  
No suitable bearing trees available  
Original distances per GLO plat August 11, 1881.

Witness corner for Center 1/4 corner for section 11. 260  
Center 1/4 falls in the paved surface of the County Road.  
Set - Witness corner N.0°43'32"E., 35.0 ft. from center 1/4 position.  
Set 1" x 30" galv. iron pipe with 2 1/2" brass cap marked:  
WC T29S R4W C1/4 S11 35.0 LS 866 1983.  
Set - Witness corner S.88°02'07"E., 25.0 ft. from center 1/4 position:  
Set 1" x 30" galv. iron pipe with 2 1/2" brass cap marked:  
WC C 1/4 S11 T29S R4W 25.0 LS 866 1983.  
Found - BLM steel fence post and sign marked "C1/4", N.0°04'E., 22.4 ft. from center 1/4. (Actually mid-point on North/South center of section).  
Set - At the center 1/4 corner a temporary point was set (1/2" nail).  
Found - The following iron rods were also tied to determine the right-of-way. I could not check the position of these monuments or other nearby right-of-way monuments with the county road map on file at the County Surveyor's office. Therefore the right-of-way is shown as approx. on the accompanying plat.:  
Found 5/8" iron rod, N.67°29'W., 68.23 ft. from center 1/4.  
Found 5/8" iron rod, S.1°41'W., 116.54 ft. from center 1/4.  
Found an axle set for North-South midpoint by Woods in 1925. The axle is N.33°18'E., 39.49 ft. from the center 1/4.  
Set - Near the right-of-way fence set a 3/4" x 30" iron rod with a 3/4" brass washer LS 866 attached. The iron rod is on the East-West center of section, N.88°02'07"W., 51.56 ft. from center 1/4.  
The detail map on the accompanying plat (M94-61) shows that Govt. Lot 11 (NE 1/4 SW 1/4) has frontage on Louis Creek County Road #176.  
Note: Witness corners fall on the westerly side of the paved surface within the county road right-of-way.

William Ruppert, LS 866  
For: Richard Schallich  
May-June 1983  
M 94 - 61 C.S. 58/270

1/4 Corner for sections 11 and 14. 261  
Found - a 3/4" iron pipe per BLM administrative survey in 1978. There is no official record of this survey. I accepted the corner because I agree with its position for the proportioned quarter corner within 1 foot.  
Set - At the position of the 3/4" iron pipe I set a 1" x 30" galv. I.P. with a 2 1/2" brass cap marked: T29S R4W 1/4 S11 S14 LS 866 198.  
The 3/4" iron pipe was placed along the north side of the 1" pipe  
A five foot iron fence post was placed approx. 1 foot east of the monument.