

Douglas County Surveyor's Record of
Government Corners Renewed

T 29 T. S. R 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron, Deputy
D. McFarland - J. Powell
Sept. 1961
C.S. File No. 49/64

Sec. 6, T29-5 : Sec. 1, T29-6 : Sec. 36, T28-6 : Sec. 31, T28-5. **110**
Found - Orig. 22", now 28" W.Oak N.84°E. 84.0 ft., not 90.4 ft.
We open & find good scribing "S S".
Orig. 24", now 30" B.Oak Snag, center rotted, no scrbing, S.45°W. 85.8'
Orig. N.W. BT. standing, shows good scars. Orig. S.E. BT. not found.
We find 1" I.P. bears N.80°E. 18.8 ft.
Set Brass Cap at Cor. Mkd: County Surveyor's Office, 1961 R6W

S36	S31
S 1	S 6

 R5W T28S T29S
New BT's: 10" W.Oak bears N.83°W. 12.5 ft. scribed S36 T28S R6W CS BT.
12" W.Oak bears S.36°W. 15.7 ft. scribed S 1 T29S R6W CS BT.
8" W.Oak bears S.64°E. 21.0 ft. scribed S 6 T29S R5W CS BT.
11" W.Oak bears N.30°E. 6.0 ft. scribed S31 T28S R5W CS BT.
Fd. brass cap and all bearing trees o.k. 10/11/73

1/4 Corner to Sec. 6, T29-5W. and Sec. 31, T28-5W. **111**
Found - 20", now S.29°E. 31.7 ft. We open & find good scribing.
We do not find N.W. BT. *SEE F.B. 107 PG 36*
Find 2 3/4" I. P. in N. S. Fence bears N.65°E. 4.0 ft.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1961 1/4 S31 T28S R5W S 6 T29S R5W
New BT's: 16" Laurel bears S.13°W. 27.3 ft. scribed 1/4 S6 CS BT.
9" Laurel bears N.29 1/2°E. 8.8 ft. scribed 1/4 S 31 CS BT.
Fences Thus:



FDOK, M119-31 Apr
Oct. 23, 1961
1994

James W. Byron, Deputy
D. McFarland - J. Powell
Nov. & Dec. 1961
C.S. File No. 49/64

1/4 Corner to Sections 11 and 12. **112**
Found - Orig. 10", now 24" W.O. N.61°W. 85.8 ft., previously opened, showed reverse scribing "B".
Find Orig., now 30" B.O. S.87°E. 46.5 ft., not 49.5 ft., previously opened.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1961 S11/S12 T29S R5W
New BT's: Rescribe Orig., now 24" W.O. N.61°W. 83.8 ft. Mkd: 1/4 S11 BT CS.
10" W.Oak bears N. 6°E. 90.0 ft. scribed 1/4 S12 CS BT.

FDOK
By Raymond
Brown 3/17
1994
A&B

Section Corner to Sections 10 - 11 - 14 - 15. **113**
Found - 1" x 48" I. P. at corner & stumps that check 1921 renewal for N.E. & N.W. BT's. We find stump hole that checks S.W. BT.
Also find, now 12" R.Fir, down, S.61 1/2°E. 13.2 ft. We open & find good scribing "S". - Rev. #28
Set - Brass Cap alongside I.P. Mkd: County Surveyor's Office, 1961

S10	S11
S15	S14

 T29S R5W
New BT's: 20" R.Fir bears N.11°W. 108.8 ft. scribed S10 T29S R5W CS BT.
15" R.Fir bears N.69°E. 25.10 ft. scribed S11 T29S R5W CS BT.
no trees suitable near to South.

1/4 Corner to Sections 11 and 14. **114**
Found - Orig. 16", now 28" B.O. S.30°W. 114.0 ft., not 116.2 ft., shows good scars, center rotted.
10", now 30" Maple N.45°E. 82.3 ft., not 84.3 ft. We open & find good scribing. - Rev. #26
Set - Brass Cap Mkd: County Surveyor's Office, 1961 1/4 S11 T29S R5W S14
New BT's: 9" W.Oak bears S.10°W. 33.1 ft. scribed 1/4 S14 CS BT.
Rescribed 28" Maple N.45°E. 82.3 ft. 1/4 S11 CS BT.
Dec. 5, 1961

RE-EXAMINED CORNER NO. #205

115